



Thomson Pavilion Todd Campus West of Scotland Science Park Maryhill Road Glasgow G20 0XA Email: information@d-h.co.uk

Stock Condition Survey 2009



Carried Out By: Richard Robertson, Antony Duffy and Owen Holleway Reference No: **Dundee** Location: **Rosendael**

Date: 30th March 2009





CONTENTS

- (1) Introduction and General Notes
- (2) Summary of 1st year costs
- (3) Brief Description of Property
- (4) Property, Building and Room List
- (5) Survey Report
- (6) Life Cycle Costing Report 30 years
- (7) Floor Plans





SECTION 1

Introduction & General Notes





INTRODUCTION AND GENERAL NOTES

- Instruction In accordance with instructions received from Scottish Veterans Residences, Dearle & Henderson carried out an inspection of **Rosendael, Dundee** on the **30 March 2009**, with a view to providing a Condition Survey Report (including a 30 year Life Cycle Report) of the property.
- **Survey Scope** The property has been visually inspected internally and externally, in accordance with Scottish Veterans Residences Condition Survey instruction.

The survey was undertaken on a visual only basis and no invasive investigations have been carried out. Similarly, services have not been tested and the condition report is based on visual assessments and locally provided information only.

The works requirements included in the report are those necessary in Year 2009 from the reporting period starting March 2009.

- Assessment of Condition The condition of each element has been categorised using professional and technical judgement taking into account the use of the buildings and rooms with particular attention to Health & Safety implications, long-term maintenance and replacement needs, disruption to operational facilities and the age of the element. A condition category has been applied to each element as follows:
 - A In a satisfactory condition
 - B Requires periodic repair
 - C Nearing end of economic life and requires extensive repair
 - D Requires renewal to prevent increased expenditure





Priority GradingWhere the surveyor has concluded that works are necessary within Year 1 the survey item has been prioritised as follows:

- 1. Health & Safety i.e. compliance with statute and or duty.
- 2. Neglect will undermine the use of the property.
- 3. Defect that might lead to damage or further deterioration of a building element, surrounding building elements or item of plant resulting in increased expenditure.
- 4. To maintain proper standards.

All building elements have been inspected and recorded as part of this survey and costs are provided for Year 1 only. In general elements that are in good condition, may require no works, are classified as 'A'. Items where no works are required have not generally been measured and no costs entered against them. Where an action is necessary a priority grading is provided.

All categories of condition or priority have been estimated and costed for use within and for the formulation of a 30 year Life Cycle Plan of each property.

Costs The rates used to estimate the costs of the various recommended works have been predominately derived from "Spon's Architect's and Builders Price Book ", and Cost Models (particularly for Mechanical & Electrical tasks) published by Davis Langdon & Everest. Other items are the subject of "spot" estimates based on the surveyor's experience and assessment of the work requirements. Budget cost estimates are included for all items where work is considered necessary in Year 1 and represent the likely cost which will need to be





expended on the basis each item is carried out individually and not as part of one contract. These costs are net figures and have not been assessed to include preliminaries, contingencies, fees or VAT.

The costs are for indicative budget purposes only as the rates are indicative for typical task and do not necessarily take into account specific variations in material or form.

The costs provided in the Summary take precedence over costs in Year One of the Life Cycle Report, where a discrepancy is found.

Building & Room

Numbers All buildings and rooms within the property have been numbered to enable defects itemised, to be inspected on site. This data has been incorporated into the database to enable calculations to be made where appropriate.

Life Cycle Cost

Plan

A Life Cycle Cost Plan is provided and is based on Year 1 works prices at April 2009. Value Added Tax is excluded.

The Life Cycle profile presented is on a property basis.

Life expectancy of building elements identified during the survey process within the Condition Survey Report are transferred into the relevant year of the corresponding Life Cycle Cost Plan and a renewal cost given within that year. The life span of the building elements, which are taken from industryaccepted norms, defines in future years within the 30 Year periods when that element should be renewed again. Depending on the element concerned predictable repair cost allowances are then made within that life span when periodic, cyclical maintenance is undertaken. It does not allow for emergency, unpredictable or unforeseeable repairs.

Where a building element has a sub-element which can be predicted to fail requiring regular periodic





renewal and is of such significance that the element as a whole will fail without its renewal, then that has been included within the Life Cycle Cost Plan for renewal of the entire element. Other significant maintenance costs are also given as appropriate:

For example, where a PVC window has a timber subframe and the timber frame fails at 20 years then the renewal of the entire unit would occur which is earlier than the actual life of the PVC frame. Where a PVC window has a hermetically sealed double-glazing unit only the glazed unit would be renewed when the glazing fails at 10 years.

The lower life expectancy of any building element stated within a Condition Survey report takes precedence over any other as the life remaining that is carried forward to the corresponding Life Cycle Cost Plan





SECTION 2

Summary

Roosendael House

Date of Survey	24/03/2009 13:25:34
Surveyor(s)	Owen Holleway, Richard Robertson, Tony Duffy

Summary of Yr 1 Costs

<u>Element</u>		Priority 1 Work (£)	Priority 2 Work (£)	Priority 3 Work (£)	Priority 4 Work (£)	TOTAL (£)
Externally						
1. Roofs		0	0	3,973	270	4,243
2. Walls		0	0	0	325	325
3. Grounds		0	0	0	300	300
Internally						
4. Structure		0	0	0	0	0
Internal Fabric						
5. Rooms		0	0	0	7,076	7,076
6. Fixtures & Fittings		0	0	0	820	820
7. Sanitary		0	0	0	328	328
8. Health & Safety		0	0	0	0	0
9. Fire Matters		0	0	0	0	0
10. Hazardous Materials		0	0	0	0	0
11. DDA Compliance & Sta	atus	0	0	0	0	0
12. Security Arrangements	i	0	0	0	0	0
13. Mechanical Services		0	0	0	0	0
14. Electrical Services		0	0	0	0	0
15. Other Mechanical & Ele	ectrical	0	0	0	0	0
Т	DTAL £	0	0	3,973	9,119	13,092





SECTION 3

Brief Description of Property





BRIEF DESCRIPTION OF PROPERTY

Overall Condition	В

Overall condition of the property – Rated A – D

- A Performing well and operating efficiently
- B Performing adequately but showing minor deterioration
- C Showing major defects and/or not operating adequately
- D Life expired and/or serious risk of imminent failure

<u>Building</u>

Block 1 (Kyd): Traditionally built two-storey stone construction with basement and attic areas.

Building comprises slated/mineral felt roofs and stone walls with timber single and double glazed windows and porch at Main entrance. Internal finishes – decoration, floor coverings, internal doors are in good order.

Sanitary ware is generally in a satisfactory condition.

Block 2 (McKinney): Brick built roughcast and brick wall finish, metal profiled roof and a combination of timber and PVC-u double-glazed windows.

Internal finishes – decoration, floor coverings, internal doors are in good order.

Sanitary ware is generally in a satisfactory condition.

Block 3 (Dalhousie): Brick built roughcast wall finish, metal profiled roof and PVC-u double-glazed windows.

Internal finishes – decoration, floor coverings, internal doors are in good order.

Sanitary ware is generally in a satisfactory condition.





Block 4 (Keays): Concrete framed, brick and roughcast wall finishes, concrete tiled roof and PVC-u double-glazed windows; purpose built addition from McKinney block.

Internal finishes – decoration, floor coverings, internal doors are in good order.

Sanitary ware is generally in a satisfactory condition, although upgrading to some toilets required (currently in progress in unoccupied rooms).

Block 5 (Dining): Situated between Kyd and McKinney blocks, the block is a traditionally built building with proprietary roof covering and roughcast walls, together with aluminium/timber glazed windows and doors.

Internal finishes – decoration, floor coverings, internal doors are in good order.

Block 6 (Greenhouse): PVC-u/glazed wall and roof sections. Internal finishes – decoration, floor coverings in good order.

Block 7 (Flat 1A): Traditionally built two-storey house with ground floor flat and upper floor incorporated into McKinney block. Building comprises slated roof and stone walls with timber framed and PVC-u double glazed windows and added porch with mineral felt roof and PVC-u door and frame.

Block 8 (Lodge): The Lodge is a traditionally built bungalow with slate roof; stone and roughcast walls and timber/aluminium double-glazed windows.

<u> M&E</u> Block1 – 6

Main Power Incomer:

Power is supplied from the main REC supplies. This feeds a switching system supplying a number of Distribution Boards (DB). A number of observations were noted:

- No Statuary Signage present at main DB location
- Evidence of cables disconnected from the DB and left in place, BS7671 states that all redundant cabling should be removed.







Redundant cables should be removed.

• A CB has been installed with the protective cover incorrectly fitted.



Cover not fitted properly.



Power distribution was via a mix of Wylex, GEC and Merlin Gerin DBs located around the bld. Wiring was contained within trunking. This also houses the IT & Telephone system. All were in a fair condition with no defects noted. However there was evidence of extension leads and 3-way adapters in use throughout the bld. This can lead to an overload of the circuits, it is recommended that the use of extensions is reviewed and the removal of 3-way adapters is considered.



3-way adapters in use

particularly worrying, a 3-way adapter plugged into an extension lead

Heating:

Heating was provided from three different boiler rooms supplying different locations within the main bld.

McKinney & Dalhousie Block:

Heating was provided by 2 Remeha Quinta 65 Gas fired boilers. Hot water from system was pumped round the bld to a number of convection radiators, by a Grundfos pumping setup. The heating and its associated equipment were in fair condition with no defects noted. However within the boiler room there was evidence of water pooling on the floor, the source of this is unknown and should be investigated further. There was also a hose within the boiler room which appeared to be redundant; it is recommended that its purpose be ascertained.







Redundant Hose

Water pooling on floor.

Kyd Block:

Heating was provided by 2 Remeha Quinta 65 Gas fired boilers. Hot water from the system was pumped round the bld to a number of convection radiators, by a Grundfos pumping setup. The heating and its associated equipment were in fair condition however it was noted that the control of the radiators via the TRV's was poor, within rooms 3, 5 & 7 the radiators were cold when on settings 3 & 4, when TRV turned slightly the radiator appeared to heat to maximum temperature. It is recommended that the set up of the TRV's is investigated.



TRV operation to check





Keays Block:

Heating was provided by a Powrmatic Gas fired boiler. Hot water from system was pumped round the bld to a number of convection radiators by a Grundfos pumping setup. The heating and its associated equipment were in fair condition with no defects noted.

Conservatory:

Within the Conservatory two Dimplex Electric have been installed, however one of them has been plugged into the ring main and the other has still to be connected. As these heaters have been fixed to the wall they are now a fixed source of heating therefore it is recommended that they be supplied by a dedicated circuit.



Still to be connected

Connected via a standard plug

Greenhouse:

Within the greenhouse Electric Tubular heating was installed. The condition of this was fair with no defects noted.

<u>Lighting:</u>

In the main this was T8, (fitted with anti glare diffusers) tungsten and 2D fluorescent fittings. The corridors were controlled by PIR's all other lighting were manually controlled. The condition of the lighting and its associated equipment was fair with no defects noted. However this survey did not look at system compliance, a further lighting compliance survey would be required.





It is recommended that an ongoing maintenance plan is introduced for the replacement of all tungsten lights with CFL lighting; this would help towards reducing the annual electricity costs.

Emergency Lighting:

This consisted of a mix of maintained and non-maintained self contained fittings. The condition of the system was fair with no defects noted. However this survey did not look at system compliance, a further in-depth compliance survey would be required.

External Lighting:

This consisted of a number of Halogen Floodlight and Spotlights which are controlled by dawn/dusk sensors. The condition of these was fair with no defect noted. However this survey did not look at system compliance, a further in-depth compliance survey would be required.

Fire Alarm:

An automatic system consisting of a number of break glass manual call points, detectors and audible alarms connected to a Gent Vigilon Compact control panel. The condition of the system was fair with no defects noted. However this survey did not look at system compliance, a further in depth compliance survey would be required.

<u>I.T.</u>

The bld is connected to the main Council IT network via a Netgear Router located within the Managers office. This provides a secure wireless network throughout the building. The condition of the IT network was fair with no defects noted.

Domestic Hot Water:

McKinney Block:

Hot water was provided by the main boiler to a Calorfier, the water was pumped throughout the bld by Grundfos pumps. All pipework was lagged and identified. The condition of the equipment was fair with no defects noted.





Dalhousie Block:

Hot water was provided by an electric Calorfier, the water was pumped throughout the bld by Grundfos pumps. All pipework was lagged and identified. The condition of these was fair with no defects noted.

Kydd Block & Kitchen:

Hot water was provided by two A.O.Smith Gas Fired DHW Boilers. The water was pumped throughout the bld by Grundfos pumps. All pipework was lagged and identified. The condition of these was fair with no defects noted.

Keays Block:

Hot water was provided by the main boiler to a Calorfier, the water was pumped throughout the bld by Grundfos pumps. All pipework was lagged and identified. The condition of the equipment was fair with no defects noted.

Ventilation:

There was a mix of Manrose, Vectaire and Vent Axia single point extractors in use within the toilets in the resident's rooms. Single point Delta Extract extractors are installed within communal toilets. The dining area has a Roof Units Group extraction system in place. Within the kitchen an industrial Canopy Extractor was installed and a Vent Axia extractor fitted. A mix of Vent Axia and Xpelair extraction units were installed within the Laundry room. The condition of these was fair with no defects noted.

<u>CCTV:</u>

A 7-camera CCTV system is in use. This covers the entrances and the ground boundaries .The condition of these was fair with no defects noted.

Security System:

There is a secure door entry installed and the bld is protected by a Nova alarm system. The condition of these was fair with no defects noted.





Lift:

There were two passenger lifts in use within the main building. The condition of these and their associated equipment was fair with no defects noted.

Pre Planned Maintenance

At the time of survey, there was no evidence of a Pre-Planned Maintenance Scheme covering the Dundee facilities in place. It is therefore recommended that a Planned Maintenance Program is introduced.

Block 7 (Flat 1A)

Main Power Incomer:

Power is supplied from the main Bld REC supply. This feeds the MEM Distribution Board (DB).

Power Distribution:

Power distribution was via a MEM DB located within a cupboard in the hallway. Wiring was contained within the walls of the bld. All were in a fair condition with no defects noted.

<u>Heating:</u>

Heating was provided by boilers within the Keays block of the main bld. Hot water from the system was pumped round the bld to a number of convection radiators. The heating and its associated equipment were in fair condition with no defects noted.

<u>Lighting:</u>

In the main this was a mix of tungsten, CFL, and T8 fittings. There were no signs of automatic controls. The condition of the lighting and its associated equipment was fair with no defects noted. However this survey did not look at system compliance, a further lighting compliance survey would be required.





This consisted of tungsten fitting with PIR control front of the bld. At the rear of the bld there is a Halogen fitting with PIR control. The condition of these was fair with no defect noted. However this survey did not look at system compliance, a further in-depth compliance survey would be required.

Fire Alarm:

Smoke detectors connected to the main bld Fire Alarm System have been installed. The condition of the detectors was fair with no defects noted. However this survey did not look at system compliance, a further in depth compliance survey would be required.

Domestic Hot Water:

Hot water was supplied by a 3Kw single electric immersion Calorfier. The condition of this was fair with no defects noted.

Ventilation:

Within the toilet an Aidelle Loovent extractor is fitted and a domestic extractor hood is fitted within the kitchen. The condition of these was fair with no defects noted.

Security System:

The bld is protected by a Nova alarm system. The condition of this was fair with no defects noted.

A CCTV camera is mounted on the bld facing the boundary area; this is monitored from the main house. The condition of this was fair with no defect noted.

<u>Shed:</u>

Within the garden a shed has been erected. An electrical power supply from the house supply has been installed. This is connected directly to a twin socket. The supply to a single tungsten light is wired into the rear of the socket and a RCD is plugged into the socket protecting a 4way extension.







The supply to the shed should be from a dedicated circuit with rcd protection. This should then supply DB within the shed. From this the lighting and socket supplies should be supplied from dedicated circuits. Both should have rcd protection and the sockets installed should be external sockets. It is recommended that this installation complies with the requirements of BS7671.

Block 8 (Lodge)

Main Power Incomer:

Power is supplied from the main REC supplies. This feeds a MEM Distribution Board (DB). The main incomer and associated equipment were located within a dedicated cupboard in the hallway. All were in fair condition with no defects evident.

Power Distribution:





Power distribution was via a MEM DB located within a cupboard in the hallway. Wiring was contained within the walls of the bld. All were in a fair condition with no defects noted.

<u>Heating:</u>

Heating was provided by a Saunier Duval Combi-boiler. Hot water from system was pumped round the bld to a number of convection radiators. The heating and its associated equipment were in fair condition with no defects noted.

<u>Lighting:</u>

In the main this was a mix of tungsten and CFL fittings. There were no signs of automatic controls. The condition of the lighting and its associated equipment was fair with no defects noted. However this survey did not look at system compliance, a further lighting compliance survey would be required.

External Lighting:

This consisted of tungsten fitting with PIR control and a Halogen fitting with Dawn/dusk and PIR control at the rear of the bld. At the front of the bld there is Halogen fittings with PIR control. The condition of these was fair with no defect noted. However this survey did not look at system compliance, a further in-depth compliance survey would be required.

Fire Alarm:

There are two battery operated smoke detectors situated within the hallway. The condition of the detectors was fair with no defects noted. However this survey did not look at system compliance, a further in depth compliance survey would be required.

Domestic Hot Water:

Hot water was supplied by the Combi-boiler to the kitchen, toilet and bathroom. The condition of these was fair with no defects noted.

Ventilation:

Within the shower a domestic extractor fitted and a domestic extractor hood is fitted within the kitchen. The condition of these was fair with no defects noted.





The bld is protected by a Nova alarm system. The condition of this was fair with no defects noted.

A CCTV camera is mounted on the bld facing the main entrance from the main road; this is monitored from the main house. The condition of this was fair with no defect noted.





SECTION 4

Properties, Buildings & Room Lists

Building Name : Block 01 Kyd Room No Room Name **Entrance Foyer** 002/1/0/001 002/1/0/002 Hall Office 002/1/0/003 002/1/0/004 Library 002/1/0/005 Games 002/1/0/006 Reception 002/1/0/007 Hall 002/1/0/008 Manager **Circulation Area** 002/1/0/009 002/1/0/010 Store 002/1/0/011 Store 002/1/0/012 Lounge 002/1/0/013 Laundry **Circulation Area** 002/1/0/014 002/1/0/015 **Kitchen Store Kitchen** 002/1/0/016 Kitchen (small area) 002/1/0/017 002/1/0/017A Store 002/1/0/018 **Kitchen Store** 002/1/0/019 **Kitchen Store Kitchen Staff** 002/1/0/020 002/1/0/021 **Kitchen Store Circulation Area** 002/1/0/022 **Circulation Area** 002/1/0/022A 002/1/0/023 **Circulation Area** 002/1/0/023A **Store** 002/1/0/024 **Store** 002/1/0/025 Store 002/1/0/026 **Toilet**

Building Name : Block 01 Kyd **Room No Room Name** 002/1/1/001 **Circulation Area** 002/1/1/002 **Bathroom** 002/1/1/003 **Boiler** 002/1/1/004 **Bedroom 7** 002/1/1/005 **Toilet 7** 002/1/1/006 **Bedroom 6 Toilet 6** 002/1/1/007 002/1/1/008 **Bedroom 5 Toilet** 002/1/1/009 002/1/1/010 **Circulation Area** 002/1/1/011 Store (No Access) 002/1/1/012 Bedroom 4 002/1/1/013 **Toilet 4 Circulation Area** 002/1/1/014 002/1/1/015 **Bedroom 3** 002/1/1/016 **Toilet 3** 002/1/1/017 **Circulation Area** 002/1/1/018 **Bedroom 2** 002/1/1/019 **Toilet 2** 002/1/1/020 **Circulation Area** 002/1/1/021 **Bedroom 1** 002/1/1/022 Toilet 1 002/1/1/023 **Circulation Area**

Building Name : Block 02 McKinney	
Room No	Room Name
002/2/0/001	Circulation Area
002/2/0/002	Circulation Area
002/2/0/003	Store
002/2/0/004	Toilet
002/2/0/005	Toilet
002/2/0/006	Store
002/2/0/007	Plant Room
002/2/0/008	Circulation Area
002/2/0/009	Circulation Area
002/2/0/010	Bedroom 8
002/2/0/011	Toilet 8
002/2/0/012	Bedroom 9
002/2/0/013	Toilet 9
002/2/0/014	Circulation Area/Stairs
002/2/0/015	Circulation Area/Stairs
002/2/0/016	Grampian Lounge
002/2/1/001	Circulation Area
002/2/1/001A	Circulation Area
002/2/1/002	Bedroom 22
002/2/1/003	Toilet 22
002/2/1/004	Circulation Area 21
002/2/1/005	Bedroom 21
002/2/1/006	Toilet 21
002/2/1/007	Living Room 21
002/2/1/008	Store 21
002/2/1/009	Circulation Area 20
002/2/1/010	Bedroom 20
002/2/1/011	Toilet 20
002/2/1/012	Living Room 20
	-

Building Name : Block 02 McKinney	
Room No	Room Name
002/2/1/013	Store (No Access)
002/2/1/014	Circulation Area 19
002/2/1/015	Bedroom 19
002/2/1/016	Toilet 19
002/2/1/017	Living Room 19
002/2/1/018	Circulation Area 18
002/2/1/019	Bedroom 18
002/2/1/020	Toilet 18
002/2/1/021	Living Room 18
002/2/1/022	Circulation Area (included in adjacent area)
002/2/1/023	Circulation Area 24
002/2/1/024	Bedroom 24
002/2/1/025	Toilet 24
002/2/1/026	Living Room 24
002/2/1/027	Bedroom 23
002/2/1/028	Toilet 23

Building Name : Block 03 Dalhousie	
Room No	Room Name
002/3/0/001	Circulation Area/Stairs
002/3/0/002	Store (Designed Out)
002/3/0/003	Circulation Area (included in adjacent area)
002/3/0/004	Store
002/3/0/005	Store
002/3/0/006	Circulation Area
002/3/0/007	Bedroom 12A
002/3/0/008	Toilet 12A
002/3/0/009	Bedroom 12
002/3/0/010	Toilet 12
002/3/0/011	Bedroom 11
002/3/0/012	Toilet 11
002/3/0/013	Bedroom 10
002/3/0/014	Toilet 10
002/3/0/015	HWC Tank room
002/3/1/001	Circulation Area
002/3/1/002	Bathroom
002/3/1/003	Bedroom 17
002/3/1/004	Toilet 17
002/3/1/005	Bedroom 16
002/3/1/006	Toilet 16
002/3/1/007	Store
002/3/1/008	Store
002/3/1/009	Circulation Area (included in adjacent area)
002/3/1/010	Bedroom 15
002/3/1/011	Toilet 15
002/3/1/012	Bedroom 14

Building Name : Block 03 Dalhousie Room No 002/3/1/013

Room Name Toilet 14

Building Name : Block 04 Keays	
Room No	Room Name
002/4/0/001	Circulation Area (included in adjacent area)
002/4/0/002	Lounge
002/4/0/003	Male WC
002/4/0/004	Store
002/4/0/005	Bedroom 39
002/4/0/006	Toilet 39
002/4/0/007	Bedroom 38
002/4/0/008	Toilet 38
002/4/0/009	Circulation Area
002/4/0/010	Bedroom 37
002/4/0/011	Toilet 37
002/4/0/012	Bedroom 36
002/4/0/013	Toilet 36
002/4/0/014	Boiler
002/4/0/015	Store
002/4/0/016	Circulation Area/Stairs
002/4/0/017	Circulation Area
002/4/0/018	Toilet
002/4/0/019	Bedroom 45
002/4/0/020	Toilet 45
002/4/0/021	Bedroom 44
002/4/0/022	Toilet 44
002/4/0/023	Bedroom 43
002/4/0/024	Toilet 43
002/4/0/025	Circulation Area
002/4/0/026	Bedroom 42
002/4/0/027	Toilet 42
002/4/0/028	Bedroom 41

Building Name : Block 04 Keays	
Room No	Room Name
002/4/0/029	Toilet 41
002/4/0/030	Bedroom 40
002/4/0/031	Toilet 40
002/4/0/032	Toilet
002/4/0/033	Lift Machinery
002/4/1/001	Circulation Area (included in adjacent area)
002/4/1/002	Electrical Store
002/4/1/003	Bedroom 25
002/4/1/004	Toilet 25
002/4/1/005	Bathroom
002/4/1/006	Bedroom 26
002/4/1/007	Toilet 26
002/4/1/008	Bedroom 27
002/4/1/009	Toilet 27
002/4/1/010	Circulation Area
002/4/1/011	Bedroom 28
002/4/1/012	Toilet 28
002/4/1/013	Bedroom 29
002/4/1/014	Toilet 29
002/4/1/015	Bedroom 30
002/4/1/016	Toilet 30
002/4/1/017	Toilet
002/4/1/018	Circulation Area
002/4/1/019	Cupboard (No Access)
002/4/1/020	Bedroom 31
002/4/1/021	Toilet 31
002/4/1/022	Bedroom 32
002/4/1/023	Toilet 32

Building Name : Block 04 Keays	
Room No	Room Name
002/4/1/024	Circulation Area
002/4/1/025	Bedroom 33
002/4/1/026	Toilet 33
002/4/1/027	Bedroom 34
002/4/1/028	Toilet 34
002/4/1/029	Bedroom 35
002/4/1/030	Toilet 35

Building Name : Block 05 Dining Room No 002/5/0/001

Room Name Dining Room

Building Name : Block 06 Greenhouse	
Room No	Room Name
002/6/0/001	Conservatory 1
002/6/0/002	Conservatory 2

 Building Name : Block 07 Flat 1A

 Room No
 Ro

 002/7/0/001
 Liv

 002/7/0/002
 Kit

 002/7/0/003
 Cir

 002/7/0/004
 Ba

 002/7/0/005
 Be

Room Name Living Room Kitchen Circulation Area Bathroom Bedroom

PROPERTY, BUILDING & ROOM LIST

Building Name : Block 08 Lodge Room No 002/8/0/001 002/8/0/002 002/8/0/003 002/8/0/004 002/8/0/005 002/8/0/006 002/8/0/006 002/8/0/009 002/8/0/009 002/8/0/010

Room Name Vestibule Bedroom 1 Bedroom 2 Living Room Bathroom Toilet Kitchen Circulation Area Bedroom 3 Bedroom 4





SECTION 5

Survey Report

ROOFS

BUILDING : Block 01 Kyd	UPRN :		R : Roof			
ROOM : Roof001	No : 002/1	/R/001 US	E:			
Element : Covering	CODE:1					Replacement
Description Natural slate	Condition Fair with several slipped ,cra	Action cked Repair/Replace missing,cra	Cond/Ind Priority cked B 3	L'Expec 25	Quantity 224 m2	Cost (£) 41,341
	and missing slates	and slipped slates				Year 1 Repair Cost (# 500
Photo 1	Photo 2		osition			Replacement
Description Mineral felt	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Description Mineral felt	Fair	No action required	В	15	37 m2	3,034






Photo 2



Element : Rainwater goods Description Cast iron ogee gutters and downpipes 2 No. Cast iron outlet boxes	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 15	Quantity 37 m	Replacement Cost (£) 2,529 Year 1 Repair Cost (£)
Photo 1	Photo 2	Ρ	osition			
Element : Rainwater goods	CODE:1					Replacement
Description UPVC downpipe	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 10	Quantity 4 m	Cost (£) 164
						Year 1 Repair Cost (£)
Photo 1	Photo 2	Ρ	osition			

Element : Chimney stacks/flues Description	CODE : 1 Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Replacement Cost (£)
Stone chimneys	Fair although chimney inspectio required	n Chimney inspection required to assess condition of pointing to pots	Β 4	30	3	No.	7,341 Year 1 Repair Cost (£ 150
Photo 1	Photo 2	Positi	on IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII				
Element : TV aerials/dishes etc Description	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 10	Quantit 10	y No.	Replacement Cost (£) 1,640
10 No. Metal aerials/dishes				10	10		







Element : TV aerials/dishes etc Description Weather vane	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 15	Quantity 1 No.	Replacement Cost (£) 800 Year 1 Repair Cost (f
Photo 1	Photo 2	F	Position			
Element : Decoration Description Redecorate all CI gutters and downpipes Gloss paint to timber finishes	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 3	Quantity 41 m2	Replacement Cost (£) 336 Year 1 Repair Cost (
Element : Roof Lights Description Leaded timber framed GW rooflight	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 25	Quantity 1	Replacemen Cost (£) 600



BUILDING : Block 01 Kyd ROOM : Roof002	UPRN : No : 002/1		FLOOR : Roof USE :					
Element : Covering	CODE : 1							Replacement
Description Mineral felt	Condition Fair	Action No action required	Cond/Ind F B	Priority L'Ex 10	рес Q 12	uantity 2	m2	Cost (£) 984
								Year 1 Repair Cost (£
Photo 1	Photo 2		Position					
Element : Structure Description	CODE : 1 Condition	Action	Cond/Ind F	Priority L'Ex		uantity		Replacement Cost (£)

Element : Flashings	CODE : 1						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Felt	Fair	No action required	В	10	8 m2	m2	656
							Year 1 Repair Cost (

Element : Rainwater goods	CODE:1						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
CI Downpipe	Fair	No action required	В	15	4	m	273
							Year 1 Repair Cost (£)
Photo 1	Photo 2	Pos	sition				

BUILDING : Block 01 Kyd	UPRN :	FLOC	R:Roof			
ROOM : Roof003	No : 002/	1/R/003 US	USE :			
Element : Covering	CODE : 1					Replacement
Description Natural slate	Condition Fair with several slipped sla		Cond/Ind Priorit	y L'Expec 25	Quantity 36 m2	Cost (£) 5,758
		slates				Year 1 Repair Cost (£ 150
Photo 1	Photo 2		Position			
Element : Structure Description	CODE : 1 Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Replacement Cost (£)
Timber joists and rafters	Fair	No action required	В	35	36 m2	3,986
						Year 1 Repair Cost (£
Element : Flashings	CODE : 1					Replacement
Description Lead (inc. in roof)	Condition Fair	Action No action required	Cond/Ind Priorit	y L'Expec 25	Quantity 24 m	Cost (£) 1,804
						Year 1

Repair Cost (£)

Photo [•]	1
--------------------	---




Element : Parapets CODE:1 Replacement Description Condition Action Cond/Ind Priority L'Expec Quantity Cost (£) Lead gutter Fair No action required В 25 18 m 2,706 Year 1 Repair Cost (£)

Position

Photo 1 Position Position Element : Rainwater goods COE :1 COE :1

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)	·
Cast iron downpipe Cast iron outlet box	Fair but with choked outlet	Clean out choked gutters	В	15	4	m	273	
							Year 1	

Repair Cost (£)



Replacement Cost (£) Quantity m2 32

3

4

Year 1 Repair Cost (£)

Element : Roof Lights	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Metal glazed skylight	Fair	No action required	В	15	1	300
						Year 1 Repair Cost (f

Photo 1



Photo 2

Element : Roof Lights	CODE :	1				Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
2 No. Leaded timber framed GW rooflights	Fair	No action required	В	25	2	5,000
loongno						Year 1 Repair Cost (£)
Photo 1	P	Photo 2	Position			

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : Roof			
ROOM : Roof004	No : 002/1/R/004		USE :			
Element : Covering	CODE : 1					Replacement
Description Mineral felt	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 10	Quantity 6 m2	Cost (£) 492
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : Structure Description Timber joists and rafters	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 35	Quantity 6 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (
Element : Flashings	CODE : 1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Felt	Fair	No action required	В	10	5 m2	410
						Year 1

Photo 1	Photo 2		Position			
Element : Rainwater goods	CODE:1					Replacement
Description CI Downpipe and box	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 15	Quantity 4 m	Cost (£) 273
						Year 1 Repair Cost (£)
Photo 1	Photo 2		Position			

BUILDING : Block 01 Kyd	UPRN :	FLOOR : R	oof			
ROOM : Roof005	No : 002/1/R/0	05 USE :	USE :			
Element : Covering	CODE:1					Replacement
Description Natural slate	Condition Fair with several slipped slates	Action Repair/Replace missing,slipped slates	Cond/Ind Priority B 3	L'Expec 25	Quantity 98 m2	Cost (£) 15,675
		Sidles				Year 1 Repair Cost (100
Photo 1	Photo 2	Positi	on			
Element : Structure	CODE : 1					
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Timber joists and rafters	Fair	No action required	В	35	98 m2	10,852
						Year 1 Repair Cost (/
Element : Flashings	CODE : 1					Replacement
Description Lead (inc. in roof)	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 25	Quantity 7 m	Cost (£) 526
						Year 1 Repair Cost (#

Element : Flashings Description Galvanised zinc ridging and hips	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 30	Quantity 32 m	Replacement Cost (£) 2,406 Year 1 Repair Cost (£)
Element : Rainwater goods Description Cast iron ogee gutters and downpipes Cast iron outlet box	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 15	Quantity 47 m	Replacement Cost (£) 3,212 Year 1 Repair Cost (£)
Photo 1	Photo 2		Position			
Element : Decoration Description Redecorate all CI gutters and downpipes	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 3	Quantity 47 m2	Replacement Cost (£) 385 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	FLOOR : R	loof			
ROOM : Roof006	No : 002/1/R/0	06 USE :	USE :			
Element : Covering Description	CODE : 1 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Natural slate	Fair with several slipped slates	Repair/Replace missing,slipped slates	B 3	25	154 m2	24,632
		314163				Year 1 Repair Cost (300
Photo 1	Photo 2	Positi	on			
Element : Structure	CODE :1					Replacement
Description Timber joists and rafters	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 35	Quantity 154 m2	Cost (£) 17,053
						Year 1 Repair Cost (ł
Element : Flashings	CODE : 1					Replacement
Description Galvanised zinc ridging and hips	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 25	Quantity 24 m	Cost (£) 1,804
						Year 1 Bopair Cost (/

Repair Cost (£)

Photo 2

Element : Flashings	CODE:1						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Lead (inc. in roof)	Fair with patching	No action required	В	25	58	m	4,361
							Year 1 Repair Cost (£)
Photo 1	Photo 2		Position				
Element : Rainwater goods	CODE : 1						
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	itv	Replacement Cost (£)
Cast iron downpipe Cast iron outlet box	Fair	No action required	B	15	3	m	205
Cast non ouliet box							Year 1 Repair Cost (£)

Photo 2

Element : Rainwater goods	CODE:1							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantit	у	Cost (£)
UPVC Gutters and downpipes	Fair	No action required	В		15	25	m	1,025
								Year 1 Repair Cost (£
Photo 1	Photo 2	Positi	on					
Element : Chimney stacks/flues Description	CODE : 1 Condition	Action	Cond/Ind	Priority	L'Expec	Quantit		Replacement Cost (£)
Stone chimney	Fair	Chimney inspection to determine condition of pointing to pots		25	1 No.	-	2,447	
								Maran 4

Position







Position

Element : TV aerials/dishes etc	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Metal aerials/dishes	Fair	No action required	В	10	1 No.	164
						Year 1 Repair Cost (£)
Photo 1	Photo 2		Position			
Element : Decoration	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Redecorate CI downpipe and box	Fair	No action required	В	3	3 m2	24

Element : Roof Lights	CODE : 1			L'Expec 25		Replacement
Description Leaded timber framed GW rooflights	Condition Fair	Action No action required	Cond/Ind Priority B		Quantity 1	Cost (£) 1,200
roomgnio						Year 1 Repair Cost (£)
Photo 1	Photo	2	Position			



BUILDING : Block 01 Kyd ROOM : Roof007	UPRN : No : 00)2/1/R/007	FLOOR : Roof USE :			
Element : Covering	CODE : 1					
Description Mineral felt	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 10	Quantity 6 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Structure	CODE : 1					Replacement
Description Timber joists and rafters	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 35	Quantity 6 m2	Cost (£) 492
						Year 1 Repair Cost (£

Element : Flashings	CODE:1						Replacement	
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)	
Felt	Fair	No action required	В	10	6 r	m2	492	
							Voor 1	

Element : Rainwater goods Description	CODE : 1 Condition	Action	Cond/Ind Priority	L'Expec	Quant	itv	Replacement Cost (£)
CI Downpipe and box	Fair	No action required	B	15	4	m	273
							Year 1 Repair Cost (£)
Photo 1	Photo 2	F	Position				

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Roof			
ROOM : Roof008	No : 002/	(1/R/008	USE :			
Element : Covering	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plastic transluscent sheeting	Fair	No action required	В	10	5 m2	410
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : Structure Description Metal roof sections	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 20	Quantity 5 m2	Replacement Cost (£) 847
						Year 1 Repair Cost (
Element : Flashings	CODE : 1					Replacement

Liement. Hashings	CODE						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Lead (inc. in roof)	Fair	No action required	В	35	4	m	300
							Year 1

Repair Cost (£)

Element : Rainwater goods Description uPVC Ogee gutters	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 15	Quantity 4 m	Replacement Cost (£) 164 Year 1 Repair Cost (£)
Photo 1	Photo 2	F	Position			
Element : Rainwater goods	CODE :1					Replacement
Description Cast iron/downpipe	Condition Fair but joint requires refixing	Action Refix defective joint	Cond/Ind Priority B 3	L'Expec 20	Quantity 3 m	Cost (£) 205
						Year 1 Repair Cost (£)
						70
Element : Decoration	CODE : 1					70
Element : Decoration Description	CODE : 1 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	
		Action No action required	Cond/Ind Priority B	L'Expec 3	Quantity 3 m2	70 Replacement Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Roofs			
ROOM : Roof001	No : 002/	2/R/001	USE :			
Element : Covering	CODE:1					Replacement
Description Metal profiled sheeting	Condition Fair	Action No action required	Cond/Ind Priority B	20 L'Expec	Quantity 270 m2	Cost (£) 26,391
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : Structure	CODE : 1					Replacement
Description Timber joists and rafters	Condition Fair	Action No action required	Cond/Ind Priority B	/ L'Expec 35	Quantity 270 m2	Cost (£) 28,791
						Year 1 Repair Cost (I
Element : Rainwater goods	CODE : 1					Replacement
Description UPVC Gutters and downpipes	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 45 m	Cost (£) 1,845
			_			Year 1 Repair Cost (£

Element : Rainwater goods	CODE:1						Replacem
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	у	Cost (£)
Cast iron gutters and downpipes	Fair	No action required	В	15	36	m	2,460
							Year 1 Repair Cos
Element : Fascias	CODE : 1						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	у	Cost (£)
Plastisol fascias and soffits	Fair	No action required	В	28	32	m	2,624
							Year 1 Repair Co
Element : Chimney stacks/flues	CODE : 1						Replacem
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	у	Cost (£)
Brick chimney	Fair	No action required	В	20	1	No.	2,447
							Year 1 Repair Co
Element : TV aerials/dishes etc	CODE:1						Replacem
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	у	Cost (£)
Metal aerials/dishes	Fair	No action required	В	10	4	No.	656
							Year 1 Repair Co

Element : Decoration Description	CODE : 1 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
All timber and Cl downpipes/gutters	Fair	No action required	В	3	36	m2	295
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Roofs			
ROOM : Roof002	No : 002/2/R/002		USE :			
Element : Covering	CODE : 1					Replacement
Description Proprietory roof coating	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 13	Quantity 56 m2	Cost (£) 4,593
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Structure	CODE : 1					Devlessment
Description Timber joists and rafters	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 35	Quantity 56 m2	Replacement Cost (£) 4,593
						Year 1 Repair Cost (£
Element : Rainwater goods	CODE : 1					Replacement
Description UPVC downpipe	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 23	Quantity 5 m	Cost (£) 205
						Year 1 Repair Cost (£

Element : Fascias Description	CODE : 1 Condition	Action	Cond/Ind Priority	L'Expec	Qua	ntity	Replacement Cost (£)
Metal profiled fascias	Fair	No action required	В	15	1	m	82
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Roofs			
ROOM : Roof003	No : 002/2/R/003		USE :			
Element : Covering	CODE:1					Replacement
Description Mineral felt	Condition Fair	Action No action required	Cond/Ind Priorit	y L'Expec 13	Quantity 100 m2	Cost (£) 4,593
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Structure	CODE : 1					Replacement
Description Timber joists and rafters	Condition Fair	Action No action required	Cond/Ind Priorit	y L'Expec 35	Quantity 100 m2	Cost (£) 8,202
						Year 1 Repair Cost (£
Element : Rainwater goods	CODE : 1					Replacement
Description Cast iron/downpipes	Condition Fair	Action No action required	Cond/Ind Priorit	y L'Expec 23	Quantity 23 m	Cost (£) 1,572
						Year 1 Repair Cost (£

Element : Fascias Description Timber softwood fascias	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 15	Quantity 37 m	Replacement Cost (£) 1,264
						Year 1 Repair Cost (£)
Element : Decoration	CODE : 1 Condition	Action	Cond/Ind Priority	l 'Expos	Quantity	Replacement
Description All timber and CI	Fair	No action required	B	L'Expec 3	Quantity 60 m2	Cost (£) 492
downpipes/gutters	i an		D	0	00 1112	Year 1
						Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Roof			
ROOM : Roof001	No : 002/3,	/R/001	USE :			
Element : Covering	CODE:1					Replacement
Description Metal profiled sheeting	Condition Fair	Action No action required	Cond/Ind Pric B	rity L'Expec	Quantity 104 m2	Cost (£) 10,165
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : Structure	CODE : 1					Replacement
Description Timber trusses	Condition Fair	Action No action required	Cond/Ind Pric B	rity L'Expec 35	Quantity 104 m2	Cost (£) 11,089
						Year 1 Repair Cost (£
Element : Flashings	CODE : 1					Replacement
Description Metal flashing detail between root	Condition fs Fair	Action No action required	Cond/Ind Pric B	rity L'Expec	Quantity 10 m2	Cost (£) 820
						Year 1 Repair Cost (£

Element : Rainwater goods	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
UPVC gutters and downpipes and soil vent	Fair but with choked gutters	Clean out choked gutters	B 3	9	43 m	1,763
						Year 1 Repair Cost (£) 80
Photo 1	Photo 2	Positi	ion			

BUILDING : Block 04 Keays	UPRN :	FL	LOOR : Roof			
ROOM : Roof001	No :	002/4/R/001	USE :			
Element : Covering Description Concrete interlocking tiles	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 31	Quantity 324 m2	Replacement Cost (£) 34,549
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Covering Description	CODE : 1 Condition	Action	Cond/Ind Priority	L'Expec	Quantity 12 m2	Replacement Cost (£)

Photo 1	Photo 2		Position			
Element : Structure	CODE :1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber joists and rafters	Fair	No action required	В	35	324 m2	34,549
						Year 1 Repair Cost (£)
Element : Flashings	CODE : 1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Lead (inc. in roof)	Fair	No action required	В	41	14 m	1,052
						Year 1 Repair Cost (£)
Element : Rainwater goods	CODE : 1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
UPVC Gutters and downpipes	Fair	No action required	В	15	104 m	4,265
						Year 1 Repair Cost (£)

Element : TV aerials/dishes etc	CODE:1						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Metal aerials/dishes	Fair	No action required	В	10	1	No.	164
							Year 1 Repair Cost (£)


BUILDING : Block 04 Keays	UPRN :		FLOOR : Roof			
ROOM : Roof002	No : 002/4/R/002		USE :			
Element : Covering	CODE:1					Replacement
Description Aluminium frame with glazing panels	Condition Fair	Action No action required	Cond/Ind Priority B	25 L'Expec	Quantity 21 m2	Cost (£) 3,466
						Year 1 Repair Cost (I
Photo 1	Photo 2		Position			
Element : Structure	CODE:1					Replacement
Description Metal purlins and trusses	Condition Fair	Action No action required	Cond/Ind Priority B	 L'Expec 31 	Quantity 21 m2	Cost (£) 4,093
						Year 1 Repair Cost (£
Element : Flashings	CODE:1					Replacement
Description Lead (inc. in roof)	Condition Fair	Action No action required	Cond/Ind Priority B	 L'Expec 41 	Quantity 13 m	Cost (£) 977
						Year 1 Repair Cost (£

Element : Rainwater goods	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
UPVC gutter	Fair but with choked gutter and	Clean out choked gutter	B 3	6	7 m	287
	heavy vegetation					Year 1 Repair Cost (£) 40
Photo 1	Photo 2	Pos	sition			
Element : Decoration	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Paint metal finishes	Fair	No action required	В	3	26 m2	213
						Year 1 Repair Cost (£)

BUILDING : Block 05 Dining	UPRN :		FLOOR : Roof					
ROOM : Roof001	No : 002/5/	/R/001	USE :					
Element : Covering	CODE:1							Replacement
Description Metal profiled sheeting	Condition Fair	Action No action required	Cond/I B	nd Priority	L'Expec 15	Quantit 56	y m2	Cost (£) 5,473
								Year 1 Repair Cost (f
Photo 1	Photo 2		Position					
Element : Structure	CODE : 1							Doplocoment
Description Timber trusses	Condition Fair	Action No action required	Cond/I B	nd Priority	L'Expec 30	Quantit 56	y m2	Replacement Cost (£) 5,971
								Year 1 Repair Cost (£
Element : Flashings	CODE:1							Replacement
Description Felt	Condition Fair	Action No action required	Cond/I B	nd Priority	L'Expec 13	Quantit 16	y m2	Cost (£) 1,312
								Year 1 Repair Cost (£

BUILDING : Block 06 Greenhou	ISE UPRN :	F	LOOR : Roof			
ROOM : Roof	No : 00	2/6/R/001	USE :			
Element : Covering	CODE : 1					Replacement
Description PVC-u glazed roof sections	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 20	Quantity 132	Cost (£) 20,000
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Structure	CODE : 1					Denlessment
Description Metal frame	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 40	Quantity 1 m2	Replacement Cost (£) 170
						Year 1 Repair Cost (£
Element : Flashings	CODE : 1					Replacement
Description Lead (inc. in roof)	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 50	Quantity 12 m	Cost (£) 902
						Year 1

Repair Cost (£)



Replacement Description Condition Action Cond/Ind Priority . Cost (£) L'Expec Quantity PVC-u gutters and downpipes No action required 30 Fair В 15 m 1,230 Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A	UPRN :	FL	OOR : Roof			
ROOM : Roof001	No : 002/7/R/001		USE :			
Element : Covering Description Natural slate	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 30	Quantity 30 m2	Replacement Cost (£) 4,798
						Year 1 Repair Cost (/
Photo 1	Photo 2		Position			
Element : Structure Description Timber joists and rafters	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 35	Quantity 30 m2	Replacement Cost (£) 3,199
imber joists and raiters						Year 1 Repair Cost (£
Element : Flashings	CODE:1					Replacement
Element : Flashings Description Galvanised zinc ridging and hips	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 25	Quantity 18 m	Replacement Cost (£) 1,353

Element : Rainwater goods Description	CODE : 1 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Cast iron/downpipes	Fair	No action required	В	20	22	m	1,503
							Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A ROOM : Roof002	UPRN : No : 002/		FLOOR : Roof USE :			
Element : Covering	CODE : 1					Replacement
Description Mineral felt	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 13	Quantity 8 m2	Cost (£) 656
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Structure	CODE :1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber joists and rafters	Fair	No action required	В	48	8 m2	656
						Year 1

Element : Flashings	CODE:1						Replacement
Description Felt	Condition	Action No action required	Cond/Ind Priority B	L'Expec 13	Quantity		Cost (£)
	Fair				4	m2	328
							Year 1 Repair Cost (£)

Element : Rainwater goods	CODE : 1						Replacement
Description PVC-u gutter and downpipe	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantit 7	y m	Cost (£) 287
							Year 1 Repair Cost (£)
Element : Fascias	CODE : 1						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Timber softwood fascias	Fair	No action required	В	23	6	m	205
							Year 1 Repair Cost (£)
Element : Decoration	CODE :1						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Timber finishes	Fair	No action required	В	3	6	m2	49
							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :	FLOOR : R	oofs			
ROOM : Roof 001	No : 002/8/R/0	001 USE :				
Element : Covering	CODE:1					Replacement
Description Natural slate	Condition Fair with several slipped slates	Action Repair/Replace missing,slipped slates	Cond/Ind Priority B 3	L'Expec 41	Quantity 187 m2	Cost (£) 29,910
		Sidles				Year 1 Repair Cost (£ 598
Photo 1	Photo 2	Positie	on			
Element : Structure	CODE : 1					Replacement
Description Timber joists and rafters	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 45	Quantity 187 m2	Cost (£) 19,940
						Year 1 Repair Cost (£
Element : Flashings	CODE : 1					Replacement
Description Galvanised zinc ridging and hips	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 41	Quantity 55 m	Cost (£) 4,135
						Year 1 Repair Cost (£

Element : Flashings	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Lead (inc. in roof)	Fair	No action required	В	41	67 m	5,037
						Year 1 Repair Cost (£)
Element : Rainwater goods	CODE : 1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Cast iron/downpipes	Fair but with choked gutters and outlets	Clean out choked gutters	B 3	10	14 m	956
						Year 1 Repair Cost (£) 120
Element : Rainwater goods	CODE : 1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
UPVC Gutters and downpipes	Fair	No action required	В	10	18 m	738
						Year 1 Repair Cost (£)
Element : Fascias	CODE : 1					Deulessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Timber softwood fascias	Fair	No action required	В	10	17 m	581
						Year 1 Repair Cost (£)

Element : Chimney stacks/flues Description Stone/brick chimneys	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 15	Quantity 1 No.	Replacement Cost (£) 2,447 Year 1 Repair Cost (£)
Photo 1	####################################	Ρ	osition			
Element : TV aerials/dishes etc	CODE:1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Metal aerials/dishes	Fair	No action required	В	10	2 No.	328
						Year 1 Repair Cost (£)
Photo 1	Photo 2	Ρ	osition			

L

Element : Decoration	CODE : 1					Replacement
Description All timber and CI downpipes/gutters	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 3	Quantity 31 m2	Cost (£) 254 Year 1 Repair Cost (£)
Element : Roof Lights Description Metal glazed skylight	CODE : 1 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 10	Quantity 1	Replacement Cost (£) 500
						Year 1 Repair Cost (£)
Photo 1	Photo 2	F	Position			

BUILDING : Block 08 Lodge	UPRN :	FLOC	R : Roofs			
ROOM : Roof 002	No : 002/8/R	./002 US	SE :			
Element : Covering	CODE : 1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Mineral felt	Fair but signs of vegetation	Clean vegetation off roof	B 4	8	3 m2	246
						Year 1 Repair Cost (£ 40
Photo 1	Photo 2	I	Position			
Element : Structure	CODE :1					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber joists and rafters	Fair	No action required	В	45	3 m2	246
						Year 1 Repair Cost (£

Element : Flashings	CODE:1						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Lead (inc. in roof)	Fair	No action required	В	41	4	m	300
							Year 1 Repair Cost (£

WALLS

BUILDING : Block 01 Kyd	UPRN :	FLOC	R: Elevations			
ROOM : Elevation001	No : 002/	1/E/001 US	SE :			
Element : External walls	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Stone walls	Fair	No Action Required	В	50	95 m2	16,883
						Year 1 Repair Cost (£
Photo 1	Photo 2	I	Position			
Element : External walls	CODE : 2					Replacement
Description Faced stone mullions and lintols	Condition Fair	Action Monitor condition annually	Cond/Ind Priority B	L'Expec 20	Quantity 49 m2	Cost (£) 8,708
						Year 1 Repair Cost (f

Element : External walls	CODE :2	A			0		Replacement
Description Stone pointed finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 20	Quantity 95	/ m2	Cost (£) 2,597
							Year 1 Repair Cost (
Element : Windows	CODE:2						Replacement
9 No. Timber hardwood sash and	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 22	/ m2	Cost (£) 14,436
case single glazed							Year 1 Repair Cost (
Element : Windows	CODE :2						Replacement
	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 28	Quantity 16	/ m2	Cost (£) 7,874
case double glazed							Year 1 Repair Cost
Element : Decoration	CODE :2						Replacemen
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Re-decoration All timber and wall finishes	Fair	No Action Required	В	3	55	m2	751
							Year 1 Repair Cost

BUILDING : Block 01 Kyd	UPRN :	FL	OOR : Elevations			
ROOM : Elevation002	No : 002/1/8	E/002	USE :			
Element : External walls Description Stone walls	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 50	Quantity 73 m2	Replacement Cost (£) 12,973
						Year 1 Repair Cost
Photo 1	Photo 2		Position			
Element : External walls	CODE :2					Replacement
Description Faced stone mullions and lintols	Condition Fair	Action Monitor condition annua	Cond/Ind Priority ally B	L'Expec 20	Quantity 25 m2	Cost (£) 4,443
						Year 1 Repair Cost (
Element : External walls	CODE :2					Replacement
Description Stone pointed finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 20	Quantity 73 m2	Cost (£) 1,995
						Year 1 Repair Cost (

Element : Windows	CODE :2					Replacement
Description 5 No. Timber hardwood sash and	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 10 m2	Cost (£) 6,562
case single glazed						Year 1 Repair Cost (£)
Photo 1	Photo 2		Position			
Element : Windows	CODE : 2	A officer			Quantita	Replacement
Description 4 No.Timber softwood sash and	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 28	Quantity 8 m2	Cost (£) 3,937
case double glazed						Year 1 Repair Cost (£)
Element : Decoration	CODE :2					Replacement
Description Re-decoration	Condition Fair	Action	Cond/Ind Priority B	L'Expec 3	Quantity 78 m2	Cost (£)
All timber and wall finishes	Γall	No Action Required	D	3	10 1112	1,066
						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Elevation003	UPRN : No : 002/1		DOR : Elevations			
Element : External walls	CODE :2					Replacement
Description Stone walls	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 50	Quantity 60 m2	Cost (£) 10,663
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : External walls	CODE : 2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Faced stone mullions and lintols	Fair	Monitor condition annua	ly B	20	37 m2	6,575
						Year 1

Element : External walls	CODE :2 Condition	Action	Cond/Ind Priority	L'Expec		Replacement	
Description					Quan	tity	Cost (£)
Stone pointed finish	Fair	No Action Required	В	20	60	m2	1,640
							Year 1 Repair Cost (£)

Element : Windows	CODE:2					Replacement
Description 3 No. Aluminium double glazed	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 10 m2	Cost (£) 7,519
3 No. Aluminium double glazed	i an	No Action Required	Б	15	10 112	
						Year 1 Repair Cost (£)
Element : Windows	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
4 No.Timber softwood sash and case double glazed	Fair	No Action Required	В	28	8 m2	3,937
case double glazed						Year 1 Repair Cost (£)
Element : Doors	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Aluminium flush	Fair	No Action Required	В	18	1 No.	800
						Year 1 Repair Cost (£)
Element : Doors	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 No. Softwood timber flush door	Fair	No Action Required	В	18	2 No.	1,968
1 No. Softwood timber glazed door						Year 1 Repair Cost (£)

Element : Decoration	CODE : 2	Action			Over	4	Replacement	
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)	
Re-decoration All timber and wall finishes	Fair	No Action Required	В	3	35	m2	478	
							Year 1 Repair Cost (£)	

BUILDING : Block 01 Kyd	UPRN :	FLO	OR : Elevations			
ROOM : Elevation004	No : 002/1/	E/004 L	SE :			
Element : External walls Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Stone walls	Fair	No Action Required	В	48	20 m2	3,554
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : External walls	CODE:2					Replacement
Description Stone pointed finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 16	Quantity 20 m2	Cost (£) 546
						Year 1 Repair Cost (
Element : Windows	CODE :2					Replacement
Description Metal louvre	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 1 m2	Cost (£) 669
		-				Year 1

Repair Cost (£)

Element : Windows	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber softwood sash and case double glazed	Fair	No Action Required	В	28	1 m2	492
						Year 1 Repair Cost (
Element : Doors	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush door	Fair	No Action Required	В	10	1 No.	984
						Year 1 Repair Cost (
Element : Decoration	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	4 m2	55
						Year 1 Repair Cost

BUILDING : Block 01 Kyd ROOM : Elevation005	UPRN : No : 002/		FLOOR : Elevations USE :			
Element : External walls	CODE :2	112/000				
Description Stone walls	Condition Fair	Action No Action Required	Cond/Ind Priority B	48	Quantity 25 m2	Replacement Cost (£) 4,443
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : External walls	CODE :2					Replacement
Description Stone pointed finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 16	Quantity 25 m2	Cost (£) 683
						Year 1

Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Faced stone	Fair	No Action Required	В	30	16	m2	7,655
							Year 1 Repair Cost (£)

Element : External walls Description Stone cill,lintol and jambs	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 30	Quantity 14 m2	Replacement Cost (£) 2,488 Year 1 Repair Cost (£)
Element : Windows Description 3 No. Timber hardwood sash and case single glazed	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 6 m2	Replacement Cost (£) 3,937 Year 1 Repair Cost (£)
Element : Windows Description 1 No. Timber softwood fixed pane single glazed	CODE :2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 7	Quantity 2 m2	Replacement Cost (£) 492 Year 1 Repair Cost (£)
Element : Doors Description UPVC door	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 1 No.	Replacement Cost (£) 800 Year 1 Repair Cost (£)

Element : Decoration	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration All timber finishes	Poor	Redecorate	C 4	Replace/In	8 m2	109
						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UP	RN :	FLOOR : E	levations				
ROOM : Elevation006		No : 002/1/E/006	USE :					
Element : External walls Description	CODE : 2 Condition	Action		Cond/Ind Priority	L'Expec	Quanti	łv	Replacement Cost (£)
Stone walls	Fair	No Action Requir	ed	B	50	25	m2	4,443
								Year 1 Repair Cost (£
Photo 1	Pho	to 2	Positi	on				

Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Faced stone mullions and lintols	Fair	Monitor condition annually	В	20	16	m2	2,843
							Year 1 Repair Cost (£)
Element : External walls	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Stone pointed finish	Fair	No Action Required	В	20	25	m2	683
							Year 1

Element : Windows	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	у	Cost (£)
2 No. Timber hardwood sash and case single glazed	Fair	No Action Required	В	15	4	m2	2,624
							Year 1 Repair Cost (£)
Element : Windows	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	у	Cost (£)
1 No. Timber softwood sash and case double glazed	Fair	No Action Required	В	28	2	m2	984
							Year 1 Repair Cost (£)
Element : Decoration	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	у	Cost (£)
Re-decoration All timber and wall finishes	Fair	No Action Required	В	3	21	m2	287
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Elevations			
ROOM : Elevation007	No : 002/1/	E/007	USE :			
Element : External walls Description Stone walls	CODE :2 Condition Fair	Action	Cond/Ind Priorit	 L'Expec 50 	Quantity 24 m2	Replacement Cost (£)
Stone waiis	Fair	No Action Required	Б	50	24 m2	4,265 Year 1 Repair Cost (/
Photo 1	Photo 2		Position			
Element : External walls	CODE :2					Donlocomont
Description Faced stone window surrounds	Condition Fair	Action No Action Required	Cond/Ind Priority B	20 L'Expec	Quantity 20 m2	Replacement Cost (£) 3,554 Year 1
						Repair Cost (£
Element : External walls	CODE :2					Replacement
Description Stone featured panel	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 50	Quantity 1 m2	Cost (£) 1,500
						Year 1 Repair Cost (I

Element : Windows	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
4 No. Timber sash and case double glazed	Fair	No Action Required	В	28	8	m2	3,937
doublo glazou							Year 1 Repair Cost (£)
Element : Decoration	CODE :2						Replacement
Element : Decoration Description	CODE :2 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Description Re-decoration		Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quant 8	ity m2	-
Description	Condition		•	•		•	Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	LOOR : Elevations			
ROOM : Elevation008	No : 002/1/	E/008	USE :			
Element : External walls Description Stone walls	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 50	Quantity 22 m2	Replacement Cost (£) 3,909
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : External walls	CODE : 2					Replacement
Description	Condition	Action	Cond/Ind Priority	-	Quantity	Cost (£)
Cement render	Fair	No Action Required	В	10	2 m2	109
						Year 1 Repair Cost (£
Element : Windows	CODE : 2					Replacement
Description	Condition	Action	Cond/Ind Priority	-	Quantity	Cost (£)
5 No. Timber softwood casement	Fair	No Action Required	В	15	8 m2	3,281

B 5 No. Timber softwood casement Fair single glazed frames No Action Required 15

Year 1 Repair Cost (£)

Condition	Action	Cond/Ind Priority	L'Expec		•	Replacement Cost (£) 1,968
1 an	No Action Required		15	Z	NO.	Year 1 Repair Cost (£)
CODE : 2	Action	Cond/Ind Priority	l 'Expec	Quanti	tv	Replacement Cost (£)
Fair	No Action Required	B	3	12	m2	164 Year 1
	Fair CODE : 2 Condition	Fair No Action Required CODE : 2 Condition Action	Fair No Action Required B CODE : 2 Action Cond/Ind Priority	Fair No Action Required B 15 CODE :2 Action Cond/Ind Priority L'Expec	Fair No Action Required B 15 2 CODE :2 Action Cond/Ind Priority L'Expec Quantity	Fair No Action Required B 15 2 No. CODE :2 Action Cond/Ind Priority L'Expec Quantity

BUILDING : Block 01 Kyd	UPRN :	FLC	OR : Elevations			
ROOM : Elevation009	No : 002/1/E/0	09 1	USE :			
Element : External walls	CODE:2					Replacement
Description Stone walls	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 50	Quantity 9 m2	Cost (£) 1,599
						Year 1 Repair Cost (I
Photo 1	Photo 2		Position			
Element : External walls	CODE :2					Replacement
Description Faced stone mullions and lintols	Condition Fair but with spalling to face in	Action Monitor condition annual	Cond/Ind Priority	L'Expec 20	Quantity 22 m2	Cost (£) 3,909
	isolated areas					Year 1 Repair Cost (£
Element : Windows	CODE :2					Paulasanat
Description 5 No. Timber softwood sash and	Condition Fair but requires redecoration	Action Refer to decoration	Cond/Ind Priority B	L'Expec 15	Quantity 10 m2	Replacement Cost (£) 4,101
case single glazed						Year 1 Repair Cost (£

Element : Decoration	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Re-decoration All timber finishes	Poor	Redecorate	C 4	Replace/In	10	m2	136
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	FL	OOR : Elevations			
ROOM : Elevation010	No : 002/1/	/E/010	USE :			
Element : External walls Description Stone walls	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 48	Quantity 2 m2	Replacement Cost (£) 355
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : External walls	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Render	Fair	No Action Required	В	16	1 m2	54
						Year 1 Repair Cost (
Element : Doors	CODE :2					Replacement
Description Softwood timber flush door	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No.	Cost (£) 984

Year 1 Repair Cost (£)

Element : External joinery	CODE:2						Replacement
Description Timber shiplap boarding	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quanti 2	ty m2	Cost (£) 109
							Year 1 Repair Cost (£)
Element : External joinery	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Timber board	Fair	No Action Required	В	23	2	m2	109
							Year 1 Repair Cost (£)
Element : Decoration	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	6	m2	82
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	LOOR : Elevations			
ROOM : Elevation011 (High	n level) No : 00	2/1/E/011	USE :			
Element : External walls Description Stone walls	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 48	Quantity 12 m2	Replacement Cost (£) 2,132
						Year 1 Repair Cost
Photo 1	Photo 2		Position			
Element : External walls Description Render	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 16	Quantity 2 m2	Replacemen Cost (£) 109
						Year 1 Repair Cost
Element : Windows	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
The base of the second second second second						

No Action Required

В

28

2

m2

Timber softwood sash and case double glazed

Fair

Year 1 Repair Cost (£)

984

BUILDING : Block 01 Kyd	UPRN :		FLOOR : R	oof				
ROOM : Roof001	No : 002/1/R/0	01	USE :					
Element : Windows Description 2 No.Timber softwood casement	CODE :2 Condition Fair but at end of economic life	Action No Action Required		Cond/Ind Priority B	L'Expec 5	Quant 4	ity m2	Replacement Cost (£) 1,640
single glazed								Year 1 Repair Cost (£)



BUILDING : Block 01 Kyd ROOM : Roof002	UPRN : No : 002	2/1/R/002	FLOOR : R USE :	Roof				
Element : Decoration Description Re-decoration	CODE : 2 Condition Fair	Action No Action Requi	red	Cond/Ind Priority B	L'Expec 3	Quan 4	tity m2	Replacement Cost (£) 54
Cast iron downpipe								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Roof004	UPRN : No : 0	02/1/R/004	FLOOR : R USE :	Roof				
Element : Decoration Description Re-decoration	CODE : 2 Condition Fair	Action No Action Re	equired	Cond/Ind Priority B	L'Expec 3	Quan 4	tity m2	Replacement Cost (£) 54
Cast iron downpipe with box at the top								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Roof007	UPRN : No : 002	2/1/R/007	FLOOR : R USE :	Roof				
Element : Decoration Description Re-decoration	CODE : 2 Condition Fair	Action No Action Require	ed	Cond/Ind Priority B	L'Expec 3	Quant 4	t ity m2	Replacement Cost (£) 54
Cast iron downpipe with box at the top								Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Elevations			
ROOM : Elevation001	No : 002/2/	/E/001	USE :			
Element : External walls Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Facing brick	Fair	No Action Required	В	48	28 m2	2,870
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : External walls	CODE : 2					Replacement
Description Wet Dash	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 35 m2	Cost (£) 1,913
						Year 1 Repair Cost (£
Element : External walls	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	-	Quantity	Cost (£)
Pointing	Fair	No Action Required	В	28	28 m2	765
						Year 1 Repair Cost (£

Element : Windows	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
7 No. PVC-u tilt and turn double glazed	Fair	No Action Required	В	28	7	m2	5,263
<u></u>							Year 1 Repair Cost (
Element : External joinery	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
uPVC fascia and soffit	Fair	No Action Required	В	23	7	m2	382
							Year 1 Repair Cost (
Element : Cills	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
Concrete cills	Fair	No Action Required	В	38	7	m	3,500
							Year 1 Repair Cost (

BUILDING : Block 02 McKinney		RN :	FLOOR : E	levations				
ROOM : Elevation002		No:002/2/E/002	USE :	USE :				
Element : External walls Description Wet Dash	CODE : 2 Condition Fair	Action No Action Requi	red	Cond/Ind Priority B	L'Expec 33	Quantit 29	y m2	Replacement Cost (£) 1,585
								Year 1 Repair Cost (£
Photo 1	Phot	to 2	Positi	on				

Element : Windows	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
PVC-u casement double glazed	Fair	No Action Required	В	28	2	m2	1,503
transome							Year 1 Repair Cost (£)
Element : Windows	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
6 No. PVC-u tilt and turn double glazed	Fair	No Action Required	В	28	13	m2	9,774

Element : Doors	CODE:2						Replacement
Description UPVC glazed doors	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quanti 2	i ty No.	Cost (£) 3,253
							Year 1 Repair Cost (£)
Element : External joinery	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
uPVC fascia and soffit	Fair	No Action Required	В	23	7	m2	382
							Year 1 Repair Cost (£)
Element : Cills	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Concrete cills	Fair	No Action Required	В	38	7	m	3,500
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	y UPRN :	i	FLOOR : Elevations				
ROOM : Elevation003	No : 002	/2/E/003	USE :				
Element : External walls	CODE:2						Replacement
Description Facing brick	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 48	Quantity 3	/ m2	Cost (£) 307
							Year 1 Repair Cost (£
Photo 1	Photo 2		Position				
Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	-	Quantity		Cost (£)
Pointing	Fair	No Action Required	В	28	3	m2	82

Year 1 Repair Cost (£)

Element : Windows	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
2 No. PVC-u casement double glazed	Fair	No Action Required	В	28	2	m2	1,503
giazou							Year 1 Repair Cost (£)

Element : External joinery	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber shiplap boarding	Fair	No Action Required	В	23	3 m2	164
						Year 1 Repair Cost (£)
Element : Decoration	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	3 m2	41
						Year 1 Repair Cost (£)
Element : Cills	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Concrete cills	Fair	No Action Required	В	38	2 m	1,000
						Year 1 Repair Cost (£)

-	No : 002/2/ CODE : 2 Condition Fair	Action	USE : Cond/Ind Priority			Replacement
Description C	Condition		Cond/Ind Priority			Renlacement
		No Action Required	В	L'Expec 48	Quantity 14 m	Cost (£)
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			

Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Pointing	Fair	No Action Required	В	28	14	m2	382
							Year 1 Repair Cost (£)
Element : External walls	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Wet Dash	Fair	No Action Required	В	33	28	m2	1,531
							Year 1 Repair Cost (£)

Element : Windows	CODE:2						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	y	Cost (£)
6 No. PVC-u tilt and turn double glazed	Fair	No Action Required	В	28	12	m2	9,022
giazeu							Year 1 Repair Cos
Element : Windows	CODE : 2						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	y	Cost (£)
9 No. PVC-u casement double	Fair	No Action Required	В	28	18	m2	13,534
glazed							Year 1 Repair Cos
Element : External joinery	CODE : 2						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	•	Cost (£)
Timber shiplap boarding	Fair	No Action Required	В	23	11	m2	601
							Year 1 Repair Cos
Element : Decoration	CODE:2						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	y	Cost (£)
Re-decoration	Fair	No Action Required	В	3	11	m2	150
All timber finishes							Year 1 Repair Cos

Element : Cills Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Concrete cills	Fair	No Action Required	В	38	17	m	8,500
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Elevations			
ROOM : Elevation005	No : 002/2/	/E/005	USE :			
Element : External walls	CODE :2					Replacement
Description Facing brick	Condition Fair	Action No Action Required	Cond/Ind Priority B	48 L'Expec	Quantity 3 m2	Cost (£) 307
						Year 1 Repair Cost (£
Element : External walls	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pointing	Fair	No Action Required	В	28	3 m2	82
						Year 1 Repair Cost (£
Element : Windows	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
2 No. PVC-u casement double	Fair	No Action Required	В	28	2 m2	1,503
glazed						Year 1 Repair Cost (£
Element : External joinery	CODE :2					Denlessment
Description Timber shiplap boarding	Condition Fair	Action No Action Required	Cond/Ind Priority B	23	Quantity 2 m2	Replacement Cost (£) 109
· · · · · · · · · · · · · · · · · · ·						Year 1 Repair Cost (£

Element : Decoration	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	2	m2	27
							Year 1 Repair Cost (£)
Element : Cills	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Concrete cills	Fair	No Action Required	В	38	3	m	1,500
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinn	ey UPRN :	F	FLOOR : Elevations			
ROOM : Elevation006	No : 00	2/2/E/006	USE :			
Element : External walls Description Facing brick	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 48	Quantity 8 m2	Replacement Cost (£) 820
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : External walls	CODE :2					

Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Pointing	Fair	No Action Required	В	28	8	m2	218
							Year 1 Repair Cost (£)
Element : External walls	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Glass bricks	Fair	No Action Required	В	48	4	m2	410
							Year 1 Repair Cost (£)

Element : Windows	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
1 No. PVC-u casement double glazed	Fair	No Action Required	В	28	2	m2	1,503
giazeu							Year 1
							Repair Cost
Element : Doors	CODE : 2						Replacemer
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	Y	Cost (£)
Timber glazed fire exit door	Fair	No Action Required	В	18	1	No.	984
							Year 1 Repair Cost
Element : Decoration	CODE : 2						Replacemer
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	ÿ	Cost (£)
Re-decoration	Fair	No Action Required	В	3	2	m2	27
All timber finishes							Year 1 Repair Cost
Element : Cills	CODE :2						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	ÿ	Cost (£)
Concrete cill and lintol	Fair	No Action Required	В	38	4	m	2,000
							Year 1
							i cui i

BUILDING : Block 02 McKinney			FLOOR : Elevatio	ons				
ROOM : Elevation007	No : 002	/2/E/007	USE :					
Element : External walls	CODE:2							Replacement
Description	Condition	Action	Con	d/Ind Priority	L'Expec	Quantit	ÿ	Cost (£)
Dry dash	Fair	No Action Required		В	33	3	m2	164
								Year 1 Repair Cost (£
Photo 1	Photo 2		Position					
Element : External walls	CODE:2							Replacement

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Render to soffit	Fair	No Action Required	В	33	12	m2	656
							Year 1 Repair Cost (£)
Element : Windows	CODE :2	A officer					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
1No. PVC-u tilt and turn double glazed	Fair	No Action Required	В	28	2	m2	1,503
giazeu							Year 1 Repair Cost (£)

Element : Cills	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quar	ntity	Cost (£)
Concrete cill	Fair	No Action Required	В	38	1	m	500
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Elevation008	UPRN : No : 002/2/		LOOR : Elevations USE :			
Element : External walls Description	CODE : 2 Condition	Action	Cond/Ind Priority	-	Quantity	Replacement Cost (£)
Dry dash	Fair	No Action Required	В	33	5 m2	273 Year 1 Repair Cost (f
Photo 1	Photo 2		Position			
Element : Windows Description	CODE : 2 Condition	Action	Cond/Ind Priority		Quantity	Replacement Cost (£)
1No. PVC-u tilt and turn double glazed	Fair	No Action Required	В	28	3 m2	2,255 Year 1 Repair Cost (£

Element : Cills	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Concrete cill	Fair	No Action Required	В	38	2	m	1,000
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	FI	OOR : Elevations			
ROOM : Elevation009	No : 002/2/	E/009	USE :			
Element : External walls Description Dry dash	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Replacement Cost (£) 656
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : External walls	CODE :2					
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Facing brick	Fair	No Action Required	В	48	1 m2	102
						Year 1 Repair Cost (£
Element : External walls	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)

Year 1 Repair Cost (£)

Element : External joinery Description	CODE :2 Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Replacement Cost (£)
Timber fascia	Fair	No Action Required	В	23	2	m2	109
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quanti	4 17	Replacement
Re-decoration	Fair	No Action Required	B	с схрес 3	Quanti 2	יש m2	Cost (£) 27
All timber finishes			_	-	_		– Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Elevation010	UPRN : No : 002/2		FLOOR : Elevations USE :			
Element : External walls	CODE :2					
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Dry dash	Fair	No Action Required	В	33	18 m2	984
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : External walls Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Facing brick	Fair	No Action Required	В	48	2 m2	205
						Year 1 Repair Cost (
Element : External walls	CODE : 2					Repair Cos

Description	Condition	Action	Cond/Ind Priority	L'Expec	Qua	ntity	Replacement Cost (£)	
Pointing	Fair	No Action Required	В	28	2	m2	54	
							Year 1	

Repair Cost (£)

Element : Windows	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
1 No. PVC-u casement double glazed	Fair	No Action Required	В	28	5	m2	3,759
giazeu							Year 1 Repair Cost (
Element : Doors	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
UPVC glazed fire exit door	Fair	No Action Required	В	18	1	No.	1,626
							Year 1 Repair Cost
Element : External joinery	CODE :2						Replacemen
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Timber fascia	Fair	No Action Required	В	23	3	m2	164
							Year 1 Repair Cost
Element : Decoration	CODE :2						Replacemer
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Re-decoration	Fair	No Action Required	В	3	-	m2	41
All timber finishes							Year 1 Repair Cost

Element : Cills Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Concrete cills	Fair	No Action Required	В	38	3	m	1,500
							Year 1 Repair Cost (£)

BUILDING : Block 02 Mcl ROOM : Elevation011	-	UPRN : No : 002/2/E/01	1	FLOOR : E USE :	levations				
Element : External walls Description Wet Dash	CODE Condition Fair		Action No Action Required		Cond/Ind Priority B	L'Expec 16	Quant 8	ity m2	Replacement Cost (£) 437
									Year 1 Repair Cost (£)
Photo 1		Photo 2		Positi	on				

BUILDING : Block 03 Dalhousi	e UPRN :	F	LOOR : Elevations			
ROOM : Elevation001	No : 002/3	3/E/001	USE :			
Element : External walls Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Wet Dash	Fair	No Action Required	В	11	55 m2	3,007
						Year 1 Repair Cost (I
Photo 1	Photo 2		Position			
Element : External walls Description Facing brick	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 26	Quantity 3 m2	Replacement Cost (£) 307
		No Action Required		20	5 112	Year 1 Repair Cost (
Element : External walls	CODE :2					Replacement

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quai	ntity	Cost (£)	
Cement render	Fair	No Action Required	В	11	3	m2	164	
							Year 1	

Repair Cost (£)

							Replacement
Description	Condition	Action	Cond/Ind Priority	-	Quantit	-	Cost (£)
7 No. PVC-u tilt and turn double glazed	Fair	No Action Required	В	23	14	m2	10,526
giazeu							Year 1 Repair Cost (
Photo 1	Photo 2	Ρ	Position				
	II						
Element - External joinery	CODE · 2						
Element : External joinery	CODE :2	Action	Cond/Ind Driceity		Quantit		
Element : External joinery Description		Action No Action Required	Cond/Ind Priority B	L'Expec 9	Quantit	ty m2	Replacement Cost (£) 765
Element : External joinery Description	CODE : 2 Condition	Action No Action Required		-		•	Cost (£) 765 Year 1
Element : External joinery Description Timber fascia and soffit boards	CODE : 2 Condition			-		•	Cost (£) 765 Year 1 Repair Cost (
Element : External joinery Description Timber fascia and soffit boards Element : External joinery Description	CODE : 2 Condition Fair			-		m2	Cost (£) 765 Year 1 Repair Cost (
Element : External joinery Description Timber fascia and soffit boards Element : External joinery	CODE : 2 Condition Fair CODE : 2	No Action Required	B	9	14	m2	Cost (£) 765 Year 1 Repair Cost (Replacement

CODE:2						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Fair	No Action Required	В	3	9	m2	123
						Year 1 Repair Cost (£)
CODE :2						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Fair	No Action Required	В	16	4	m	2,000
						Year 1 Repair Cost (£)
_	Condition Fair CODE : 2 Condition	Condition Action Fair No Action Required CODE :2 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :2ActionCond/Ind PriorityConditionActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 3CODE :2ActionCond/Ind PriorityL'ExpecConditionActionCond/Ind PriorityL'Expec	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 3Quantit 9CODE :2ActionActionCond/Ind PriorityL'ExpecQuantitConditionActionCond/Ind PriorityL'ExpecQuantit	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 3Quantity 9CODE :2ActionActionCond/Ind PriorityL'ExpecQuantityConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 03 Dalhousie	UPRN :	FL	OOR : Elevations			
ROOM : Elevation002	No : 002/3	3/E/002	USE :			
Element : External walls	CODE:2					Replacement
Description Facing brick	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 26	Quantity 2 m2	Cost (£) 205
						Year 1 Repair Cost (£
Element : External walls	CODE :2					Replacement
Description Wet Dash	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 11	Quantity 41 m2	Cost (£) 2,242
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Windows	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expos	Quantity	Replacement
Description 2 No. PVC-u tilt and turn double	Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 4 m2	Cost (£) 3,007
glazed						Year 1 Repair Cost (£

Repair Cost (£)

Photo 1	Photo	o 2	Position				
Element : External joinery	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Upvc fascia and soffit boards	Fair	No Action Required	В	9	12	m2	656
							Year 1 Repair Cost (£)

Element : External joinery	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Board infill panels	Fair	No Action Required	В	5	3	m2	164
							Year 1 Repair Cost (£
Element : Decoration	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Paint infill panels and lintols	Fair	No Action Required	В	3	3	m2	41
							Year 1


Element : Cills Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quar	tity	Replacement Cost (£)
Concrete cill	Fair	No Action Required	В	16	1	m	500
							Year 1 Repair Cost (£)

	ie UPRN :	FLC	OR : Elevations			
ROOM : Elevation003	No : 002/	3/E/003 l	USE :			
Element : External walls Description Wet Dash	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 11	Quantity 65 m2	Replacement Cost (£) 3,554
						Year 1 Repair Cost (/
Photo 1	Photo 2		Position			
Element : External walls	CODE:2					Doplacement
	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Description		Action No Action Required	Cond/Ind Priority B	L'Expec 26	Quantity 4 m2	Replacement Cost (£) 410
Element : External walls Description Facing brick	Condition				•	Cost (£)
Description	Condition				•	Cost (£) 410 Year 1

Element : Windows	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
7 No. PVC-u tilt and turn double glazed 1 No. PVC-u frame double glazing	Fair 9	No Action Required	В	23	16 m2	12,030 Year 1 Repair Cost (£)
Photo 1	Photo	2	Position			
Element : Doors	CODE :2					Replacement
Description UPVC Fire exit door	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 13	Quantity 1 No.	Cost (£) 1,626
	i dii				i ino.	.,•=•
					1 10.	Year 1 Repair Cost (£)

Element : External joinery	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber fascia and soffit boards	Fair	No Action Required	В	9	14 m2	765
						Year 1 Repair Cost (I
Element : External joinery	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Board infill panels	Fair	No Action Required	В	5	14 m2	765
						Year 1 Repair Cost (
Element : Decoration	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration Paint infill panels and lintols	Fair	No Action Required	В	3	28 m2	382
						Year 1 Repair Cost (
Element : Cills	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Concrete cills	Fair	No Action Required	В	16	3 m	1,500
						Year 1 Repair Cost (

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Elevations			
ROOM : Elevation001	No : 002/4/E	E/001	USE :			
Element : External walls Description Facing brick	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 31	Quantity 13 m2	Replacement Cost (£) 1,332
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : External walls	CODE : 2					
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Dry dash	Fair	No Action Required	В	16	15 m2	820
						Year 1 Repair Cost (/
Element : Windows	CODE:2					Replacement
Description 2 No. PVC-u tilt and turn double	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 11	Quantity 3 m2	Cost (£) 2,255
glazed						Voor 1



Element : External joinery	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Timber fascia and soffit boards	Fair	No Action Required	В	6	9	m2	492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	11	m2	150
							Year 1
							Repair Cost (£)
Element : Cills	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Concrete cills	Fair	No Action Required	В	21	3	m	1,500
							Year 1
							Repair Cost (£)

		FLOOR : Elevations				
No : 002	/4/E/002	USE :				
CODE :2 Condition	Action		-	-		Replacement Cost (£)
Fair	No Action Required	В	31	3	m2	307
						Year 1 Repair Cost (£
Photo 2		Position				
••						
	CODE : 2 Condition Fair	ConditionActionFairNo Action Required	CODE : 2 Condition Action Cond/Ind Priority Fair No Action Required B	CODE : 2ConditionActionCond/Ind PriorityL'ExpecFairNo Action RequiredB31	CODE : 2 Action Cond/Ind Priority L'Expec Quantity Fair No Action Required B 31 3	CODE : 2ConditionActionCond/Ind PriorityL'ExpecQuantityFairNo Action RequiredB313m2

Element : External walls	CODE:2						Replacement	
Description	Condition	Action Cond/Ind Priority L'E		Action Cond/Ind Priority L'Expec Quantity		Quantity		Cost (£)
Dry dash	Fair	No Action Required	В	16	43	m2	2,351	
							Year 1	



Photo 2

Element : Windows	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
4 No. PVC-u tilt and turn double glazed	Fair	No Action Required	В	11	4 m2	3,007
giazod						Year 1 Repair Cost (£
Photo 1	Photo 2	F	Position			
Flomont - External joinary	CODE :2					
Element : External joinery Description	CODE : 2	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Timber fascia and soffit boards	Fair	No Action Required	В	6	10 m2	546
						Voor 1

Year 1 Repair Cost (£)

Element : Decoration	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	10	m2	136
							Year 1 Repair Cost (£)
Element : Cills	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Concrete cills	Fair	No Action Required	В	21	4	m	2,000
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Elevations			
ROOM : Elevation003	No : 002/4	4/E/003	USE :			
Element : External walls Description Facing brick	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 31	Quantity 3 m2	Replacement Cost (£) 307
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : External walls	CODE : 2					Renlacement

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)	
Dry dash	Fair	No Action Required	В	16	65	m2	3,554	
							Voor 1	



Element : Windows	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
4 No. PVC-u tilt and turn double	Fair	No Action Required	В	11	4 m2	3,007
glazed						Year 1 Repair Cost (£)
Photo 1	Photo 2	P	osition			
Element : External joinery	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber fascia and soffit boards	Fair	No Action Required	В	6	14 m2	765
						Year 1 Repair Cost (£)

Element : Decoration	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	14	m2	191
							Year 1 Repair Cost (£)
Element : Cills	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Concrete cills	Fair	No Action Required	В	21	4	m	2,000
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Elevations			
ROOM : Elevation004	No : 002/4	J/E/004	USE :			
Element : External walls Description Facing brick	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Prior B	ty L'Expec 31	Quantity 33 m2	Replacement Cost (£) 3,383
						Year 1 Repair Cost (£)
Photo 1	Photo 2		Position			
Element : External walls	CODE:2					Replacement


Description	Condition	Action	Cond/Ind Priority	L'Expec	Quar	ntity	Replacement Cost (£)	
Dry dash	Fair	No Action Required	В	16	72	m2	3,937	
							Veerd	



Photo 2

Position

Element : Windows	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
12 No. PVC-u tilt and turn double	Fair	No Action Required	В	11	13	m2	9,774
glazed							Year 1
							Repair Cost (£)



Element : DoorsCODE : 2ReplacementDescriptionConditionActionCond/Ind PriorityL'ExpecQuantityCost (£)Timber louvred doorFairNo Action RequiredB101m2328

Element : Doors	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
UPVC fire exit door	Fair	No Action Required	В	10	1 No.	1,626
						Year 1 Repair Cost (
Element : External joinery	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber fascia and soffit boards	Fair	No Action Required	В	6	27 m2	1,476
						Year 1 Repair Cost (
Element : Decoration	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	29 m2	396
						Year 1 Repair Cost (
Element : Cills	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Concrete cills	Fair	No Action Required	В	21	12 m	6,000
						Year 1 Repair Cost (

DescriptionConditionActionCond/Ind PriorityL'ExpecQuantityCostFacing brickFairNo Action RequiredB313m2307Year	BUILDING : Block 04 Keays	UPRN :	F	LOOR : Elevations					
DescriptionConditionActionCond/IndPriorityL'ExpecQuantityCostFacing brickFairNo Action RequiredB313m2307Year Repar	ROOM : Elevation005	No : 002/4/	/E/005	USE :					
DescriptionConditionActionCond/IndPriorityL'ExpecQuantityCostFacing brickFairNo Action RequiredB313m2307Year Repar	Element : External walls	CODE:2							Replacement
Year Repa	Description C	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	/	Cost (£)
Repa	Facing brick F	Fair	No Action Required	В		31	3	m2	307
Photo 1 Position									Year 1 Repair Cost (
	Photo 1	Photo 2		Position					

		A (1)			•		Replacement	
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)	
Dry dash	Fair	No Action Required	В	16	65	m2	3,554	
							Year 1	

Photo 2

Element : Windows	CODE:2					Replacement
Description 4 No. PVC-u tilt and turn double	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 11	Quantity 4 m2	Cost (£) 3,007
glazed						Year 1 Repair Cost (#
Photo 1	Photo 2	F	Position			
Element : External joinery Description	CODE :2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Timber fascia and soffit boards	Fair	No Action Required	В	6	14 m2	765
						Year 1 Repair Cost (

Element : Decoration	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	14	m2	191
							Year 1 Repair Cost (£)
Element : Cills	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Concrete cills	Fair	No Action Required	В	21	4	m	2,000
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Elevations			
ROOM : Elevation006	No : 0	02/4/E/006	USE :			
Element : External walls	CODE:2					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Facing brick	Fair	No Action Required	-	31	-	n2 307
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			

Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Dry dash	Fair	No Action Required	В	16	40	m2	2,187
							Year 1 Repair Cost (f)

Photo 2



Element : Windows	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
3 No. PVC-u tilt and turn double glazed	Fair	No Action Required	В	11	3 m2	2,255
gidzod						Year 1 Repair Cost (£
Photo 1	Photo 2	Ρ	osition			
Element : External joinery	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber fascia and soffit boards	Fair	No Action Required	В	6	12 m2	656
						Year 1

Element : Decoration	CODE :2	A = (1 =			0		Replacement
Description Re-decoration	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	m2	Cost (£) 164
All timber finishes				U	12		Year 1 Repair Cost (£)
Element : Cills Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quanti	itv	Replacement Cost (£)
Concrete cills	Fair	No Action Required	B	21	3	m	1,500
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays		UPRN :	F	LOOR : E	evations				
ROOM : Elevation007		No : 002/4/E/007		USE :					
Element : External walls	CODE	:2							Donlocoment
Description	Condition	А	ction		Cond/Ind Priority	L'Expec	Quanti	ty	Replacement Cost (£)
Facing brick	Fair	Ν	lo Action Required		В	31	2	m2	205
									Year 1 Repair Cost (£
Photo 1		Photo 2		Positi	on				

Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Dry dash	Fair	No Action Required	В	16	22	m2	1,203
							Year 1

Repair Cost (£)



Photo 2

Element : Windows CODE:2 Replacement Condition Description Action Cond/Ind Priority L'Expec Cost (£) Quantity 4 No. PVC-u tilt and turn double Fair No Action Required В 11 6 m2 4,511 glazed Year 1 Repair Cost (£) Photo 1 Photo 2 Position -Element : External joinery CODE:2 Replacement Condition Cond/Ind Priority L'Expec Description Action Quantity Cost (£)

Position

Timber fascia and soffit boards

Fair

No Action Required

В 6 14 m2 765

Element : Decoration	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	14	m2	191
							Year 1 Repair Cost (£)
Element : Cills	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Concrete cills	Fair	No Action Required	В	21	8	m	4,000
							Year 1 Repair Cost (£)

BUILDING : Block 05 Dining ROOM : Elevation001	UPRN : No : 002/		FLOOR : Elevations USE :			
Element : External walls Description Wet Dash	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 10	Quantity 22 m2	Replacement Cost (£) 1,203
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Windows Description PVC-u casement double glazed	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 6 m2	Replacement Cost (£) 4,511
						Year 1 Repair Cost (£

Element : Doors	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
UPVC fire exit doors	Fair	No Action Required	В	13	2	No.	3,253
							Year 1 Repair Cost (£

						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Fair	No Action Required	В	10	1	No	68
						Year 1 Repair Cost (£)
CODE:2						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Fair	No Action Required	В	3	22	m2	300
						Year 1
						Repair Cost (£)
CODE :2						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Fair	No Action Required	В	20	5	m	2,500
						Year 1
						Repair Cost (£)
	Fair CODE : 2 Condition Fair CODE : 2 Condition	Fair No Action Required CODE : 2 Condition Action Fair No Action Required CODE : 2 CODE : 2 Condition Action	Fair No Action Required B CODE : 2 Action Cond/Ind Priority Fair No Action Required B CODE : 2 CODE : 2 Condition CODE : 2 Action Cond/Ind Priority	Fair No Action Required B 10 CODE :2 Action Cond/Ind Priority L'Expec Condition Action Required B 3 Fair No Action Required B 3 CODE :2 Action Cond/Ind Priority L'Expec CODE :2 Action Cond/Ind Priority L'Expec	Fair No Action Required B 10 1 CODE : 2 Action Cond/Ind Priority L'Expec Quanti Fair No Action Required B 3 22 CODE : 2 Condition Action Cond/Ind Priority L'Expec Quanti CODE : 2 Action Cond/Ind Priority L'Expec Quanti	Fair No Action Required B 10 1 No CODE :2 Action Cond/Ind Priority L'Expec Quantity Fair No Action Required B 3 22 m2 CODE :2 Cond/Ind Priority L'Expec Quantity CODE :2 Action Cond/Ind Priority L'Expec Quantity

BUILDING : Block 05 Dining		UPRN :		FLOOR : E	levations				
ROOM : Elevation002		No : 002/5/E/00	02	USE :					
Element : External walls	CODE	:2							Denlessment
Description	Condition		Action		Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Wet Dash	Fair		No Action Required	ł	В	10	13	m2	710
									Year 1 Repair Cost (£
Photo 1	E.	Photo 2		Positi	on				

Element : Windows	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quar	ntity	Cost (£)
Steel casements frames single glazed	Fair	No Action Required	В	10	5	m2	2,050
							Year 1 Repair Cost (£)

Photo 2

Element : Decoration CODE:2 Replacement Condition Description Action Cond/Ind Priority L'Expec Cost (£) Quantity Re-decoration Fair No Action Required В 3 13 m2 177 All wall finishes Year 1 Repair Cost (£) Element : Cills CODE:2 Replacement Condition Description Action Cond/Ind Priority L'Expec Quantity Cost (£) 20 1 No. Concrete cills Fair No Action Required В 5 2,500 m Year 1 Repair Cost (£)

BUILDING : Block 06 Greenhous	e UPRN :	:	FLOOR : E	levations				
ROOM : Elevation	No :	: 002/6/E/001	USE :					
Element : External walls Description Render finish	CODE : 2 Condition Fair	Action No Action Red	quired	Cond/Ind Priority B	L'Expec 25	Quantit 6	y m2	Replacement Cost (£) 328
								Year 1 Repair Cost (£)
Element : Windows	CODE:2							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
PVC-u casement double-glazed window sections	Fair	No Action Red	quired	В	20	9	m2	6,767
								Year 1 Repair Cost (£)



Element : Doors

CODE :2

Element . Doors	CODE .2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
PVC-u glazed door	Fair	No Action Required	В	10	1	No.	1,626

Photo 1	Photo 2	F	Position				
Element : Decoration	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Masonry paint	Fair	No Action Required	В	2	6	m2	82
		•	-	-	0	1112	

BUILDING : Block 06 Greenhous	e UPRN :	F	LOOR : Elevations			
ROOM : Elevation	No : 002/6/8	E/002	USE :			
Element : External walls	CODE:2					Replacement
Description Render finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 25	Quantity 3 m2	Cost (£) 164
						Year 1 Repair Cost (
Element : Windows	CODE:2					Replacement
Description PVC-u casement double-glazed	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 20	Quantity 18 m2	Cost (£) 13,534
window sections	Fall	No Action Required	D	20	10 1112	
						Year 1 Repair Cost (
Photo 1	Photo 2		Position			
Element : Decoration	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
	Eoir	No Action Required	В	2	3 m2	41
Masonry paint	Fair					Year 1

BUILDING : Block 06 Greenhous	e UPRN :	F	LOOR : Elevations			
ROOM : Elevation	No : 002/	6/E/003	USE :			
Element : Windows Description PVC-u casement double-glazed	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 20	Quantity 16 m2	Replacement Cost (£) 12,030
window sections		No Action Required	U	20	10 112	Year 1 Repair Cost (៛
Photo 1	Photo 2		Position			
Element : Doors Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
PVC-u glazed door	Fair	No Action Required	В	10	1 No.	1,626
						Year 1 Repair Cost (£

BUILDING : Block 06 Greenhous	e UPRN :	F	LOOR : Elevations			
ROOM : Elevation	No : 002	/6/E/004	USE :			
Element : External walls	CODE:2					Replacement
Description Render finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 25	Quantity 3 m2	Cost (£) 164
						Year 1 Repair Cost (£
Element : Windows	CODE :2					Replacement
Description PVC-u casement double-glazed	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 20	Quantity 18 m2	Cost (£) 13,534
window sections						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Decoration	CODE : 2					Replacement
Description Masonry paint	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 2	Quantity 3 m2	Cost (£) 41
						Year 1 Repair Cost (£

BUILDING : Block 06 Greenhou	ISE	UPRN :	FLOOR : E	Elevations				
ROOM : Elevation		No : 002/6/E/005	USE :					
Element : External walls Description Block pointed finish	CODE Condition Fair	Action	on Required	Cond/Ind Priority B	L'Expec 20	Quan 4	tity m2	Replacement Cost (£) 109
								Year 1 Repair Cost (£)
Photo 1		Photo 2	Posit	ion				

BUILDING : Block 07 Flat 1A	UPRN :		FLOOR : Elevations			
ROOM : Elevation001	No : 002/7/	'E/001	USE :			
Element : External walls	CODE:2					Replacement
Description Stone / render	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 9 m2	Cost (£) 1,599
Window surrounds :cills,lintols	Fall	NO ACION REQUIRED	D	30	9 1112	
and jambs						Year 1 Repair Cost (£
Element : External walls	CODE :2					
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Stone walls	Fair	No Action Required	B	50	28 m2	4,976
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Windows	CODE:2					Replacement
Description PVC-u tilt and turn double glazed	Condition Fair	Action No Action Required	Cond/Ind Priority B	28	Quantity 4 m2	Cost (£) 3,007
						Year 1 Repair Cost (£

PVC-u frame double glazed

Element : Windows Description	CODE :2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Timber sash and case double glazed	Fair	No Action Required	В	28	2	m2	984 Year 1 Repair Cost (£
Element : Windows	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
PVC-u fixed pane double glazed n porch frame	Fair	No Action Required	В	28	•	m2	2,255
							Year 1 Repair Cost (£
Element : Doors	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
UPVC door	Fair	No Action Required	В	18	1	No.	1,626
							Year 1 Repair Cost (f

Element : External joinery	CODE :2						Replacement
Description Timber boarding	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quanti 2	ty m2	Cost (£) 109
							Year 1 Repair Cost (£)
Element : External joinery	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Timber fascia	Fair	No Action Required	В	23	2	m2	109
							Year 1 Repair Cost (£)
Element : Decoration	CODE :2						Bonlocomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	tv	Replacement Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	6	m2	82
							Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A ROOM : Elevation002	UPRN : No : 002/7		LOOR : Elevations			
Element : External walls Description Stone walls	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 50	Quantity 24 m2	Replacement Cost (£) 4,265
						Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : External walls	CODE:2					Replacement
Description Stone / render Window surrounds :cills,lintols	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 9 m2	Cost (£) 1,599
and jambs						Year 1

Year 1 Repair Cost (£)

Element : Windows	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quar	ntity	Cost (£)
Timber sash and case double	Fair	No Action Required	В	28	4	m2	1,968
							Year 1 Repair Cost (£)

glazed

Element : Windows Description PVC-u tilt and turn double glazed	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 28	Quantity 2 m2	Replacement Cost (£) 1,503
						Year 1 Repair Cost (£)
Element : Decoration	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	4 m2	54
						Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A		UPRN :		FLOOR : E	levations				
ROOM : Elevation003		No : 002/7/E/003	3	USE :					
Element : External walls	CODE	:2							Replacement
Description	Condition		Action		Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Stone walls	Fair		No Action Required		В	50	11	m2	1,954
									Year 1 Repair Cost (£
Photo 1		Photo 2		Positi	on				

Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Stone / render	Fair	No Action Required	В	35	6	m2	1,066
Window surrounds :cills,lintols and jambs							Year 1 Repair Cost (£)
Element : Windows	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Timber sash and case double	Fair	No Action Required	В	28	4	m2	1,968
							Year 1 Repair Cost (£)

glazed

Element : Decoration	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quai	ntity	Cost (£)
Re-decoration All timber finishes	Fair	No Action Required	В	3	4	m2	54 Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge ROOM : Elevation001	UPRN : No : 002/8/		FLOOR : Elevations USE :			
Element : External walls Description Stone pointed finish	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 28	Quantity 31 m2	Replacement Cost (£) 847 Year 1 Repair Cost (£)
Element : External walls Description Window surrounds :cills,lintols and jambs	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 48	Quantity 40 m2	Replacement Cost (£) 7,108 Year 1 Repair Cost (£)
Element : External walls Description Render	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 33	Quantity 12 m2	Replacement Cost (£) 656 Year 1 Repair Cost (£)
Element : External walls Description Stone walls	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 35	Quantity 31 m2	Replacement Cost (£) 5,509 Year 1 Repair Cost (£)



Element : Windows CODE:2 Replacement Condition Description Action Cond/Ind Priority L'Expec Cost (£) Quantity Aluminium casement double Fair No Action Required В 28 8 m2 6,015 glazed Year 1 Repair Cost (£) Element : Decoration CODE:2 Replacement Condition Action Cond/Ind Priority Description L'Expec Quantity Cost (£) Re-decoration Fair but requires minor Redecorate flaking paint в 4 3 141 m2 1,927 All wall and timber finishes redecoration Year 1 Repair Cost (£) 80

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Elevations			
ROOM : Elevation002	No : 002/8	3/E/002	USE :			
Element : External walls Description Wet Dash	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 15 m2	Replacement Cost (£) 820
						Year 1 Repair Cost (£)
Photo 1	Photo 2		Position			

BUILDING : Block 08 Lodge	U	JPRN :	F	LOOR : EI	evations				
ROOM : Elevation003		No:002/8/E/003		USE :					
Element : External walls Description Wet Dash	CODE : 2 Condition Fair	Ad	ction lo Action Required		Cond/Ind Priority B	L'Expec 33	Quanti 13	t y m2	Replacement Cost (£) 710
									Year 1 Repair Cost (£)
Photo 1	Ph	noto 2		Positio	on				

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Elevations			
ROOM : Elevation004	No : 002/8	/E/004	USE :			
Element : External walls Description Wet Dash	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 4 m2	Replacement Cost (£) 218
						Year 1 Repair Cost (£)
Photo 1	Photo 2		Position			

BUILDING : Block 08 Lodge		UPRN :		FLOOR : E	levations				
ROOM : Elevation005		No : 002/8/E/00	05	USE :					
Element : External walls	COD	E:2							Replacement
Description	Condition		Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Wet Dash	Fair		No Action Required	ł	В	33	8	m2	437
									Year 1 Repair Cost (£
Photo 1	est-	Photo 2		Positi	on				

Element : Windows	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Aluminium casement double glazed	Fair	No Action Required	В	28	1	m2	751
<u></u>							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge ROOM : Elevation006	UPRN :	2/8/E/006	FLOOR : Elevations				
	NO :00	2/8/E/000	USE :				
Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
Wet Dash	Fair	No Action Required	В	33	9	m2	492
							Year 1 Repair Cost (
Photo 1	Photo 2		Position				
Element : Windows	CODE :2						Poplacomont

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Aluminium casement double	Fair	No Action Required	В	28	2	m2	1,503
glazed							Year 1 Repair Cost (£)
Element : Windows	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Timber softwood casement single glazed	Fair	No Action Required	В	15	1	m2	410
9.4204							Year 1 Repair Cost (£)

UILDING : Block 08 Lodge		UPRN :	FLOOR : Elevations					
ROOM : Elevation007		No : 002/8/E/007	USE :	USE :				
lement : External walls escription	CODE Condition	2 Action	Cond/Ir	nd Priority	L'Expec	Quant	it./	Replacement Cost (£)
/et Dash	Fair		Required B	na i nonty	33	6	m2	328
								Year 1 Repair Cost (£
Photo 1		Photo 2	Position					

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Cement render	Fair	No Action Required	В	20	2	m2	355
							Year 1 Repair Cost (£)
Element : External walls	CODE : 2	Action	Cond/Ind Driverity		0		Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ιτy	Cost (£)
Stone walls	Fair	No Action Required	В	48	31	m2	5,509
							Year 1 Repair Cost (£)

Element : External walls Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Stone wall pointing	Fair	No Action Required	B	28	31 m2	848
						Year 1 Repair Cost (£
Element : External walls	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Window surrounds :cills,lintols and jambs	Fair	No Action Required	В	48	10 m2	1,777
						Year 1 Repair Cost (I
Element : Windows	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Aluminium casement double glazed	Fair	No Action Required	В	28	2 m2	1,503
•						Year 1 Repair Cost (I
Element : Windows	CODE :2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber softwood casement single glazed	Fair	No Action Required	В	15	1 m2	410
3						Year 1 Repair Cost (

Element : Doors Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Qua	ntity	Replacement Cost (£)
Aluminium glazed	Fair	No Action Required	В	18	1	No.	1,200
							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge		UPRN :		FLOOR : E	levations				
ROOM : Elevation008		No : 002/8/E/008	3	USE :					
Element : External walls Description Stone walls	CODE Condition Fair	::2	Action No Action Required		Cond/Ind Priority B	L'Expec 35	Quantit 9	y m2	Replacement Cost (£) 1,599
									Year 1 Repair Cost (£
Photo 1		Photo 2		Positi	on				

Element : External walls	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Stone pointed finish	Fair	No Action Required	В	28	9	m2	246
							Year 1 Repair Cost (£)
Element : External walls	CODE : 2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Window surrounds :cills,lintols and jambs	Fair	No Action Required	В	48	10	m2	1,777
and jamps							Year 1 Repair Cost (£)

Element : Windows Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quar	tity	Replacement Cost (£)
Aluminium casement double	Fair	No Action Required	B	28	3	m2	2,255
glazed							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge ROOM : Elevation009	UPRN : No : 002	2/8/E/009	FLOOR : Ele USE :	vations				
Element : External walls Description Stone walls	CODE : 2 Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 35	Quanti 3	i ty m2	Replacement Cost (£) 533
								Year 1 Repair Cost (£)
Element : External walls	CODE :2							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Stone pointed finish	Fair	No Action Required		В	28	3	m2	82
								Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge ROOM : Elevation010	UPRN : No : 002/8		FLOOR : Elevations USE :			
Element : External walls	CODE : 2	, _ , 0 , 0				
Description Stone pointed finish	Condition Fair	Action No Action Required	Cond/Ind Prio B	rity L'Expec	Quantity 8 m2	Replacement Cost (£) 218
						Year 1 Repair Cost (£
Element : External walls	CODE :2					Deplessment
Description Window surrounds :cills,lintols	Condition Fair	Action No Action Required	Cond/Ind Prio B	rity L'Expec 48	Quantity 6 m2	Replacement Cost (£) 1,066
and jambs						Year 1 Repair Cost (£)
Element : External walls	CODE:2					
Description	Condition	Action	Cond/Ind Prio	rity L'Expec	Quantity	Replacement Cost (£)
Stone walls	Fair	No Action Required	В	35	8 m2	1,421
						Year 1 Repair Cost (£)
Element : Windows	CODE : 2					Replacement
Description	Condition	Action	Cond/Ind Prio	rity L'Expec	Quantity	Cost (£)
Aluminium casement double glazed	Fair	No Action Required	В	28	2 m2	1,503
gidzou						Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Elevations			
ROOM : Elevation011	No : 002	2/8/E/011	USE :			
Element : External walls	CODE:2					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Stone walls	Fair	No Action Required	В	35	3 m2	
						Year 1 Repair Cost (!
Photo 1	Photo 2		Position			

Element : External walls	CODE :2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Stone pointed finish	Fair	No Action Required	В	28	3	m2	82
							Year 1 Repair Cost (£)
Element : Doors	CODE:2						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Timber panelled door with glazed	Fair	No Action Required	В	18	1	No.	1,200
transome							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Elevations			
ROOM : Elevation012	No : 002/8/	/E/012	USE :			
Element : External walls Description Stone pointed finish	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	28	Quantity 8 m2	Replacement Cost (£) 218 Year 1 Repair Cost (£
Element : External walls Description Window surrounds :cills,lintols and jambs	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	7 L'Expec 48	Quantity 6 m2	Replacement Cost (£) 1,066 Year 1 Repair Cost (£)
Element : External walls Description Stone walls	CODE : 2 Condition Fair	Action No Action Required	Cond/Ind Priority B	7 L'Expec 35	Quantity 8 m2	Replacement Cost (£) 1,421 Year 1 Repair Cost (£)
Photo 1	Photo 2		Position			

Element : Windows Description	CODE : 2 Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Aluminium casement double glazed	Fair	No Action Required	В	28	2	m2	1,503 Year 1 Repair Cost (£)

EXTERNAL GROUNDS

BUILDING : Block 01 Kyd	UPRI	۱:	FLOOR : Ex	xternal Grounds			
ROOM : External Grounds	No	o :002/1/EG/EG	USE :				
Element : Roads & Parking Area	as CODE :3						Replacement
Description Concrete roads and parking	Condition Fair	Action No Action Require	ed	Cond/Ind Priority B	L'Expec 20	Quantity 938 m2	Cost (£) 76,940
							Year 1 Repair Cost (£
Photo 1	Photo		Positio	on View of the second sec			
Element : Underground Drainag Description Foul and surface water drainage	Condition	Action No Action Require	ed	Cond/Ind Priority B	L'Expec 35	Quantity 1	Replacement Cost (£)
							Year 1 Repair Cost (£

Element : Paths & Paving	CODE:3						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Concrete slab paths/paving	Fair	No Action Required	В	20	656	m2	44,840
							Year 1 Repair Cost (£)

Photo 1	Photo 2		Position				
Element : Paths & Paving	CODE:3						
Description	Condition	Action	Cond	/Ind Priority	L'Expec	Quant	ity
Chips	Fair, although isolated areas require additional chips	Make good as required	В	4	10	104	m2







Position



Replacement Cost (£)

Year 1 Repair Cost (£)

4,265

300

Element : Paths & Paving Description Monoblock paths	CODE : 3 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 286 m2	Replacement Cost (£) 15,639 Year 1 Repair Cost (£)
Photo 1	Photo 2		osition			
Element : Paths & Paving	CODE :3					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Concrete paths/paving	Fair	No Action Required	В	20	20 m2	820
						Year 1 Repair Cost (£)



Photo 2

Element : Steps/ramps Description Concrete steps/ramps	CODE : 3 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 24 m2	Replacement Cost (£) 4,921 Year 1 Repair Cost (£
Photo 1	Photo 2		Position			
Element : Handrails	CODE:3					Replacement
Description Metal handrails	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 20	Quantity 18 m	Cost (£) 1,230
						Year 1 Repair Cost (£
Element : Boundary fencing/walls	s CODE:3					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Stone boundary wall	Fair	No Action Required	В	20	424 m2	11,593
Note: Cost relates to re-pointing						Year 1 Repair Cost (f



Element : Boundary fencing/walls

CODE:3

Replacement Description Condition Action **Cond/Ind Priority** L'Expec Quantity Cost (£) Stone pointed finish Fair В 20 46 1,257 No Action Required m2

> Year 1 Repair Cost (£)

Photo '	1
---------	---



Position

Element : Boundary fencing/walls	COD	E:3					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Block painted finish retaining wall	Fair	No action required	В	15	34	m2	929
							Year 1 Repair Cost (£)
Photo 1		Photo 2	Position				

Elen

Desc Timb

ement : Boundary fencing/wa	alls CODE:3					Replacement
escription	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
mber gate	Fair	No Action Required	В	15	1	300
						Year 1

Repair Cost (£)

Photo 2

Element : Boundary fencing/walls CODE:3 Replacement Condition Description Action Cond/Ind Priority L'Expec Cost (£) Quantity Brick pointed finish Fair No Action Required В 28 14 m2 382 Year 1 Repair Cost (£) Photo 1 Photo 2 Position

Position

Element : Boundary fencing/walls CODE:3 Replacement Description Condition Action **Cond/Ind Priority** L'Expec Quantity Cost (£) 15 Fair В 14 861 Timber slatted fencing No Action Required m2 Year 1

Repair Cost (£)



Element : Outdoor Sports Facil Fixed Furniture	ities / CODE:3					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 no. timber shelter	Fair	No action required	В	10	4	10,000
2 no. timber huts						Year 1 Repair Cost (£)
1 no. gardners hut						Repair Cost (£)



Element : Outdoor Sports Facilit Fixed Furniture Description 2 no Garages	ies / CODE : 3 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 20	Quantity 2	Replacement Cost (£) 7,000 Year 1
Photo 1	Photo 2	Posi	ition			Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :	FL	OOR : External Grounds			
ROOM : External Grounds	No : 002/8/	/EG/EG	USE :			
Element : Paths & Paving Description Concrete slab paths/paving	CODE : 3 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 25	Quantity 40 m2	Replacement Cost (£) 2,734
						Year 1 Repair Cost (£
Element : Paths & Paving	CODE : 3					Replacement
Description Concrete paths	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 30	Quantity 28 m2	Cost (£) 1,148
						Year 1 Repair Cost (£)
Element : Paths & Paving	CODE : 3					Replacement
Description Monoblock paths/paving	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 25 m2	Cost (£) 1,367
						Year 1 Repair Cost (£)







Element : Steps/ramps Description 1 - 2 step concrete stair 1 - 3 step concrete stair 1 - 6 step concrete stair	CODE : 3 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 28	Quantity 11 m2	Replacement Cost (£) 2,255 Year 1 Repair Cost (£)
Photo 1	Photo		Position			
Element : Walls/dwarf walls Description Stone wall and concrete cope	CODE : 3 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 48	Quantity 21 m2	Replacement Cost (£) 6,890 Year 1 Repair Cost (£)
Element : Walls/dwarf walls Description Brick retaining wall with concrete cope	CODE : 3 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 30	Quantity 35 m2	Replacement Cost (£) 3,588 Year 1 Repair Cost (£)

						Replacemen
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
All timber finishes	Fair	No Action Required	В	3	94 m2	1,927
						Year 1 Repair Cost
Element : Landscaping	CODE : 3					Replacemer
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Various landscaping Grassed areas	Fair	No Action Required	В	1	1 m2	400
Grassed areas						Year 1 Repair Cost
Element : Boundary fencing/wa	alls CODE : 3					
Description	Condition	Action	Cond/Ind Priority	l 'Expos	Quantity	
Description Stone built boundary wall	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec	Quantity 20 m2	Replacemer Cost (£) 8.202
Description Stone built boundary wall	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 20 m2	
-	Fair		•	•	•	Cost (£) 8,202 Year 1 Repair Cost
Stone built boundary wall	Fair		•	•	•	Cost (£) 8,202 Year 1
Stone built boundary wall Element : Boundary fencing/wa	Fair alls CODE : 3	No Action Required	B	35	20 m2	Cost (£) 8,202 Year 1 Repair Cos

Element : Boundary fencing/wa	alls CODE : 3					Replacement
Description	Condition	Action	Cond/Ind Priority	-	Quantity	Cost (£)
Timber slatted fencing	Fair	No Action Required	В	10	84 m2	5,167
						Year 1 Repair Cost (£)
Photo 1	Photo 2	Po	osition			
Element : Outdoor Sports Faci	lities / CODE : 3					
Fixed Furniture					•	Replacement
Description Garden shed	Condition	Action	Cond/Ind Priority B	L'Expec	Quantity	Cost (£)
Garden sned	Fair	No Action Required	В	15	I	600
						Year 1 Repair Cost (£)

STRUCTURE

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Gro					
ROOM : Hall	No : 00	02/1/0/002	USE :					
Element : Stairs	CODE:4							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Timber stair	Fair	No action required		В	40	34	m2	3,486
								Year 1 Repair Cost (£

BUILDING : Block 01 Kyd ROOM : Structure	UPRN : FL No : 002/1/St/St		FLOOR : Str USE :	ucture				
Element : Floors Description Timber floor	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantit 1	y m2	Replacement Cost (£) 103 Year 1 Repair Cost (£)
Element : Walls Description Stone / plastered walls	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantit 1	y m2	Replacement Cost (£) 205 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Circulation Area	UPRN : No : (002/2/0/001	FLOOR : Ground USE :				
Element : Stairs Description Concrete stair	CODE : 4 Condition Fair	Action No action required	Cond/Ind Priority B	/ L'Expec 40	Quan 4	tity m2	Replacement Cost (£) 1,367
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Plant Room	UPRN : No : 00	2/2/0/007	FLOOR : Ground USE :				
Element : Stairs Description	CODE : 4 Condition	Action	Cond/Ind Priori	• •	Quant	•	Replacement Cost (£)
Timber stair	Fair	No action required	В	15	4	m2	410 Year 1 Repair Cost (£)

BUILDING : Block 02 Mck ROOM : Circulation A	-	UPRN : No : 002/2/0/014	FLOOR : Ground USE :				
Element : Stairs Description Concrete stair	CODE Condition Fair	-	Cond/Ind Priority	L'Expec 40	Quant 19	t ity m2	Replacement Cost (£) 6,600
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Circulation Area	UPRN : No :	002/2/1/001	FLOOR : Fi USE :	rst				
Element : Stairs Description Concrete stair	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 58	Quanti 2	ty m2	Replacement Cost (£) 683
								Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : F	irst				
ROOM : Circulation Area 20	No : (002/2/1/009	USE :					
Element : Stairs Description	CODE : 4	Action		Cond/Ind Priority	L'Expec	Quant	itv	Replacement Cost (£)
Timber stair	Fair	No action required		В	38	2	m2	205
								Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Structure	UPRN : No : 002/2/S	st/St	FLOOR : S USE :	tructure				
Element : Floors Description Timber floor	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantit 1	y m2	Replacement Cost (£) 103 Year 1 Repair Cost (£)
Element : Walls Description Brick/block on plaster	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantit 1	y m2	Replacement Cost (£) 137 Year 1 Repair Cost (£)

BUILDING : Block 03 Dall ROOM : Circulation A		UPRN : No : 002/3/0/001	FLOOR : Ground USE :				
Element : Stairs Description Concrete stair	CODE Condition Fair	: 4 Action No action	Cond/Ind Priority required B	L'Expec 40	Quan 8	tity m2	Replacement Cost (£) 2,734
							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie ROOM : Structure	UPRN : No : 002/3/St/	St	FLOOR : S USE :	tructure				
Element : Floors Description Timber floor	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quanti i 1	t y m2	Replacement Cost (£) 103 Year 1 Repair Cost (£)
Element : Walls Description Brick/block on plaster	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quanti 1	t y m2	Replacement Cost (£) 137 Year 1 Repair Cost (£)

BUILDING : Block 04 Kea ROOM : Circulation A		UPRN : No : 002/4/0/016	FLOOR : Ground USE :				
Element : Stairs Description Concrete stair	CODE Condition Fair		Cond/Ind Priority	L'Expec 40	Quan 10	tity m2	Replacement Cost (£) 3,417
				10		2	Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Structure	UPRN : FL No : 002/4/St/St		FLOOR : St USE :	ructure				
Element : Floors Description Concrete floor	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantity 1	/ m2	Replacement Cost (£) 164 Year 1 Repair Cost (£)
Element : Walls Description Concrete/brick walls	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantity 1	/ m2	Replacement Cost (£) 116 Year 1 Repair Cost (£)

BUILDING : Block 05 Dining ROOM : Structure	UPRN : FL No : 002/5/St/St		FLOOR : Structure USE :							
Element : Floors Description Timber floor	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantit 1	y m2	Replacement Cost (£) 103 Year 1 Repair Cost (£)		
Element : Walls Description Stone / plastered walls	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantit 1	y m2	Replacement Cost (£) 205 Year 1 Repair Cost (£		

BUILDING : Block 06 Greenhou	se UPRN:	FLOO	DR : Structure			
ROOM : Structure	No : 002/6	s/St/St U	SE :			
Element : Frame/Columns Description	CODE : 4	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Metal frame	Fair	No action required	B	50	1 tonne	2,734
						Year 1 Repair Cost (£
Element : Floors	CODE : 4					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Concrete floor	Fair	No action required	В	50	1 m2	164
						Year 1 Repair Cost (£
Element : Walls	CODE : 4					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Blockwork	Fair	No action required	В	50	1 m2	137
						Year 1 Repair Cost (£

BUILDING : Block 07 Flat 1A ROOM : Bedroom	UPRN : No : 002		FLOOR : Ground USE :				
Element : Stairs Description Concrete stair	CODE : 4 Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 35	Quant 2	i ity m2	Replacement Cost (£) 683
							Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A ROOM : Structure	UPRN : No : 002/7	7/St/St	FLOOR : Structure USE :			
Element : Floors Description Timber floor	CODE : 4 Condition Fair	Action No action required	Cond/Ind Price B	ority L'Expec 40	Quantity 1 m2	Replacement Cost (£) 102
						Year 1 Repair Cost (£)
Element : Walls	CODE : 4					Replacement
Description	Condition	Action	Cond/Ind Prie	ority L'Expec	Quantity	Cost (£)
Stone / plastered walls	Fair	No action required	В	40	1 m2	205
						Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge ROOM : Living Room	UPRN : No : 002	2/8/0/004	FLOOR : Ground USE :				
Element : Stairs Description Timber stair	CODE : 4 Condition Fair	Action No action required	Cond/Ind Prio B	ity L'Expec 32	Quar 2	ntity m2	Replacement Cost (£) 205
							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge ROOM : Structure	UPRN : No : 002/	8/St/St	FLOOR : Str USE :	ucture				
Element : Floors Description Timber floor	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantity 1 m2		Replacement Cost (£) 103 Year 1 Repair Cost (£)
Element : Walls Description Stone / plastered walls	CODE : 4 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 40	Quantit <u>i</u> 1	y m2	Replacement Cost (£) 205 Year 1 Repair Cost (£)

ROOMS

BUILDING : Block 01 Kyd	UPRN :	F	LOOR : Ground			
ROOM : Entrance Foyer	No : 002/1/	/0/001	USE :			
Element : Ceilings	CODE :5					Replacement
Description Lath & plaster ceiling, including	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 10	Quantity 9 m2	Cost (£) 1,000
ornate cornice and ceiling rose						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description Lath & plaster to walls	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 15	Quantity 13 m2	Cost (£) 710
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description Timber panelling to dado level	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 15	Quantity 5 m2	Cost (£) 341
						Year 1 Repair Cost (£
Element : Windows	CODE :5					Devlessment
Description Timber window surround	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 15	Quantity 10 m2	Replacement Cost (£) 700
						Year 1 Repair Cost (£

Element : Floors Description	CODE :5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement
Tiled mosaic floor finish	Fair	No Action Required	B	с Ехрес 15	-	Cost (£) 1,000
						Year 1 Repair Cost (£)
Element : Decoration Description	CODE :5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Emulsion to ceiling and walls; varnish to timber finishes	Fair	No Action Required	В	3	•	2 410 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Hall	UPRN : No : 002/1/		FLOOR : Ground USE :			
Element : Ceilings	CODE:5					
Description Lath & plaster ceiling, including ornate cornice	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 10	Quantity 70 m2	Replacement Cost (£) 8,000
						Year 1 Repair Cost (£
Element : Ceilings	CODE :5					
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Replacement Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	25	7 m2	239
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description Lath & plaster to walls	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 15	Quantity 280 m2	Cost (£) 15,311
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description Timber panelling to dado level	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 15	Quantity 30 m2	Cost (£) 2,050
						Year 1 Repair Cost (£)

Element : Partitions Description Timber part glazed partitions	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 9 m2	Replacement Cost (£) 1,968
Timber part glazed partitions		No Actor Required	U	10	5 112	Year 1 Repair Cost (£)
Element : Windows	CODE : 5					Replacement
Description Timber window surround	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 11 m2	Cost (£) 4,511
						Year 1 Repair Cost (£)
Element : Doors	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber door with viewing panel	Fair	No Action Required	В	15	1 No	1,093
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	2 No	2,734
						Year 1 Repair Cost (£)

Element : Floors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Carpet sheet finish, with colour contrasted non-slip nosings to steps .	Fair	No Action Required	В	8	77	m2	3,500
							Year 1 Repair Cost (£)
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	407	m2	3,338
gioco, varmen to timbol miloned							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Office	No : 002/1/0	0/003	USE :			
Element : Ceilings	CODE :5					Replacement
Description Lath & plaster ceiling, including	Condition Fair	Action No Action Required	Cond/Ind Pric	ority L'Expec	Quantity 40 m2	Cost (£) 4,400
ornate cornice and ceiling rose						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	80 m2	4,374
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description Ceramic tiles to fireplace	Condition Fair	Action No Action Required	Cond/Ind Prid B	ority L'Expec 15	Quantity 2 m2	Cost (£) 164
						Year 1 Repair Cost (£)
Element : Windows	CODE :5					Replacement
Description Timber window surround	Condition Fair	Action No Action Required	Cond/Ind Prid B	ority L'Expec 15	Quantity 19 m2	Cost (£) 950
						Year 1 Repair Cost (£)

Element : Doors Description Softwood timber panelled door	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 10	Quantity 1	/ No	Replacement Cost (£) 656 Year 1 Repair Cost (£)
Element : Floors	CODE :5						Poplacomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	40	m2	1,640
							Year 1 Repair Cost (£)
Element : Decoration	CODE:5						Donlocomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	50	m2	410 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground	1			
ROOM : Library	No : 002/1/0	0/004	USE :				
Element : Ceilings	CODE : 5						Replacement
Description Lath & plaster ceiling, including	Condition Fair	Action No Action Required	Cor	n d/Ind Priority B	L'Expec 10	Quantity 34 ı	Cost (£) m2 4,000
ornate cornice and ceiling rose							Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action	Cor	nd/Ind Priority	L'Expec	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required		В	15	64 i	m2 3,499
							Year 1 Repair Cost (£
Element : Windows	CODE :5						Replacement
Description	Condition	Action	Cor	nd/Ind Priority	L'Expec	Quantity	Cost (£)
Timber window surround	Fair	No Action Required		В	15	10 ı	m2 700
							Year 1 Repair Cost (£
Element : Doors	CODE :5						Replacement
Description Softwood timber panelled door	Condition Fair	Action No Action Required	Cor	n d/Ind Priority B	L'Expec 10	Quantity 1	Cost (£) No 656
							Year 1 Repair Cost (£

Element : Doors	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber panelled/glazed sliding doors	Fair	No Action Required	В	15	2 No	2,624
						Year 1 Repair Cost (£
Element : Floors	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	34 m2	2 1,394
						Year 1 Repair Cost (£
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair, although slight flaking of painterwork in isolated area	Make good finish	B 4	3	124 m2	2 1,017
•						Year 1 Repair Cost (£) 50

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Games	No : 002/1/0	0/005	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Lath & plaster ceiling, including	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec 10	Quantity 32 m2	Cost (£) 3,500
ornate cornice and ceiling rose						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	48 m2	2,624
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description Ceramic tiles to walls	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec 15	Quantity 2 m2	Cost (£) 164
						Year 1 Repair Cost (£
Element : Windows	CODE : 5					Replacement
Description Timber window surround	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec 15	Quantity 14 m2	Cost (£) 700
						Year 1 Repair Cost (£

CODE :5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair	No Action Required	В	10	1 No	656
					Year 1 Repair Cost (£)
CODE :5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair	No Action Required	В	15	1 No	656
					Year 1 Repair Cost (£)
CODE :5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair	No Action Required	В	15	1 No	492
					Year 1 Repair Cost (£)
CODE :5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair	No Action Required	В	8	32 m2	1,312
					Year 1 Repair Cost (£)
	Condition Fair CODE : 5 Condition Fair CODE : 5 Condition Fair CODE : 5 CODE : 5 CODE : 5	Condition FairAction No Action RequiredCODE :5Action No Action RequiredFairAction No Action RequiredCODE :5Action No Action Required	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5 Condition FairAction No Action RequiredCond/Ind Priority BCODE :5 Condition FairAction 	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 10CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15CODE :5 Condition FairAction No Action RequiredCond/Ind Priority L'ExpecL'Expec 15	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 10Quantity 1CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quantity 1CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quantity 1CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quantity 1CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quantity 1CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quantity Quantity 15

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	126	m2	1,033 Year 1
							Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Reception	UPRN : No : 002/1/	/0/006	FLOOR : Gro USE :	bund			
		0/008	03E .				
Element : Ceilings	CODE:5	Action		Cond/Ind Priority	L'Expec	Quentity	Replacement
Description Suspended grid system with	Fair	No Action Required		B	L Ехрес 10	Quantity 9 m2	Cost (£) 2 307
fibreboard tiles							Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required		В	15	9 m2	2 492
							Year 1 Repair Cost (£)
Element : Walls	CODE :5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	l	В	25	15 m2	2 512
							Year 1 Repair Cost (£)
Element : Doors	CODE : 5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber panelled top glazed	Fair	No Action Required	l	В	10	1 No	656
giazoa							Year 1 Repair Cost (£)

Element : Floors Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	9 m2	369
						Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement
•	Fair		•	•	•	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	30 m2	246
						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground					
ROOM : Hall	No : 002/1/	0/007	USE :					
Element : Ceilings	CODE :5							Replacement
Description Suspended grid system with fibreboard tiles	Condition Fair	Action No Action Required	Cond/Ind B	I Priority	L'Expec 10	Quantity 6	m2	Cost (£) 205
hbreboard tiles								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	l Priority	L'Expec	Quantity		Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	-	15	15	m2	820
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity		Cost (£)
Plaster walls	Fair	No Action Required	В		15	11	m2	451
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	l Priority	L'Expec	Quantity		Cost (£)
Softwood timber with viewing	Fair	No Action Required	В	-	10	1	No	656
panel								Year 1 Repair Cost (£)

Element : Doors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Softwood timber panelled top glazed	Fair	No Action Required	В	10	1	No	656
							Year 1 Repair Cost (
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	9	m2	369
							Year 1 Repair Cost
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	34	m2	278
-							Year 1 Repair Cost

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Manager	No : 002/1/0	0/008	USE :			
Element : Ceilings	CODE :5					Replacement
Description Lath & plaster ceiling, including ornate cornice	Condition Fair	Action No Action Required	Cond/Ind Priori B	t y L'Expec 10	Quantity 37 m2	Cost (£) 4,100
omate comice						Year 1 Repair Cost (£
Element : Walls	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priori	ty L'Expec	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	46 m2	2,515
						Year 1 Repair Cost (£
Element : Walls	CODE : 5					Replacement
Description Timber panelling to walls	Condition Fair	Action No Action Required	Cond/Ind Priori B	t y L'Expec 15	Quantity 19 m2	Cost (£) 1,298
						Year 1 Repair Cost (£)
Element : Windows	CODE:5					Poplacomont
Description Timber window surround	Condition Fair	Action No Action Required	Cond/Ind Priori B	t y L'Expec 15	Quantity 20 m2	Replacement Cost (£) 1,000
						Year 1 Repair Cost (£

CODE : 5						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
Fair	No Action Required	В	10	2	No	1,312
						Year 1 Repair Cost (£
CODE :5						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Fair	No Action Required	В	8	37	m2	1,517
						Year 1 Repair Cost (£
CODE :5						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Fair	No Action Required	В	3	126	m2	1,033
						Year 1 Repair Cost (£
	Condition Fair CODE : 5 Condition Fair CODE : 5 CODE : 5	Condition FairAction No Action RequiredCODE :5Action No Action RequiredFairAction No Action RequiredCODE :5Action No Action RequiredCODE :5Action ActionConditionAction	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority BFairAction No Action RequiredCond/Ind Priority BCODE :5Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority 	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 10CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5Action No Action RequiredL'Expec BL'Expec BCODE :5ActionL'Expec BL'Expec BCODE :5ActionL'Expec BL'Expec B	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 10Quantity 2CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 37CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 37CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 37	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 10Quantity 2NoCODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 37m2CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 37m2CODE :5Action RequiredCond/Ind Priority BL'Expec 8Quantity Guantity GuantityCODE :5ActionCond/Ind Priority BL'Expec BQuantity Guantity

BUILDING : Block 01 Kyd	UPRN :	F	LOOR : Ground			
ROOM : Circulation Area	No : 002/1	/0/009	USE :			
Element : Walls Description Stone pointed finish (painted)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 40	Quantity 10 m2	Replacement Cost (£) 273
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description Unpainted Concrete	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 40	Quantity 4 m2	Cost (£) 273
						Year 1 Repair Cost (£)
Element : Decoration	CODE :5					Doplocoment
Description Emulsion to walls; gloss/varnish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quantity 32 m2	Replacement Cost (£) 262
to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Store	No : 002/1/	/0/010	USE :			
Element : Ceilings	CODE :5					Replacement
Description Suspended grid system with	Condition Fair	Action No Action Required	Cond/Ind Priorit	y L'Expec 10	Quantity 7 m2	Cost (£) 239
fibreboard tiles						Year 1 Repair Cost (£
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priorit	•	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	6 m2	328
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description Plasterboard walls	Condition Fair	Action No Action Required	Cond/Ind Priorit	y L'Expec 25	Quantity 10 m2	Cost (£) 341
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description 1/2 hour fire door set	Condition Fair	Action No Action Required	Cond/Ind Priorit	y L'Expec 23	Quantity 1 No	Cost (£) 1,025
						Year 1 Repair Cost (£

Element : Floors Description	CODE :5 Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Replacement Cost (£)
Quarry tiled floor	Fair	No Action Required	В	20	7	m2	574
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action	Cond/Ind Drivette		Oversti		Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Emulsion to walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	16	m2	131
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground	t.			
ROOM : Store	No : 002/1/0/	/011	USE :				
Element : Ceilings	CODE :5						Replacement
Description Suspended grid system with	Condition Fair	Action No Action Required	Со	n d/Ind Priority B	L'Expec 10	Quantity 8 m2	Cost (£) 273
fibreboard tiles							Year 1 Repair Cost (£)
Element : Walls	CODE :5						Replacement
Description Plaster walls	Condition Fair	Action No Action Required	Со	n d/Ind Priority B	L'Expec 25	Quantity 26 m2	Cost (£) 1,066
							Year 1 Repair Cost (£)
Element : Doors	CODE :5						Replacement
Description Softwood timber flush	Condition Fair, although door frame	Action Make good door fram		n d/Ind Priority B 4	L'Expec 23	Quantity 1 No	Cost (£) 492
	damaged						Year 1 Repair Cost (£) 150
Element : Floors	CODE :5						Replacement
Description Carpet floor finish	Condition Fair	Action No Action Required	Со	n d/Ind Priority B	L'Expec 20	Quantity 8 m2	Cost (£) 328
							Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Emulsion to walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	26	m2	213
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Lounge	UPRN : No : 002/1/		FLOOR : Ground USE :					
Element : Ceilings	CODE :5							Damlasamant
Description Lath & plaster ceiling, including	Condition Fair	Action No Action Required		d/Ind Priority B	L'Expec 10	Quantity 50	m2	Replacement Cost (£) 5,500
ornate cornice and ceiling rose								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Benlessment
Description Lath & plaster to walls	Condition Fair	Action No Action Required		d/Ind Priority B	L'Expec 15	Quantity 49	m2	Replacement Cost (£) 2,679
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Replacement
Description Timber panelling to dado level	Condition Fair	Action No Action Required		d/Ind Priority B	L'Expec 15	Quantity 24	m2	Cost (£) 1,640
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Replacement
Description 1/2 hour fire door set, including 2	Condition Fair	Action No Action Required		d/Ind Priority B	L'Expec 15	Quantity 2	No	Cost (£) 2,050
no. timber/glazed doors				-		-		Year 1 Repair Cost (£)

CODE : 5						Replacement
Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 10	Quanti 1	i ty No	Cost (£) 656
						Year 1 Repair Cost (£
CODE : 5						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Fair	No Action Required	В	8	50	m2	2,050
						Year 1 Repair Cost (£
CODE :5						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ity	Cost (£)
Fair	No Action Required	В	3	139	m2	1,140
	CODE : 5 CODE : 5 CODE : 5 CODE : 5 CODE : 5 CODE : 5	Condition FairAction No Action RequiredCODE : 5Action No Action RequiredFairAction No Action RequiredCODE : 5Action No Action RequiredCODE : 5Action Action No Action Required	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority B	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 10CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Condition FairAction RequiredCond/Ind Priority BL'Expec 8CODE :5Action RequiredL'Expec BL'Expec BCODE :5ActionL'Expec BL'Expec BCODE :5ActionL'Expec BL'Expec B	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 10Quanti 1CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quanti 50CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quanti 50CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quanti 50CODE :5ActionCond/Ind PriorityL'Expec 8Quanti 50	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 10Quantity 1NoCODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 50m2CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 50m2CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 50m2CODE :5ActionCond/Ind PriorityL'Expec 8Quantity 50m2

BUILDING : Block 01 Kyd	UPRN :	FLOOR : G	FLOOR : Ground			
ROOM : Laundry	No : 002/1/0/01	3 USE :				
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair, with hairline cracking in isolated areas	Make good prior to redecoration	B 4	10	19 m2	273
						Year 1 Repair Cost (£ 50
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair, although slightly marked in	Make good prior to redecoration	B 4	25	43 m2	1,763
	areas					Year 1 Repair Cost (£ 100
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster walls	Fair, although slightly marked in areas	Make good prior to redecoration	B 4		11 m2	451
						Year 1 Repair Cost (£ 50
Element : Doors	CODE:5					Damlasamant
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£ 150

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 5	Quantit 19	y m2	Replacement Cost (£) 779
							Year 1 Repair Cost (£)
Element : Decoration	CODE :5	•			0		Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit		Cost (£)
Emulsion to walls; gloss/varnish to timber finishes	Poor	Redecorate	D 4	Replace/In	73	m2	598
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : Ground			
ROOM : Circulation Area	No : 002/1/	0/014	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Lath & plaster ceilin	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 10	Quantity 3 m2	Cost (£) 164
						Year 1 Repair Cost (£
Element : Ceilings	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	25	25 m2	854
						Year 1 Repair Cost (£
Element : Walls	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	30 m2	1,640
						Year 1 Repair Cost (£
Element : Walls	CODE : 5					Donlocomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	25	70 m2	2,392
						Year 1 Repair Cost (£

CODE : 5						Replacement	
Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)	
Fair	No Action Required	В	15	2	No	2,734	
						Year 1 Repair Cost (£)	
CODE :5						Replacement	
Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)	
Fair	No Action Required	В	8	28	m2	1,148	
						Year 1 Repair Cost (£)	
CODE : 5						Poplacoment	
Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)	
Fair	No Action Required	В	3	128	m2	1,049	
						Year 1 Repair Cost (£)	
	CODE :5 CODE :5 CODE :5 CODE :5 CODE :5 CODE :5	Condition FairAction No Action RequiredCODE : 5Action No Action RequiredFairAction No Action RequiredCODE : 5Action No Action RequiredCODE : 5Action ActionConditionAction	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority B	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8CODE :5Action RequiredCond/Ind Priority BL'Expec 8CODE :5Action RequiredL'Expec BL'Expec BCODE :5ActionL'Expec BL'Expec BCODE :5ActionL'Expec BL'Expec B	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quant 2CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quant 28CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quant 28CODE :5Action ActionCond/Ind Priority BL'Expec 8Quant 28CODE :5ActionCond/Ind PriorityL'Expec 8Quant 28	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quantity 2NoCODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 28m2CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 8Quantity 28m2CODE :5Action RequiredCond/Ind Priority BL'Expec 8Quantity 28m2CODE :5ActionCond/Ind Priority BL'Expec 8Quantity 28m2	

BUILDING : Block 01 Kyd ROOM : Kitchen Store	UPRN : No : 002/1/0/01	FLOOR : G 5 USE :	round			
Element : Ceilings	CODE :5					
Description Lath & plaster ceiling	Condition Fair, with slight cracking in isolated areas	Action Make good prior to redecoration	Cond/Ind Priority B 4	L'Expec 10	Quantity 4 m2	Replacement Cost (£) 218
	ISUIALEU ALEAS					Year 1 Repair Cost (£ 50
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster walls	Fair	No Action Required	В	15	23 m2	943
						Year 1 Repair Cost (£
Element : Doors	CODE : 5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 10	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Poplacement
Description Vinyl sheet finish (non-slip)	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 4 m2	Replacement Cost (£) 164
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	30	m2	246 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Kitchen	No : 002/1/	/0/016	USE :			
Element : Ceilings	CODE :5					Replacement
Description Suspended grid system with fibreboard tiles	Condition Fair	Action No Action Required	Cond/Ind Prio B	rity L'Expec 18	Quantity 47 m2	Cost (£) 1,606
hbreboard tiles						Year 1 Repair Cost (£)
Element : Walls	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Prio	rity L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	15	49 m2	2,009
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prio	rity L'Expec	Quantity	Cost (£)
Metal lining sheet to walls	Fair	No Action Required	В	15	11 m2	451
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prio	•	Quantity	Cost (£)
Softwood timber with viewing	Fair	No Action Required	В	10	1 No	656
panel						Year 1 Repair Cost (£)

Element : Floors Description	CODE :5 Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	47	m2	1,927
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Kitchen (small area)	UPRN : No : 002/1/0		FLOOR : Ground USE :			
Element : Ceilings	CODE :5					Replacement
Description Suspended grid system with fibreboard tiles	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 18	Quantity 14 m2	Cost (£) 478
hbreboard tiles						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	15	28 m2	1,148
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	10	1 No	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description Aluminium insect barrier door	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 10	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description	CODE :5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	itv	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	14	m2	574
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Store	No : 002/1/0/017A		USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority	L'Expec 35	Quantity 8 m2	Cost (£) 273
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I B	35	31 m2	1,059
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	I B	10	1 No	1,025
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	-	8	8 m2	328
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	39	m2	319 Year 1
							Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Kitchen Store	No : 002/1/	/0/018	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Pre finished board	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 6 m2	Cost (£) 328
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Doplocoment
Description Pre-finished board	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 20 m2	Replacement Cost (£) 820
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	10	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Donlocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	6 m2	246
						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Kitchen Store	No : 002/1/	0/019	USE :			
Element : Ceilings	CODE :5					Poplacement
Description Suspended grid system with fibreboard tiles	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 15	Quantity 8 m2	Replacement Cost (£) 273
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	15	26 m2	1,066
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 10	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Replacement
Description Vinyl sheet finish (non-slip)	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 8	Quantity 8 m2	Cost (£) 328
						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Kitchen Staff	No : 002/1/	0/020	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Suspended grid system with	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 10	Quantity 4 m2	Cost (£) 136
fibreboard tiles						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Plaster walls	Fair	No Action Required	В	15	17 m2	697
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 10	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£
Element : Floors	CODE:5					Replacement
Description Timber laminate floor	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 8	Quantity 4 m2	Cost (£) 164
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	17	m2	139
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Kitchen Store	No : 002/1/0	/021	USE :			
Element : Ceilings	CODE :5					Replacement
Description Suspended grid system with	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec	Quantity 14 m2	Cost (£) 478
fibreboard tiles						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	35	35 m2	697
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description 1/2 hour fire door set	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec	Quantity 1 No	Cost (£) 1,025
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Poplacement
Description Timber laminate floor	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec 8	Quantity 14 m2	Replacement Cost (£) 574
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	Cond/Ind Priority L'Expec Quantity		tity	Cost (£)
Emulsion to walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	35	m2	287
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : Ground			
ROOM : Circulation Area	No : 002/1/	/0/022	USE :			
Element : Ceilings	CODE :5					Replacement
Description Suspended grid system with	Condition Fair	Action No Action Required	Cond/Ind Priority B	y L'Expec 10	Quantity 4 m2	Cost (£) 136
fibreboard tiles						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Plaster walls	Fair	No Action Required	В	15	14 m2	574
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	10	2 No	2,734
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Poplacomont
Description Timber laminate floor	Condition Fair	Action No Action Required	Cond/Ind Priority B	y L'Expec 8	Quantity 4 m2	Replacement Cost (£) 164
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	14	m2	114
							Year 1 Repair Cost (£)

UPRN :		FLOOR : Gr	ound				
No : 002/1/	/0/022A	USE :					
CODE : 5							Replacement
Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Fair	No Action Required	l	В	10	5	m2	273
							Year 1 Repair Cost (£)
CODE:5							Donlocoment
Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Fair	No Action Required	l	В	15	22	m2	1,203
							Year 1 Repair Cost (£)
CODE : 5							Replacement
Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Fair	No Action Required	l	В	15	2	m2	82
							Year 1 Repair Cost (£)
CODE :5							Donlocoment
Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Fair	No Action Required	I	В	10	1	m2	410
							Year 1 Repair Cost (£)
	No : 002/1. CODE : 5 Condition Fair CODE : 5 Condition Fair CODE : 5 Condition Fair CODE : 5 Condition Fair	No : 002/1/0/022A CODE :5 Condition Fair CODE :5 Condition Fair CODE :5 Condition Fair No Action Required CODE :5 Condition Action No Action Required	No : 002/10/022A USE : CODE : 5 Action No Action Required CODE : 5 Action No Action Required Fair Action No Action Required CODE : 5 Action Condition Action Required	No : 002/1/0/022A USE : CODE :5 Condition Action Cond/Ind Priority Fair No Action Required B CODE :5 Condition Cond/Ind Priority Fair No Action Required Cond/Ind Priority Fair Action Cond/Ind Priority Fair No Action Required B	No : 002/1/0/022A USE : CODE :5 Cond/Ind Priority L'Expec CODE :5 Action Cond/Ind Priority L'Expec Fair Action Cond/Ind Priority L'Expec Fair Action Cond/Ind Priority L'Expec Fair Action Required Cond/Ind Priority L'Expec CODE :5 Action Required B 15 Condition Action Required B 15 Fair No Action Required B 15	No : 002/1/0/022A USE : CODE :5 Cond/Ind Priority L'Expec Quantity Fair Action Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Required Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Required Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Required Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Required Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Required Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Required Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Required Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Required Cond/Ind Priority L'Expec Quantity CODE :5 Condition Action Cond/Ind Priority L'Expec Quantity Condition Action Cond/Ind Priority L'Expe	No : 002/1/0/022A USE : CODE :5 Action No Action Required Cond/Ind Priority B L'Expec Quantity 5 m2 CODE :5 Action No Action Required Cond/Ind Priority B L'Expec Quantity 22 m2 CODE :5 Action No Action Required Cond/Ind Priority B L'Expec Quantity 22 m2 CODE :5 Action No Action Required Cond/Ind Priority B L'Expec Quantity 22 m2 CODE :5 Action No Action Required Cond/Ind Priority B L'Expec Quantity 2 m2 CODE :5 Action Required Cond/Ind Priority B L'Expec Quantity 2 m2 CODE :5 Action Required Cond/Ind Priority B L'Expec Quantity 2 m2 CODE :5 Action Required Cond/Ind Priority B L'Expec Quantity 2 m2

Element : Floors Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	5	m2	205
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quanti	tv	Replacement Cost (£)
Emulsion to ceiling and walls;	Fair	No Action Required	B	3	27	m2	221
gloss/varnish to timber finishes							Year 1

BUILDING : Block 01 Kyd	UPRN :	22	FLOOR : G	round				
ROOM : Circulation Area	No : 002/1/0/0	23	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	y	Cost (£)
Plasterboard ceiling	Fair	No Action Required	l	В	35	10	m2	341
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	y	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	l	В	15	10	m2	341
								Year 1 Repair Cost (£
Element : Floors	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	y	Cost (£)
Timber laminate floor	Fair	No Action Required	l	В	8	3	m2	123
								Year 1 Repair Cost (£)
Element : Decoration	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	y	Cost (£)
Emulsion to ceiling and walls;	Fair	No Action Required	l	В	3	13	m2	106
gloss/varnish to timber finishes								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Store	UPRN : No : 002/1/0/02		FLOOR : Grour USE :	nd				
Element : Ceilings	CODE : 5							Deplessment
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Co	ond/Ind Priority B	L'Expec 10	Quantity 1	/ m2	Replacement Cost (£) 34
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Denlessment
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required		В	25	9	 m2	307
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Donlocoment
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required		В	10	1	No	492
								Year 1 Repair Cost (£)
Element : Floors	CODE:5							Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Vinyl tile floor finish	Fair, although showing signs of	No Action Required		В	2	1	m2	41
	age							Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	12	m2	98 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground			
ROOM : Store	No : 002/1/	/0/024	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 10	Quantity 4 m2	Cost (£) 218
						Year 1 Repair Cost (£ 50
Element : Walls	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	17 m2	929
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	25	3 m2	102
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	В	10	1 No	492
						Year 1 Repair Cost (£)

Element : Floors	CODE:5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Vinyl tile floor finish	Fair, although showing signs of	No Action Required	В	2	4	m2	164
	age						Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action	Cond/Ind Priority	L'Expos	Quanti	41 <i>7</i>	Replacement
Description			•	L'Expec	Quanti	•	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	26	m2	213
gioss/variish to timber finishes							Year 1 Repair Cost (£)

UPRN :	FLOOR :	Ground			
No : 002/1/0/	025 USE :				
CODE : 5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair, although damaged in isolated areas	Replace damaged sections	B 4	15	20 m2	
					Year 1 Repair Cost (£) 200
CODE :5					Poplacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Fair	No Action Required	В	10	1 Nc	492
					Year 1 Repair Cost (£)
CODE :5					Denlessment
Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 20	Quantity 2 m2	Replacement Cost (£) 2 164
					Year 1 Repair Cost (£)
	No : 002/1/0/ CODE : 5 Condition Fair, although damaged in isolated areas CODE : 5 CODE : 5 CODE : 5 CODE : 5 CODE : 5	No : 002/1/0/025 USE : CODE : 5 Action Fair, although damaged in isolated areas Replace damaged sections CODE : 5 Action Condition Action Fair No Action Required CODE : 5 Action Action No Action Required	No : 002/1/0/025 USE : CODE :5 Action Cond/Ind Priority Fair, although damaged in isolated areas Action Cond/Ind Priority CODE :5 Action Cond/Ind Priority Condition Action Cond/Ind Priority Fair Action Cond/Ind Priority CODE :5 Action Required B CODE :5 Action Required Cond/Ind Priority Fair Action Required Cond/Ind Priority	No : 002/10/025 USE : CODE :5 Condition Priority L'Expec Fair, although damaged in isolated areas Replace damaged sections B 4 15 CODE :5 Condition Action Cond/Ind Priority L'Expec CODE :5 Action Cond/Ind Priority L'Expec Fair No Action Required B You have the section of the section o	No : 002/1/0/025 USE : CODE :5 Action Cond/Ind Priority L'Expec Quantity Fair, although damaged in isolated areas Replace damaged sections B 4 15 20 m2 CODE :5 Condition Action Cond/Ind Priority L'Expec Quantity Fair No Action Required B 10 1 No CODE :5 Condition Action Required B 10 1 No CODE :5 Condition Action Required B 10 1 No

BUILDING : Block 01 Kyd	UPRN :	FLOOR : G	round			
ROOM : Toilet	No : 002/1/0/02	6 USE :				
Element : Ceilings	CODE :5					Replacement
Description Lath & plaster ceiling	Condition Fair, although bossed and	Action Make good prior to redecoration	Cond/Ind Priority B 4	L'Expec 10	Quantity 12 m2	Cost (£) 656
	damaged in areas					Year 1 Repair Cost (£) 250
Element : Walls	CODE :5					Deplessment
Description Ceramic tiles to walls	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 30 m2	Replacement Cost (£) 2,460
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description Lath & plaster to walls	Condition Fair, with minor marks in isolated	Action Make good prior to redecoration	Cond/Ind Priority B 4	L'Expec 15	Quantity 20 m2	Cost (£) 1,093
	areas					Year 1 Repair Cost (£ 50
Element : Partitions	CODE :5					Replacement
Description Plaster on hard to partitions	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 40	Quantity 10 m2	Cost (£) 1,162
						Year 1 Repair Cost (£

Element : Windows	CODE : 5						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Timber windows to internal	Fair	No Action Required	В	10	1	m2	410
walls/partitions							Year 1
							Repair Cos
Element : Doors	CODE :5						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Softwood timber panelled door	Fair	No Action Required	В	10	-		656
							Year 1 Repair Cos
Element : Doors	CODE :5						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Softwood timber panelled top glazed	Fair	No Action Required	В	10	1	No	656
giazeu							Year 1 Repair Cos
Element : Floors	CODE :5						Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Tiled mosiac floor finish	Fair	No Action Required	В	10	12	m2	2,000
							Year 1
							Repair Cos

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind Pri	iority	L'Expec	Quant	ity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Poor, with flaking painterwork	Redecorate	D 4		Replace/In	42	m2	344
g								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	LOOR : First			
ROOM : Circulation Area	No : 002/1/ ²	1/001	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 25 m2	Cost (£) 854
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	35	65 m2	2,221
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	1 No	1,367
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	25 m2	1,025
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	90	m2	738 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First				
ROOM : Bathroom	No : 002/1/	/1/002	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Co	ond/Ind Priority B	L'Expec 35	Quantity 4 r	Cost (£) n2 136
							Year 1 Repair Cost (
Element : Walls	CODE :5						Deplessment
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required		В	35	10 r	m2 341
							Year 1 Repair Cost (
Element : Walls	CODE :5						Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required		В	28	9 r	m2 738
							Year 1 Repair Cost (
Element : Doors	CODE :5						Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required	Co	ond/Ind Priority B	L'Expec 23	Quantity	Replacement Cost (£) No 492
							Year 1 Repair Cost (

CODE :5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair, although loose at upstand	Refix vinyl sheet at upstand to hath	B 4	8	25 m2	1,025
	Jan				Year 1 Repair Cost (£) 50
CODE :5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair	No Action Required	В	3	14 m2	114
					Year 1 Repair Cost (£)
	Condition Fair, although loose at upstand CODE :5 Condition	ConditionActionFair, although loose at upstandRefix vinyl sheet at upstand to bathCODE :5ActionConditionAction	Condition Fair, although loose at upstandAction Refix vinyl sheet at upstand to bathCond/IndPriority BCODE :5ActionActionCond/Ind	Condition Fair, although loose at upstandAction Refix vinyl sheet at upstand to bathCond/IndPriority BL'Expec 8CODE :5ActionActionCond/IndFriorityL'Expec	Condition Fair, although loose at upstandAction Refix vinyl sheet at upstand to bathCond/IndPriority 8L'Expec 8Quantity 25m2CODE :5ActionActionCond/IndPriorityL'ExpecQuantityConditionActionCond/IndPriorityL'ExpecQuantity

BUILDING : Block 01 Kyd	UPRN :	FLOOR :	First			
ROOM : Boiler	No : 002/1/1/003	3 USE :				
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 9 m2	Cost (£) 307
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description Plasterboard walls	Condition Fair, although unfinished in corner area and cill	Action Make good plasterboard finish	Cond/Ind Priority B 4	L'Expec 35	Quantity 30 m2	Cost (£) 1,025
	area and cili					Year 1 Repair Cost (£) 350
Element : Floors	CODE :5					Replacement
Description Plywood sheeting	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 9 m2	Cost (£) 738
						Year 1 Repair Cost (£)
Element : Decoration	CODE :5					Donlocoment
Description Emulsion to ceiling and walls;	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec З	Quantity 29 m2	Replacement Cost (£) 237
gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : First			
ROOM : Bedroom 7	No : 002/1/	/1/004	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 16 m2	Cost (£) 546
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	33 m2	1,127
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	1 No	1,367
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 16 m2	Cost (£) 656
						Year 1 Repair Cost (£)

Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	49	m2	401 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First			
ROOM : Toilet 7	No : 002/1/	/1/005	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Pric	ority L'Expec 15	Quantity 4 m2	Cost (£) 136
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	7 m2	239
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Pric	ority L'Expec	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant 3	ity m2	Replacement Cost (£) 123
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quant	itv	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	13	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : First			
ROOM : Bedroom 6	No : 002/1/	/1/006	USE :			
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	15	16 m2	546
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	10 m2	546
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	23 m2	786
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	1 No	1,367
						Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant 16	i ity m2	Replacement Cost (£) 656
	i un			0	10	1112	Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	-i+v/	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	B	3	4 9	m2	401
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	-	FLOOR : First			
ROOM : Toilet 6	No : 002/1/	/1/007	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	2 L'Expec 15	Quantity 4 m2	Cost (£) 136
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	7 m2	239
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3	m2	123
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с Ехрес 3	Quant 15	m2	123
Emulsion to ceiling and walls; gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : First			
ROOM : Bedroom 5	No : 002/1/	/1/008	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priorit	/ L'Expec 15	Quantity 17 m2	Cost (£) 581
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Denlessment
Description	Condition	Action	Cond/Ind Priorit	/ L'Expec	Quantity	Replacement Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	6 m2	328
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priorit	/ L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	26 m2	888
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priorit	/ L'Expec	Quantity	Replacement Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	1 No	1,367
						Year 1 Repair Cost (£

Element : Floors Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	17	m2	697
							Year 1 Repair Cost (£)
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	49	m2	401
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First			
ROOM : Toilet	No : 002/1/	/1/009	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 15	Quantity 6 m2	Cost (£) 205
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	10 m2	341
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	8 m2	656
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Doplocoment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Replacement Cost (£)
Fair	No Action Required	В	8	5	m2	205
						Year 1 Repair Cost (£)
CODE :5	A officer			0	•••	Replacement
		•	•		•	Cost (£)
Fair	No Action Required	В	3	20	m2	164
						Year 1 Repair Cost (£)
	Condition Fair	Condition Action Fair No Action Required CODE :5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5ActionActionL'Expec bConditionActionCond/Ind PriorityL'Expec b	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quant 5CODE :5ActionActionCond/Ind PriorityL'ExpecQuantConditionActionCond/Ind PriorityL'ExpecQuant	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quantity 5m2CODE :5ActionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 01 Kyd	UPRN :	F	LOOR : First			
ROOM : Circulation Area	No : 002/1/	1/010	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Ceilings	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	15	2 m2	68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	20	22 m2	751
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Denlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	35	8 m2	273
						Year 1 Repair Cost (£)

Element : Walls	CODE : 5					Replaceme
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard finish	Fair	No Action Required	В	15	4 m2	136
						Year 1 Repair Cos
Element : Walls	CODE:5					Replacem
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	15	3 m2	102
						Year 1 Repair Co
Element : Doors	CODE:5					Replacem
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Co
Element : Doors	CODE:5					Replacem
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber panelled	Fair	No Action Required	В	23	1 No	656
						Year 1 Repair Co

Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber strip flooring/hardboard	Fair	No Action Required	В	10	3 m2	246
						Year 1 Repair Cost (
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	3 m2	123
						Year 1 Repair Cost (
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	35 m2	287
						Year 1 Repair Cost (/
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration	Fair	No Action Required	В	3	13 m2	106
Emulsion to ceiling and walls; gloss/varnish to timber finishes						Year 1 Repair Cost (

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First			
ROOM : Bedroom 4	No : 002/1/	/1/012	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priori B	ty L'Expec 15	Quantity 23 m2	Cost (£) 786
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priori	ty L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	42 m2	1,435
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priori	ty L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	1 No	1,367
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priori	ty L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	23 m2	943
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	65	m2	533 Year 1
							Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First			
ROOM : Toilet 4	No : 002/1/	/1/013	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 4 m2	Cost (£) 136
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	7 m2	239
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	3 m2	246
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 3 m	Replacement Cost (£) 2 123
				0	0 11	Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	13 m	

BUILDING : Block 01 Kyd	UPRN :	l	FLOOR : First			
ROOM : Circulation Area	No : 002/1/	1/014	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec 15	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Ceilings	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Cost (£)
Loft hatch	Fair	No Action Required	В	33	1 m2	54
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Cost (£)
Plasterboard finish	Fair	No Action Required	В	15	6 m2	205
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Cost (£)
Softwood timber panelled	Fair	No Action Required	В	23	1 No	656
						Year 1 Repair Cost (£

CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant i 3	i ty m2	Replacement Cost (£) 123
						Year 1 Repair Cost (£)
CODE : 5	Action	Cond/Ind Priority	l 'Expos	Quanti	i4.,	Replacement
		•	•		•	Cost (£) 106
Fdii	No Action Required	В	3	15	1112	100
						Year 1 Repair Cost (£)
_	Condition Fair	Condition Action Fair No Action Required CODE : 5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5ActionCond/Ind PriorityL'Expec 8	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quanti 3CODE : 5ActionActionCond/Ind PriorityL'ExpecQuanti 3	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quantity 3CODE :5ActionActionCond/Ind PriorityL'ExpecQuantityConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : First			
ROOM : Bedroom 3	No : 002/1/	/1/015	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	7 L'Expec 15	Quantity 24 m2	Cost (£) 820
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	44 m2	1,503
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	1 No	1,367
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	24 m2	984
						Year 1 Repair Cost (£)

Element : Decoration	ement : Decoration CODE : 5					Replacement	
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	70	m2	574 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First			
ROOM : Toilet 3	No : 002/1/	/1/016	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec 15	Quantity 4 m2	Cost (£) 136
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	7 m2	239
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	3 m2	246
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Prior B	ity L'Expec	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 3 m	Replacement Cost (£) 2 123
				0	0 11	Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	13 m	

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First			
ROOM : Circulation Area	No : 002/1/	1/017	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 15	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Ceilings	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Loft hatch	Fair	No Action Required	В	33	1 m2	54
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard finish	Fair	No Action Required	В	15	9 m2	307
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber panelled	Fair	No Action Required	В	23	1 No	656
						Year 1 Repair Cost (£)

CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant 3	i ty m2	Replacement Cost (£) 123
						Year 1 Repair Cost (£)
CODE : 5	Action	Cond/Ind Priority	L'Expos	Quant	4.,	Replacement
		•	•		•	Cost (£)
Fair	No Action Required	В	3	22	mz	180
						Year 1 Repair Cost (£)
-	Condition Fair	Condition Action Fair No Action Required CODE :5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionCond/Ind PriorityConditionActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5ActionCond/Ind PriorityL'Expec 8	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quanti 3CODE :5ActionActionCond/Ind PriorityL'ExpecQuanti 3	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quantity 3CODE :5ActionActionCond/Ind PriorityL'ExpecQuantityConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First					
ROOM : Bedroom 2	No : 002/1/	/1/018	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind B	Priority	L'Expec 15	Quantity 23	y m2	Cost (£) 786
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	y	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	-	15	42	m2	1,435
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	y	Cost (£)
1 hour fire door set	Fair	No Action Required	В	-	23	1	No	1,367
								Year 1 Repair Cost (£)
Element : Floors	CODE :5							Devlessment
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	y	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	-	8	23	m2	943
								Year 1 Repair Cost (£)

Element : Decoration	nt : Decoration CODE : 5					Replacement	
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	65	m2	533 Year 1
							Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : First			
ROOM : Toilet 2	No : 002/1/	/1/019	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	7 L'Expec 15	Quantity 4 m2	Cost (£) 136
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	7 m2	239
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	3 m2	246
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£

Element : Floors Description Vinyl sheet finish (non-slip)	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 3 m	Replacement Cost (£) 2 123
		No Fotor Required	_	C C	0 11	Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	13 m	

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : First			
ROOM : Circulation Area	No : 002/1/	/1/020	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priori B	ty L'Expec 15	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Ceilings	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priori	ty L'Expec	Quantity	Replacement Cost (£)
Loft hatch	Fair	No Action Required	В	33	1 m2	54
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priori	ty L'Expec	Quantity	Replacement Cost (£)
Plasterboard finish	Fair	No Action Required	В	15	6 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priori	ty L'Expec	Quantity	Replacement Cost (£)
Softwood timber panelled	Fair	No Action Required	В	23	1 No	656
						Year 1 Repair Cost (£)

CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant i 3	i ty m2	Replacement Cost (£) 123
						Year 1 Repair Cost (£)
CODE : 5	Action	Cond/Ind Priority	l 'Expos	Quanti	i4.,	Replacement
		•	•		•	Cost (£) 106
Fdii	No Action Required	В	3	15	1112	100
						Year 1 Repair Cost (£)
_	Condition Fair	Condition Action Fair No Action Required CODE : 5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5ActionCond/Ind PriorityL'Expec 8	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quanti 3CODE : 5ActionActionCond/Ind PriorityL'ExpecQuanti 3	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quantity 3CODE :5ActionActionCond/Ind PriorityL'ExpecQuantityConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : First			
ROOM : Bedroom 1	No : 002/1/	/1/021	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	2 L'Expec 15	Quantity 18 m2	Cost (£) 615
r lasterboard ceiling	i aii	No Action Required	D	15	10 1112	
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Lath & plaster to walls	Fair	No Action Required	В	15	22 m2	1,203
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	13 m2	444
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	1 No	1,367
						Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant 18	ity m2	Replacement Cost (£) 738
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	55	m2	451
Emulsion to ceiling and walls; gloss/varnish to timber finishes			_	C C			Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First			
ROOM : Toilet 1	No : 002/1/	/1/022	USE :			
Element : Ceilings	CODE :5					Replacement
Description Loft hatch	Condition Fair	Action No Action Required	Cond/Ind Pr B	riority L'Expec 33	Quantity 1 m2	Cost (£) 54
						Year 1 Repair Cost (£)
Element : Ceilings	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Pr	riority L'Expec	Quantity	Replacement Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	15	5 m2	170
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Pr	riority L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	15	13 m2	444
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Pr	riority L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	15	7 m2	239
						Year 1 Repair Cost (£)

Element : Walls	CODE :5					Replacement
Description Ceramic tiles to walls	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 28	Quantity 6 m2	Cost (£) 492
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Replacement
Description Vinyl sheet finish (non-slip)	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 5 m2	Cost (£) 205
						Year 1 Repair Cost (£)
Element : Decoration	CODE :5					Benlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	27 m2	221
gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : First			
ROOM : Circulation Area	No : 002/1/	/1/023	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priorit	y L'Expec 15	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	y L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	15	2 m2	68
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	y L'Expec	Quantity	Cost (£)
Softwood timber panelled	Fair	No Action Required	В	23	1 No	656
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Deplessment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	2 m2	82
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	12	m2	98 Year 1
							Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : G	round			
ROOM : Circulation Area	No : 002/2/0/0	001	USE :				
Element : Ceilings	CODE : 5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	ł	Cond/Ind Priority B	L'Expec 25	Quantity 13 m2	Cost (£) 444
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Danlagament
Description Plasterboard walls	Condition Fair	Action No Action Required	ł	Cond/Ind Priority B	L'Expec 25	Quantity 30 m2	Replacement Cost (£) 1,025
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Replacement
Description Carpet sheet finish, with colour	Condition Fair	Action No Action Required	ł	Cond/Ind Priority B	L'Expec 8	Quantity 13 m2	Cost (£) 600
contrasted non-slip nosings to steps .							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description Emulsion to ceiling and walls;	Condition Fair	Action No Action Required	4	Cond/Ind Priority B	L'Expec 3	Quantity 43 m2	Cost (£) 352
gloss/varnish to timber finishes	i all		4	D	5		352 Year 1 Repair Cost (£

BUILDING : Block 02 McKinney	UPRN :		FLOOR : G	round				
ROOM : Circulation Area	No : 002/2/0/	002	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard ceiling	Fair	No Action Required	l	В	25	25	m2	854
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	25	14	m2	478
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	25	64	m2	2,187
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
1 hour fire door set	Fair	No Action Required	I	В	23	1	No	1,367
								Year 1 Repair Cost (£)

Element : Floors Description Carpet sheet finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 25	y m2	Replacement Cost (£) 1,025
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	v	Replacement Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	103	m2	844 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : G	round				
ROOM : Store	No : 002/2/0/	003	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 25	Quantity 2	m2	Cost (£) 68
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Doulocomout
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	25	6	m2	205
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required	l	В	25	6	m2	205
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Doulocomout
Description 1 hour fire door set	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 23	Quantity 2	No	Replacement Cost (£) 2,734
								Year 1 Repair Cost (£

Element : Floors Description Unpainted Concrete	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 40	Quantity 2 m2	Replacement Cost (£) 136
						Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement
•			•	-	•	Cost (£)
Re-decoration	Still to be decorated	Decorate	D 4	Replace/In	16 m2	131
						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : G	round				
ROOM : Toilet	No : 002/2/0/	/004	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 25	Quantity 3	m2	Cost (£) 102
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Doplacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	l	В	28	18	m2	1,476
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Softwood timber flush	Fair	No Action Required	l	В	23	1	No	492
								Year 1 Repair Cost (£)
Element : Floors	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Quarry tiled floor	Fair	No Action Required	I	В	28	-	m2	246
								Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quar	tity	Cost (£)
Emulsion to ceiling; gloss/varnish to timber finishes	Fair	No Action Required	В	3	3	m2	24
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Toilet	UPRN : No : 002/2/0		FLOOR : Groun USE :	ld			
Element : Ceilings	CODE :5						
Description Suspended grid system with fibreboard tiles	Condition Fair	Action No Action Required	Co	ond/Ind Priority B	L'Expec 18	Quantity 9 m2	ReplacementCost (£)2307
							Year 1 Repair Cost (£
Element : Walls	CODE : 5						Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required		В	28	29 m2	2 2,378
							Year 1 Repair Cost (£
Element : Walls	CODE:5						Replacement
Description Pre-finished board	Condition Fair	Action No Action Required	Co	ond/Ind Priority B	L'Expec 23	Quantity 3 m2	Cost (£)
							Year 1 Repair Cost (£
Element : Partitions	CODE:5						Replacement
Description Timber laminate partition	Condition Fair	Action No Action Required	Co	ond/Ind Priority B	L'Expec 23	Quantity 2 m2	Cost (£)
							Year 1 Repair Cost (£)

Element : Windows	CODE :5					Replacemen
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
PVC-u windows to internal	Fair	No Action Required	В	38	2 m2	820
walls/partitions						Year 1
						Repair Cost
Element : Doors	CODE :5					Replacemen
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1
						Repair Cost
Element : Floors	CODE : 5					Replacemer
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Quarry tiled floor	Fair	No Action Required	В	28	19 m2	1,558
						Year 1 Repair Cost
Element : Decoration	CODE :5					Replacemer
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Gloss/varnish to timber finishes	Fair	No Action Required	В	3	2 m2	16
only						Year 1 Repair Cost

BUILDING : Block 02 McKinney	UPRN :	FLOOR : G	round			
ROOM : Store	No : 002/2/0/00	06 USE :				
Element : Ceilings	CODE : 5					Replacement
Description Plaster ceiling	Condition Fair, with slight cracking in isolated areas	Action Make good prior to redecoration	Cond/Ind Priority B 4	L'Expec 25	Quantity 2 m2	Cost (£) 68
	isolaleu areas					Year 1 Repair Cost (£) 50
Element : Walls	CODE :5					Replacement
Description Plaster on hard to walls	Condition Fair, although slight cracking is	Action Make good prior to redecoration	Cond/Ind Priority B 4	L'Expec 25	Quantity 12 m2	Cost (£) 410
	evident in areas					Year 1 Repair Cost (£) 50
Element : Doors	CODE :5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description Unpainted Concrete	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 40	Quantity 2 m2	Cost (£) 136
						Year 1 Repair Cost (£)

Element : Decoration	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration	Poor	Redecorate	D 4	Replace/In	12 m2	98
						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	FLOOR : G	round			
ROOM : Plant Room	No : 002/2/0/00	7 USE :				
Element : Ceilings Description Plasterboard ceiling	CODE : 5 Condition Fair, although 'AmesTaping'	Action Make good prior to redecoration	Cond/Ind Priority B 4	L'Expec 25	Quantity 14 m2	Replacement Cost (£) 478
	required in areas					Year 1 Repair Cost (£ 150
Element : Walls	CODE :5					Replacement
Description Brick pointed finish (painted)	Condition Fair, although repointing required	Action Make good prior to redecoration	Cond/Ind Priority B 4	L'Expec 18	Quantity 70 m2	Cost (£) 1,913
	in areas					Year 1 Repair Cost (£ 200
Element : Doors	CODE:5					Replacement
Description 1 hour fire door set	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 1,367
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Replacement
Description Unpainted Concrete	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 40	Quantity 14 m2	Cost (£) 956
						Year 1 Repair Cost (£

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind Pri	iority	L'Expec	Quanti	ty	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Poor	Redecorate	D 4		Replace/In	84	m2	689
g								Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Ground			
ROOM : Circulation Area	No : 002/2/0	/008	USE :			
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	25	3 m2	102
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Poplacement
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	12 m2	984
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Donlocomont
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Replacement Cost (£)
Quarry tiled floor	Fair	No Action Required	В	28	3 m2	246
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quar	tity	Cost (£)
Emulsion to ceiling; gloss/varnish to timber finishes	Fair	No Action Required	В	3	3	m2	24
							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Ground			
ROOM : Circulation Area	No : 002/2/0)/009	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 25	Quantity 10 m2	Cost (£) 341
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority		Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	25	14 m2	478
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	25	11 m2	375
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Donlocoment
Description Carpet sheet finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 10 m2	Replacement Cost (£) 410
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	35	m2	287 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : G	round				
ROOM : Bedroom 8	No : 002/2/0/	/010	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	ł	В	33	14	m2	478
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Doplocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	ł	В	38	20	m2	683
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required	ł	В	33	8	m2	273
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description 1 hour fire door set	Condition Fair	Action No Action Required	ł	Cond/Ind Priority B	L'Expec 23	Quantity	, No	Cost (£) 1,367
								Year 1 Repair Cost (£)

CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant 14	t ity m2	Replacement Cost (£) 574
						Year 1 Repair Cost (£)
CODE : 5	Action	Cond/Ind Priority	L'Expos	Quant	+i4. <i>,</i>	Replacement
		•	•		•	Cost (£) 377
Fall	No Action Required	Б	3	40	1112	511
						Year 1 Repair Cost (£)
	Condition Fair	Condition Action Fair No Action Required CODE :5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionActionConditionActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5ActionActionL'expec bConditionActionCond/Ind PriorityL'expec b	Condition Action Cond/Ind Priority L'Expec Quant Fair No Action Required B 8 14 CODE :5 Action Cond/Ind Priority L'Expec Quant Condition Action Cond/Ind Priority L'Expec Quant	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quantity 14CODE :5ActionActionCond/Ind PriorityL'ExpecQuantityConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 02 McKinney	UPRN :		FLOOR : G	round			
ROOM : Toilet 8	No : 002/2/0/0)11	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 33	Quantity 3 r	Cost (£) n2 102
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	I	В	28	9 r	m2 738
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	I	В	38	7 r	m2 478
							Year 1 Repair Cost (£
Element : Doors	CODE:5						Danlagement
Description Softwood timber flush	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 23	Quantity	Replacement Cost (£) No 492
							Year 1 Repair Cost (£

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : G	round				
ROOM : Bedroom 9	No : 002/2/0	/012	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 33	Quantity 14	/ m2	Cost (£) 478
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	20	m2	683
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Denlegement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	8	m2	273
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Devlessment
Description 1 hour fire door set	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 23	Quantity 1	No	Replacement Cost (£) 1,367
								Year 1 Repair Cost (£)

CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant 14	t ity m2	Replacement Cost (£) 574
						Year 1 Repair Cost (£)
CODE : 5	Action	Cond/Ind Priority	L'Expos	Quant	+i4. <i>,</i>	Replacement
		•	•		•	Cost (£) 377
Fall	No Action Required	Б	3	40	1112	511
						Year 1 Repair Cost (£)
	Condition Fair	Condition Action Fair No Action Required CODE :5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionActionConditionActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5ActionActionL'expec bConditionActionCond/Ind PriorityL'expec b	Condition Action Cond/Ind Priority L'Expec Quant Fair No Action Required B 8 14 CODE :5 Action Cond/Ind Priority L'Expec Quant Condition Action Cond/Ind Priority L'Expec Quant	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quantity 14CODE :5ActionActionCond/Ind PriorityL'ExpecQuantityConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Gr	ound				
ROOM : Toilet 9	No : 002/2/0	0/013	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 33	Quantity 3	m2	Cost (£) 102
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required		В	28	9	m2	738
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Pre-finished board	Fair	No Action Required		В	38	7	m2	478
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 23	Quantity 1	No	Replacement Cost (£) 492
								Year 1 Repair Cost (£

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN UPRN	:	FLOOR : Ground					
ROOM : Circulation Area/St	airs No	: 002/2/0/014	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Require	Cond/Ind ed B	Priority	L'Expec 25	Quantity 48	/ m2	Cost (£) 1,640
								Year 1 Repair Cost (£
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Cost (£)
Suspended grid system with	Fair	No Action Require	ed B		18	20	m2	683
fibreboard tiles								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Require	ed B	-	25	11	m2	375
								Year 1 Repair Cost (£
Element : Walls	CODE : 5							Replacement
Description Plaster on hard to walls	Condition Fair	Action No Action Require	Cond/Ind ed B	Priority	L'Expec 25	Quantity 154	/ m2	Cost (£) 5,263
								Year 1 Repair Cost (£

Element : Doors	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	5 No	6,835
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Carpet sheet finish, with colour contrasted non-slip nosings to	Fair	No Action Required	В	8	65 m2	2,800
steps .						Year 1 Repair Cost (£
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	213 m2	1,747
						Year 1 Repair Cost (£

BUILDING : Block 02 McKinney	UPRN :	FLOOR : G	round			
ROOM : Circulation Area/Stain	rs No : 002/2/0/01	5 USE :				
Element : Walls	CODE : 5					Replacement
Description Plaster on hard to walls	Condition Fair, with minor marks in isolated	Action Make good prior to redecoration	Cond/Ind Priority B	L'Expec 25	Quantity 9 m2	Cost (£) 307
	areas					Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 10	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Replacement
Description Vinyl sheet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 4	Quantity 4 m2	Cost (£) 164
						Year 1 Repair Cost (£
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	1	15 m2	123
						Year 1 Repair Cost (£

BUILDING : Block 02 McKinney	UPRN :	FLOOR : G	round			
ROOM : Grampian Lounge	No : 002/2/0/0	16 USE :				
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair, although slight cracking	Action Make good prior to redecoration	Cond/Ind Priority B 4	L'Expec 25	Quantity 102 m2	Cost (£) 3,486
	noted in isolated areas					Year 1 Repair Cost (£ 50
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	25	92 m2	3,144
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Replacement
Description Plasterboard walls	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 25	Quantity 10 m2	Cost (£) 341
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 492
						Year 1 Repair Cost (£

Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit 27	-	Cost (£)
Timber laminate floor	Fair	No Action Required	В	8	27	m2	2,214
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Carpet sheet finish	Fair	No Action Required	В	8	75	m2	3,075
							Year 1 Repair Cost (£
Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Emulsion to ceiling, decorative paper to walls; gloss to timber	Fair	No Action Required	В	3	204	m2	1,673
finishes							Year 1 Repair Cost (£

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First				
ROOM : Circulation Area	No : 002/2/1/0	001	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required		ond/Ind Priority B	L'Expec 33	Quantity 17 m2	Cost (£)
							Year 1 Repair Cost (£
Element : Ceilings	CODE:5						Devlessment
Description	Condition	Action	C	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Loft hatch	Fair	No Action Required		В	33	1 m2	.,
							Year 1 Repair Cost (£
Element : Walls	CODE:5						Replacement
Description	Condition	Action	C	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	33	8 m2	273
							Year 1 Repair Cost (£
Element : Walls	CODE:5						Devlessment
Description	Condition	Action	C	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Timber panelling to walls	Fair	No Action Required		В	38	6 m2	.,
							Year 1 Repair Cost (£

Condition Fair CODE : 5 Condition Fair	Action No Action Required Action	Cond/Ind Priority B	L'Expec 33	Quantity 33 m2	Replacement Cost (£) 1,127 Year 1 Repair Cost (£)
CODE : 5 Condition			33	33 m2	Year 1 Repair Cost (£
Condition	Action				Repair Cost (£
Condition	Action				
	Action				Replacement
Fair		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
	No Action Required	В	38	3 m2	1,230
					Year 1 Repair Cost (£)
CODE:5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair	No Action Required	В	23	1 No	1,367
					Year 1 Repair Cost (£)
CODE:5					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Fair	No Action Required	В	8	17 m2	697
					Year 1 Repair Cost (£)
	CODE : 5 Condition Fair CODE : 5 Condition	CODE : 5 Condition Action Fair No Action Required CODE : 5 Condition Action	CODE :5 Action Cond/Ind Priority Fair No Action Required B CODE :5 Action Cond/Ind Priority CODE :5 Action Cond/Ind Priority	CODE :5 Action Cond/Ind Priority L'Expec Fair No Action Required B 23 CODE :5 Condition Action Cond/Ind Priority L'Expec CODE :5 Action Cond/Ind Priority L'Expec	CODE :5 Condition Action Cond/Ind Priority L'Expec Quantity Fair No Action Required B 23 1 No CODE :5 Condition Action Cond/Ind Priority L'Expec Quantity Condition Action Cond/Ind Priority L'Expec Quantity

Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	80	m2	656 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First					
ROOM : Circulation Area	No : 002/2	2/1/001A	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action	Cond/Ir	nd Priority	L'Expec	Quantity	у	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В		33	10	m2	341
								Year 1 Repair Cost (£
Element : Walls	CODE : 5							Replacement
Description	Condition	Action	Cond/Ir	nd Priority	L'Expec	Quantity	y	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	-	38	42	m2	1,435
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Replacement
Description	Condition	Action	Cond/Ir	nd Priority	L'Expec	Quantity	у	Cost (£)
1 hour fire door set	Fair	No Action Required	В		23	1	No	1,367
								Year 1 Repair Cost (£)
Element : Floors	CODE : 5							Denlessment
Description	Condition	Action	Cond/Ir	nd Priority	L'Expec	Quantity	у	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required		-	8	10	m2	410
								Year 1 Repair Cost (£)

Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	64	m2	524 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	st				
ROOM : Bedroom 22	No : 002/2/1	/002	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	1	Cond/Ind Priority B	L'Expec 33	Quantity	/ m2	Cost (£) 375
Flasterboard celling	Fall	NO ACION REQUIRED	Į	D	33	11	ΠZ	
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	38	8	m2	273
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required	i	В	33	20	m2	683
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
1 hour fire door set	Fair	No Action Required	I	В	23	-	No	1,367
								Year 1 Repair Cost (£)

CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant 11	ity m2	Replacement Cost (£) 451
						Year 1 Repair Cost (£)
CODE : 5	Action	Cond/Ind Briority	L'Expos	Quant	i4	Replacement
		•	•		•	Cost (£) 352
Fall	No Action Required	D	3	43	ΠZ	552
						Year 1 Repair Cost (£)
	Condition Fair	Condition Action Fair No Action Required CODE :5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionActionConditionActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5ActionActionCond/Ind PriorityL'Expec 8	Condition Action Cond/Ind Priority L'Expec Quant Fair No Action Required B 8 11 CODE :5 Action Cond/Ind Priority L'Expec Quant Condition Action Cond/Ind Priority L'Expec Quant	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quantity 11CODE :5ActionActionCond/Ind PriorityL'ExpecQuantityConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fin	rst				
ROOM : Toilet 22	No : 002/2/1	/003	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	ł	Cond/Ind Priority B	L'Expec 33	Quantity 4	m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	ł	В	28	4	m2	328
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard walls	Fair	No Action Required	ł	В	38	7	m2	239
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required	i	Cond/Ind Priority B	L'Expec 23	Quantity 1	No	Replacement Cost (£) 492
								Year 1 Repair Cost (£

CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quanti 3	ty m2	Replacement Cost (£) 82
						Year 1 Repair Cost (£)
CODE : 5	Action	Cond/Ind Priority	l 'Expec	Quanti	tv	Replacement Cost (£)
Fair	No Action Required	B	3	13	m2	106
	Condition Fair CODE : 5 Condition	Condition Action Fair No Action Required CODE :5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8CODE :5ActionActionL'Expec bConditionActionCond/Ind PriorityL'Expec b	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quanti 3CODE :5ActionActionCond/Ind PriorityL'ExpecQuanti Quanti	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 8Quantity 3m2CODE :5ActionActionCond/Ind PriorityL'ExpecQuantityConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	st				
ROOM : Circulation Area 21	No : 002/2/1/	/004	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard ceiling	Fair	No Action Required	l	В	33	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard walls	Fair	No Action Required	l	В	33	4	m2	136
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
1 hour fire door set	Fair	No Action Required	l	В	23	1	No	1,367
								Year 1 Repair Cost (£
Element : Floors	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Carpet floor finish	Fair	No Action Required	l	В	8	2	m2	82
								Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	12	m2	98 Year 1
							Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First				
ROOM : Bedroom 21	No : 002/2/	/1/005	USE :				
Element : Ceilings	CODE : 5						Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	33	13 n	n2 444
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	35 n	n2 1,196
							Year 1 Repair Cost (£)
Element : Doors	CODE :5						Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required		В	23	1 N	lo 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Donlocoment
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required		В	8	13 n	n2 533
							Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	52	m2	426 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	st				
ROOM : Toilet 21	No : 002/2/1	/006	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 33	Quantity 4	/ m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	I	В	28	5	m2	410
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard walls	Fair	No Action Required	l	В	33	6	m2	205
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	I	В	23	-	No	492
								Year 1 Repair Cost (£)

Element : Floors Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3 m2	123 Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	12 m2	98 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	st				
ROOM : Living Room 21	No : 002/2/1/	/007	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	l	В	33	16	m2	546
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required	l	В	33	37	m2	1,264
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Softwood timber flush	Fair	No Action Required	l	В	23	1	No	492
								Year 1 Repair Cost (£
Element : Floors	CODE : 5							Doplocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	l	В	8	16	m2	656
								Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	55	m2	451 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	I	FLOOR : First				
ROOM : Store 21	No : 002/2/	1/008	USE :				
Element : Ceilings	CODE :5						Replacement
Description	Condition	Action	С	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	33	1 r	n2 34
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Deplessment
Description	Condition	Action	c	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	7 r	n2 239
							Year 1 Repair Cost (£
Element : Doors	CODE :5						Replacement
Description	Condition	Action	C	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required		В	23	2 N	lo 984
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Replacement
Description	Condition	Action	С	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required		В	8	1 r	n2 41
							Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	12	m2	98 Year 1
							Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	FL	.OOR : First			
ROOM : Circulation Area 20	No : 002/2	/1/009	USE :			
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	33	6 m2	205
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	33	20 m2	683
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	В	23	1 No	1,367
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	6 m2	82
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	34	m2	278 Year 1
							Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Firs	t			
ROOM : Bedroom 20	No : 002/2/	1/010	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	(Cond/Ind Priority B	L'Expec 33	Quantity 9 m	Cost (£) 12 307
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	31 m	
							Year 1 Repair Cost (£)
Element : Doors	CODE:5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required		В	23	1 N	lo 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required		В	8	9 m	
							Year 1 Repair Cost (£)

Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	42	m2	344 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First	st				
ROOM : Toilet 20	No : 002/2/1/0)11	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	1	Cond/Ind Priority B	L'Expec 33	Quantity 4	, m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	1	В	28	•	m2	410
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	1	В	33	6	m2	205
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Softwood timber flush	Fair	No Action Required		В	23	1	No	492
								Year 1 Repair Cost (£

Element : Floors Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3 m2	123 Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	12 m2	98 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	F	FLOOR : First			
ROOM : Living Room 20	No : 002/2/	/1/012	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 19 m2	Cost (£) 649
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	33	40 m2	1,367
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	19 m2	779
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	61	m2	500 Year 1
globs variable to amber minories							Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	st				
ROOM : Circulation Area 19	No : 002/2/1/	/014	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	I	В	33	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	33	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	2	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
1 hour fire door set	Fair	No Action Required	I	В	23	-	No	1,367
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 2 m	Replacement Cost (£) 2 82
						Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Ourartitu	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	14 m	2 656
gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	rst				
ROOM : Bedroom 19	No : 002/2/1	/015	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	I	В	33	8	m2	273
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	33	•	m2	341
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Banlagament
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	38	10	m2	341
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	I	В	23	1	No	492
								Year 1 Repair Cost (£)

Element : Floors Description Carpet floor finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant i 8	ity m2	Replacement Cost (£) 328
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action	Cond/Ind Driverity	LIEvnoo	Quent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	•	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	30	m2	344
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	st			
ROOM : Toilet 19	No : 002/2/ ⁻	1/016	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 33	Quantity 4 r	Cost (£) n2 136
							Year 1 Repair Cost (£
Element : Walls	CODE:5						Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	l	В	28	5 r	m2 410
							Year 1 Repair Cost (£
Element : Walls	CODE:5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	33	6 r	m2 205
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	38	-	m2 102
							Year 1 Repair Cost (£

Element : Doors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1	No	492
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3	m2	123
							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	15	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 02 McKinney ROOM : Living Room 19	UPRN : No : 002/2/1/01		FLOOR : Fir USE :	st			
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair, although slightly marked in areas	Action No Action Required		Cond/Ind Priority B	L'Expec 33	Quantity 10 m2	Cost (£) 341
	aleas						Year 1 Repair Cost (£
Element : Walls	CODE : 5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	8 m2	273
							Year 1 Repair Cost (£
Element : Walls	CODE:5						Replacement
Description Plaster on hard to walls	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 38	Quantity 20 m2	Cost (£) 683
							Year 1 Repair Cost (£
Element : Doors	CODE:5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 492
							Year 1 Repair Cost (£

Element : Floors Description	CODE:5 Condition	Action	Cond/Ind Prio	ity L'Exp	Quant	ity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	B	8	Quan 10	m2	410
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Prio	ity L'Exp	Quant	ity	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair, although minor repairs required	Ceiling to be decorated	B 4	3	38	m2	311
gloss/varnish to timber finishes	Decorate ceiling						Year 1

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First	st				
ROOM : Circulation Area 18	No : 002/2/1	1/018	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	33	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	33	2	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
1 hour fire door set	Fair	No Action Required		В	23	1	No	1,367
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 2 m	Replacement Cost (£) 2 82
						Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Ourartitu	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	14 m	2 656
gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fi	rst				
ROOM : Bedroom 18	No : 002/2/1/	/019	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	Ł	В	33	8	m2	273
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	k	В	33	10	m2	341
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	Ł	В	38	10	m2	341
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	k	В	23	-	No	492
								Year 1 Repair Cost (£)

Element : Floors Description Carpet floor finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant i 8	ity m2	Replacement Cost (£) 328
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action	Cond/Ind Driverity	LIEvnoo	Quent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	•	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	30	m2	344
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First	st				
ROOM : Toilet 18	No : 002/2/ ²	1/020	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 33	Quantity 4	(Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required		В	28	5 i		410
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	6 1	m2 2	205
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	•		102
								Year 1 Repair Cost (£

Element : Doors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1	No	492
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3	m2	123
							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	15	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Firs	st			
ROOM : Living Room 18	No : 002/2/1/0	21	USE :				
Element : Ceilings	CODE :5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	33	10 m	12 341
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	-	12 273
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	20 m	12 683
							Year 1 Repair Cost (£
Element : Doors	CODE:5						Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required		В	23	1 N	
							Year 1 Repair Cost (£

Element : Floors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	10	m2	410
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quanti	tv	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	B 4	3	38	m2	311
gloss/varnish to timber finishes							Year 1 Repair Cost (£) 80

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fin	rst				
ROOM : Circulation Area 24	No : 002/2/1/0	023	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard ceiling	Fair	No Action Required	ł	В	33	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	k	В	33	2	m2	68
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plaster on hard to walls	Fair	No Action Required	ł	В	33	2	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
1 hour fire door set	Fair	No Action Required	ł	В	23	1	No	1,367
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 2 m	Replacement Cost (£) 2 82
						Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Ourartitu	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	14 m	2 656
gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First					
ROOM : Bedroom 24	No : 002/2/1/0	024	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action	c	Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	I	В	33	8	m2	273
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Donlocoment
Description	Condition	Action	C	Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	•	m2	341
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Replacement
Description	Condition	Action	C	Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	38	10	m2	341
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Denlessment
Description	Condition	Action	C	cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	I	В	23	-	No	492
								Year 1 Repair Cost (£)

Element : Floors Description Carpet floor finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant i 8	ity m2	Replacement Cost (£) 328
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action	Cond/Ind Driverity	LIEvnoo	Quent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	•	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	30	m2	344
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First	st				
ROOM : Toilet 24	No : 002/2/ ²	1/025	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 33	Quantity 4	, m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Benlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required		В	28	5	m2	410
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	3	m2	102
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	-	m2	205
								Year 1 Repair Cost (£)

Element : Doors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1	No	492
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3	m2	123
							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	15	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	st				
ROOM : Living Room 24	No : 002/2/1	/026	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	l	В	33	10	m2	341
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	33	•	m2	273
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	l	В	38	20	m2	683
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	l	В	23	1	No	492
								Year 1 Repair Cost (£)

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quant 10	ity m2	Replacement Cost (£) 410
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			0		Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	-	Cost (£)
Re-decoration	Fair	No Action Required	В	3	38	m2	311
Emulsion to ceiling and walls; gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : First					
ROOM : Bedroom 23	No : 002/2/1/02	27	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	33	10	m2	341
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Damlaaamant
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	•	m2	512
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	10	m2	341
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Devlessment
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
1 hour fire door set	Fair	No Action Required		В	23	•	No	1,367
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quanti 10	ty m2	Replacement Cost (£) 451
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	29	m2	237
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Fir	st			
ROOM : Toilet 23	No : 002/2/ ⁻	1/028	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 33	Quantity 4 n	Cost (£) n2 136
							Year 1 Repair Cost (£
Element : Walls	CODE:5						Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required		В	28	•	n2 410
							Year 1 Repair Cost (£
Element : Walls	CODE:5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required		В	38	7 n	n2 239
							Year 1 Repair Cost (£)
Element : Walls	CODE:5						Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	•	n2 68
							Year 1 Repair Cost (£)

Element : Doors Description Softwood timber flush	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quant 1	ity No	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3	m2	82
							Year 1 Repair Cost (£)
Element : Decoration	CODE :5						Bonlooomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	itv	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	15	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhous			DR : Ground				
ROOM : Circulation Area/	Stairs No: 002	/3/0/001 U	SE :				
Element : Ceilings	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	25	18	m2	615
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	25	46	m2	1,572
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required	В	25	33	m2	1,127
							Year 1 Repair Cost (£
Element : Doors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	18	1	No	1,025
							Year 1 Repair Cost (£

Element : Doors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	ty	Cost (£)
1 hour fire door set	Fair	No Action Required	В	18	2	No	2,734
							Year 1 Repair Cost (£
Element : Floors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	t y	Cost (£)
Carpet sheet finish, with colour contrasted non-slip nosings to	Fair	No Action Required	В	5	18	m2	850
steps.							Year 1 Repair Cost (£)
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	t y	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	2	97	m2	795
							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : G	round			
ROOM : Store	No : 002/3/0/	004	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	ł	Cond/Ind Priority B	L'Expec 28	Quantity 2 m	Cost (£)
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	1	В	28	6 m	2 205
							Year 1 Repair Cost (£
Element : Doors	CODE :5						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Required	1	В	18	1 N	o 1,367
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet floor finish	Fair	No Action Required	ł	В	3	2 m	
							Year 1 Repair Cost (£

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	10	m2	82
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : G	ound				
ROOM : Store	No : 002/3/0	/005	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 28	Quantity 2	m2	Cost (£) 68
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	28	6	m2	205
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
1 hour fire door set	Fair	No Action Required	l	В	18	1	No	1,367
								Year 1 Repair Cost (£
Element : Floors	CODE :5							Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Vinyl sheet floor finish	Fair	No Action Required	I	В	3	2	m2	82
								Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	10	m2	82
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Ground			
ROOM : Circulation Area	No : 002/3/0	0/006	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority	L'Expec 28	Quantity 10 m2	Cost (£) 341
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I B	33	34 m2	1,162
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required	I B	3	10 m2	410
						Year 1 Repair Cost (£)
Element : Decoration	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration	Fair	No Action Required	I B	2	56 m2	459
Emulsion to ceiling and walls; gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Ground			
ROOM : Bedroom 12A	No : 002/3/0/00	07	USE :			
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	28	12 m2	410
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Donlocoment
Description	Condition	Action	Cond/Ind Prie	ority L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		33	24 m2	820
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prie	ority L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	28	8 m2	273
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Donlocoment
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required		18	1 No	492
						Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	ty m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	48	m2	393
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Gr	ound				
ROOM : Toilet 12A	No : 002/3/0	/008	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 28	Quantity 4	/ m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	28	8	m2	273
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	2	m2	68
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	l	В	23	-	m2	82
								Year 1 Repair Cost (£

Element : Doors	CODE :5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quantit 1	y No	Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	V	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	3	3	m2	123
							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	15	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Grou	und				
ROOM : Bedroom 12	No : 002/3/0	/009	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action	(Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	28	12	m2	410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocoment
Description	Condition	Action	C	Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	33	24	m2	820
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action	C	Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard walls	Fair	No Action Required		В	28	8	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Donlocoment
Description	Condition	Action	C	Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required		В	18	1	No	492
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	ty m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	48	m2	393
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Ground					
ROOM : Toilet 12	No : 002/3/0	0/010	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind P B	•	L 'Expec 28	Quantity 4	, m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Devlessment
Description	Condition	Action	Cond/Ind P	Priority I	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В		28	8	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Replacement
Description	Condition	Action	Cond/Ind P	Priority I	L'Expec	Quantity	,	Cost (£)
Softwood timber flush	Fair	No Action Required	В		18	1	No	492
								Year 1 Repair Cost (£
Element : Floors	CODE:5							Devlessment
Description	Condition	Action	Cond/Ind P	Priority I	L'Expec	Quantity	,	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	-	3	-	m2	123
								Year 1 Repair Cost (£

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	2	14	m2	114 Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Ground			
ROOM : Bedroom 11	No : 002/3/0/0	11	USE :			
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	B	28	12 m2	410
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		33	24 m2	820
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	I B	28	8 m2	273
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Donlocoment
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Quantity	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	В	18	1 No	492
						Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	ty m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	48	m2	393
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Ground					
ROOM : Toilet 11	No : 002/3/0)/012	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind B	Priority	L'Expec 28	Quantity 4	/ m2	Cost (£) 136
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	-	28	8	m2	273
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	/	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	-	23	1	m2	82
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description Softwood timber flush	Condition Fair	Action	Cond/Ind B	Priority	L'Expec 18	Quantity	/ No	Cost (£) 492
	Fall	No Action Required	В		10	I	INU	
								Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quan 3	tity m2	Replacement Cost (£) 123
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	2	13	m2	114
Emulsion to ceiling and walls;			_	-			

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : G	round				
ROOM : Bedroom 10	No : 002/3/0/	013	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard ceiling	Fair	No Action Required	1	В	28	12	m2	410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	ł	В	33	24	m2	820
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard walls	Fair	No Action Required	ł	В	28	8	m2	273
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Donlocomont
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	ł	В	18	1	No	492
								Year 1 Repair Cost (£)

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	ty m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	48	m2	393
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : G	round				
ROOM : Toilet 10	No : 002/3/0/	014	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	ł	Cond/Ind Priority B	L'Expec 28	Quantity 4	m2	Cost (£) 136
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Denlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	ł	В	28	•	m2	273
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	ł	В	33	2	m2	68
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	ł	В	23	-	m2	82
								Year 1 Repair Cost (£)

Element : Doors	CODE :5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quantit 1	y No	Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	V	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	3	3	m2	123
							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	15	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Gr	ound				
ROOM : HWC Tank room	No : 002/3/0/	015	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	l	В	28	3	m2	102
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	10	m2	341
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
1 hour fire door set	Fair	No Action Required	l	В	18	1	No	1,367
								Year 1 Repair Cost (£
Element : Floors	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Unpainted Concrete	Fair	No Action Required	I	В	33	-	m2	205
								Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : First	st				
ROOM : Circulation Area	No : 002/3/1/0	01	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 28	Quantity 20	m2	Cost (£) 683
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	33	66	m2	2,392
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard walls	Fair	No Action Required		В	28	4	m2	136
								Year 1 Repair Cost (£
Element : Floors	CODE :5							Deplessment
Description Carpet floor finish	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 3	Quantity 20	m2	Replacement Cost (£) 820
				J	5	20	1112	
								Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	2	108	m2	885 Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fir	st				
ROOM : Bathroom	No : 002/3/1/	/002	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition Fair	Action		Cond/Ind Priority B	L'Expec 28	Quantity 7	m2	Cost (£) 239
Plasterboard ceiling	Fall	No Action Required	1	D	20	/	ΠZ	
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	8	m2	273
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	28	10	m2	341
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Ceramic tiles to walls	Fair	No Action Required	I	В	23	1	m2	82
								Year 1 Repair Cost (£

Element : Doors	CODE :5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quantit 1	y No	Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	V	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	3	7	m2	287
							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	27	m2	221
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fir	st				
ROOM : Bedroom 17	No : 002/3/1/	003	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	28	12	m2	410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	33	•	m2	820
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required		В	28	8	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required		В	18	1	No	492
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	ty m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	48	m2	393
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fir	st				
ROOM : Toilet 17	No : 002/3/1/	/004	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 28	Quantity 4	, m2	Cost (£) 136
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	28	8	m2	273
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	2	m2	68
								Year 1 Repair Cost (£)
Element : Walls	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	I	В	23	-	m2	82
								Year 1 Repair Cost (£

Element : Doors	CODE : 5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quantit 1	y No	Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	V	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	3	3	m2	123
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5						Bonlooomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	16	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fir	st				
ROOM : Bedroom 16	No : 002/3/1/	005	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard ceiling	Fair	No Action Required	I	В	28	12	m2	410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	•	m2	820
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	28	8	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	I	В	18	1	No	492
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	ty m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	48	m2	393
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fir	st				
ROOM : Toilet 16	No : 002/3/1	/006	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 28	Quantity 4	, m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	28	8	m2	273
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	I	В	23	-	m2	82
								Year 1 Repair Cost (£

Element : Doors	CODE : 5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quantit 1	y No	Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	V	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	3	3	m2	123
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5						Bonlooomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	16	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fin	rst				
ROOM : Store	No : 002/3/1/	/007	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard ceiling	Fair	No Action Required	ł	В	28	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Doplocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	ł	В	28	6	m2	205
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
1 hour fire door set	Fair	No Action Required	ł	В	18	1	No	1,367
								Year 1 Repair Cost (£
Element : Floors	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Vinyl sheet floor finish	Fair	No Action Required	ł	В	3	2	m2	82
								Year 1 Repair Cost (£

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	10	m2	82
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Firs	t				
ROOM : Store	No : 002/3/	1/008	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	28	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Doplocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Plasterboard walls	Fair	No Action Required		В	28	6	m2	205
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
1 hour fire door set	Fair	No Action Required		В	18	1	No	1,367
								Year 1 Repair Cost (£
Element : Floors	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Vinyl sheet floor finish	Fair	No Action Required		В	3	2	m2	82
								Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	10	m2	82
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fir	st				
ROOM : Bedroom 15	No : 002/3/1/0	010	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	ł	В	28	12	m2	410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Doulocomout
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	1	В	33	•	m2	820
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required	ł	В	28	8	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Softwood timber flush	Fair	No Action Required	ł	В	18	1	No	492
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	ty m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	48	m2	393
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fir	st				
ROOM : Toilet 15	No : 002/3/1/0	11	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	I	Cond/Ind Priority B	L'Expec 28	Quantity 4	, m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Doulocomout
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	28	•	m2	273
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	2	m2	68
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	I	В	23	-	m2	82
								Year 1 Repair Cost (£)

Element : Doors	CODE : 5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quantit 1	y No	Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	V	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	3	3	m2	123
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5						Bonlooomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	16	m2	123
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : First	st				
ROOM : Bedroom 14	No : 002/3/1/	012	USE :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard ceiling	Fair	No Action Required	I	В	28	12	m2	410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Devlessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	I	В	33	•	m2	820
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required	I	В	28	8	m2	273
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Deplessment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	I	В	18	1	No	492
								Year 1 Repair Cost (£

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quanti 12	ty m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action			Owent	4	Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quanti	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	48	m2	393
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fin	rst				
ROOM : Toilet 14	No : 002/3/1/	/013	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Ł	Cond/Ind Priority B	L'Expec 28	Quantity 4	, m2	Cost (£) 136
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	t	В	28	8	m2	273
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required	d	В	33	2	m2	68
								Year 1 Repair Cost (£
Element : Walls	CODE : 5							Donlocoment
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	ł	В	23	-	m2	82
								Year 1 Repair Cost (£

Element : Doors	CODE : 5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 18	Quantit 1	y No	Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	V	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	3	3	m2	123
							Year 1 Repair Cost (£
Element : Decoration	CODE:5						
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	16	m2	131
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Lounge	No : 002/4/	/0/002	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 29 m2	Cost (£) 991
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No action required	В	35	42 m2	1,435
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber panelled top &	Fair	No Action Required	В	10	1 No	656
bottom glazed						Year 1 Repair Cost (£
Element : Floors	CODE : 5					
Description Carpet sheet finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 29 m2	Replacement Cost (£) 1,189
						Year 1 Repair Cost (£

Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Emulsion to ceiling, decorative paper to walls; gloss to timber finishes	Fair	No Action Required	В	3	77	m2	631 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Male WC	No : 002/4/	/0/003	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 5 m2	Cost (£) 170
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	16 m2	1,312
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	28	4 m2	164
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Softwood timber sliding door	Fair	No Action Required	В	23	1 m2	341
						Year 1 Repair Cost (£)

Element : Floors Description	CODE :5	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	5	m2	205
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE :5	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Emulsion to ceiling; gloss/varnish		No Action Required	B	с Ехрес 3	5	m2	41
to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Store	No : 002/4/0	0/004	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 13 m2	Cost (£) 444
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	35	31 m2	1,059
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet floor finish	Fair	No Action Required	В	8	13 m2	533
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	44	m2	360 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : Ground			
ROOM : Bedroom 39	No : 002/4/	0/005	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Deplessment
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 12 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Toilet 39	No : 002/4/	/0/006	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Bedroom 38	No : 002/4/0	0/007	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Deplessment
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 12 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : Ground			
ROOM : Toilet 38	No : 002/4/	0/008	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Donlocomont
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Circulation Area	No : 002/4	/0/009	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priori B	ty L'Expec 33	Quantity 8 m2	Cost (£) 273
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priori	y L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	32 m2	1,093
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priori	y L'Expec	Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	8 m2	328
						Year 1 Repair Cost (£)
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priori	y L'Expec	Quantity	Cost (£)
Re-decoration	Fair	No Action Required	В	3	50 m2	410
Emulsion to ceiling and walls; gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Bedroom 37	No : 002/4/	/0/010	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£
Element : Floors	CODE:5					Doplocoment
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B 4	L'Expec 2	Quantity 12 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Toilet 37	No : 002/4/0	0/011	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Donlocomont
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£

Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	2	m2	82
							Year 1 Repair Cost (£)
Element : Decoration	CODE:5					•.	Replacement
Description	Condition	Action	Cond/Ind Priority	•	Quant		Cost (£)
Re-decoration Emulsion to ceiling only	Fair	No Action Required	B 4	3	2	m2	16
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Bedroom 36	No : 002/4/0	0/012	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Donlocoment
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B 4	L'Expec 2	Quantity 12 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : Ground			
ROOM : Toilet 36	No : 002/4/	0/013	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 2 m2	Replacement Cost (£) 82 Year 1 Repair Cost (£)
Element : Decoration Description	CODE :5 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration Emulsion to ceiling only	Poor	Redecorate ceiling ,wash down walls	C 4	Replace/In	2 m2	16 Year 1 Repair Cost (£) 50

BUILDING : Block 04 Keays ROOM : Boiler	UPRN : No : 002/4/0		FLOOR : Ground USE :			
Element : Ceilings	CODE : 5					Replacement
Description Fibreboard finish	Condition Fair	Action No Action Required	Cond/Ind Pric	rity L'Expec 35	Quantity 10 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Denlessment
Description	Condition	Action	Cond/Ind Pric	ority L'Expec	Quantity	Replacement Cost (£)
Block pointed finish (unpainted)	Fair	No Action Required	В	35	26 m2	710
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Pric	ority L'Expec	Quantity	Cost (£)
Unpainted Concrete	Fair	No Action Required	В	40	10 m2	684
						Year 1 Repair Cost (£)
Element : Decoration	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Pric	ority L'Expec	Quantity	Replacement Cost (£)
Gloss/varnish to timber finishes	Fair	No Action Required	В	3	2 m2	16
only						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Store	No : 002/4/	0/015	USE :			
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	25	6 m2	205
						Year 1 Repair Cost (£
Element : Doors	CODE : 5					Donlocomont
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	В	10	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Vinyl sheet floor finish	Fair	No Action Required	В	4	3 m2	123
						Year 1 Repair Cost (£
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Emulsion to ceiling and walls;	Fair	No Action Required	В	3	11 m2	90
gloss/varnish to timber finishes						Year 1 Repair Cost (£

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Circulation Area/St	airs No : 0	002/4/0/016	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Require	Cond/Ind Priorit	/ L'Expec 35	Quantity 13 m2	Cost (£) 444
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No action required	В	35	64 m2	2,187
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
1 hour fire door set	Fair	No Action Require	ed B	23	1 No	1,367
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Require	ed B	23	1 No	1,025
						Year 1 Repair Cost (£

Element : Floors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Carpet sheet finish, with colour contrasted non-slip nosings to steps .	Fair	No Action Required	В	8	13 m2	700 Year 1 Repair Cost (£)
Element : Decoration	CODE :5					
	Condition	Action	Cond/Ind Brigrity	L'Expos	Quantity	Replacement
Description Emulsion to ceiling and walls;	Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 3	Quantity 79 m2	Cost (£) 648
gloss/varnish to timber finishes	Fall	No Action Required	Б	3	79 IIIZ	040
5						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : Ground			
ROOM : Circulation Area	No : 002/4/	0/017	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 13 m2	Cost (£) 444
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	38 m2	1,298
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1 hour fire door sets	Fair	No Action Required	В	23	4 No	5,468
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	13 m2	533
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	73	m2	598 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Toilet	No : 002/4/	/0/018	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 35	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Devlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	35	15 m2	512
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description Vinyl sheet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 4	Quantity 3 m2	Cost (£) 123
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	20	m2	164 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Bedroom 45	No : 002/4/	0/019	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	2 L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£
Element : Floors	CODE:5					Doplocoment
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B 4	8 8	Quantity 12 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Toilet 45	No : 002/4/	/0/020	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priorit	/ L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priorit	/ L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	· · · · ·	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Bedroom 44	No :002/4/0/	/021	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE : 5					Deplessment
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B 4	L'Expec 8	Quantity 12 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Toilet 44	No : 002/4/	0/022	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priorit	/ L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : Ground			
ROOM : Bedroom 43	No : 002/4/	0/023	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	B 4	8	12 m2	492
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Poor	Redecorate	C 4	Replace/In	46 m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : Ground			
ROOM : Toilet 43	No : 002/4/0	0/024	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Donlocomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Doplocoment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 2 m2	Replacement Cost (£) 82 Year 1 Repair Cost (£)
Element : Decoration Description	CODE :5 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration Emulsion to ceiling only	Poor	Redecorate ceiling ,wash down walls	C 4	Replace/In	2 m2	16 Year 1 Repair Cost (£) 50

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Circulation Area	No : 002/4/	/0/025	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	y L'Expec 33	Quantity 8 m2	Cost (£) 273
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	y L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	32 m2	1,093
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	8 m2	328
						Year 1 Repair Cost (£)
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Re-decoration	Fair	No Action Required	В	3	50 m2	410
Emulsion to ceiling and walls; gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : Ground			
ROOM : Bedroom 42	No : 002/4/	0/026	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE : 5					Deplessment
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B 4	L'Expec 8	Quantity 12 m2	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : Ground			
ROOM : Toilet 42	No : 002/4/	0/027	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	 L'Expec 33 	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Denlessment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : Ground			
ROOM : Bedroom 41	No : 002/4/	0/028	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Donlocomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	B 4	8	12 m2	492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Toilet 41	No : 002/4/	0/029	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE : 5					Denlessment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bedroom 40	UPRN : No : 002/4/		FLOOR : Ground USE :					
	NO : 002/4/	0/030	032 :					
Element : Ceilings	CODE :5							Replacement
Description	Condition	Action		Ind Priority	L'Expec	Quantity	•	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В		33	12	m2	410
								Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Cond	Ind Priority	L'Expec	Quantity	y	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	·	38	30	m2	1,025
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description	Condition	Action	Cond	Ind Priority	L'Expec	Quantity	y	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В		23	1	No	1,025
								Year 1 Repair Cost (£)
Element : Floors	CODE :5							Replacement
Description	Condition	Action	Cond	Ind Priority	L'Expec	Quantity	y	Cost (£)
Carpet floor finish	Poor	Replace	С	4	Replace/In	-	m2	492
								Year 1 Repair Cost (£)

Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Poor	Redecorate	C 4	Replace/In	46 m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : Ground			
ROOM : Toilet 40	No : 002/4/0	0/031	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 33	Quantity 2 m2	Cost (£) 68
J. J						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Devileeeweet
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Donlocoment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantii 2	t y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
Re-decoration Emulsion to ceiling only	Poor	Redecorate	C	Replace/In	2	m2	16
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Toilet	No : 002/4/	0/032	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	7 m2	239
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	2 m2	136
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Denlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	1 m2	82
						Year 1 Repair Cost (£)

Element : Doors	CODE : 5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantit 1	y No	Cost (£) 492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	V	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3	m2	123
							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	12	m2	98
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Lift Machinery	No : 002/4/0)/033	USE :			
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	35	4 m2	136
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	18 m2	615
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Unpainted Concrete	Fair	No Action Required	В	40	18 m2	1,230
						Year 1 Repair Cost (£
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Emulsion to ceiling and walls;	Fair	No Action Required	В	3	24 m2	196
gloss/varnish to timber finishes						Year 1 Repair Cost (£

BUILDING : Block 04 Keays	UPRN :	FLOO	R:First			
ROOM : Electrical Store	No : 002/4/1/00	02 US	E:			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair, although slight cracking is	Make good plaster finish	B 4	38	15 m2	512
	evident in areas					Year 1 Repair Cost (£) 100
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Deplessment
Description Vinyl tile floor finish	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantity 3 m2	Replacement Cost (£) 123
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration	Poor	Redecorate	C 4	Replace/In	20 m2	164
						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First					
ROOM : Bedroom 25	No : 002/4/	/1/003	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind B	Priority	L'Expec 33	Quantity 12	, m2	Cost (£) 410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocoment
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	-	38	•	m2	1,025
								Year 1 Repair Cost (£
Element : Doors	CODE:5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В		23	1	No	1,025
								Year 1 Repair Cost (£
Element : Floors	CODE :5							Devlessment
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required		4	8	-	m2	492
								Year 1 Repair Cost (£

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First			
ROOM : Toilet 25	No : 002/4/	1/004	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Prid B	ority L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Donlocomont
Description	Condition	Action	Cond/Ind Pri	ority L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Donlocomont
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First					
ROOM : Bathroom	No : 002/4/	1/005	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required		d/Ind Priority B	L'Expec 33	Quantity 3	m2	Cost (£) 102
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Denlessment
Description	Condition	Action	Con	d/Ind Priority	L'Expec	Quantity		Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	7	m2	239
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Con	d/Ind Priority	L'Expec	Quantity		Cost (£)
Timber board finish	Fair	No Action Required		В	20	2	m2	82
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Con	d/Ind Priority	L'Expec	Quantity		Cost (£)
Ceramic tiles to walls	Fair	No Action Required		В	28	-	m2	246
								Year 1 Repair Cost (£

Element : Doors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1	No	1,025
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	2	m2	82
							Year 1 Repair Cost (£)
Element : Decoration	CODE :5						Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	itv	Replacement Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	14	m2	114
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First					
ROOM : Bedroom 26	No : 002/4/	/1/006	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind B	Priority	L'Expec 33	Quantity 12	/ m2	Cost (£) 410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	-	38	30	m2	1,025
								Year 1 Repair Cost (£
Element : Doors	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В		23	1	No	1,025
								Year 1 Repair Cost (£
Element : Floors	CODE :5							Doulocomout
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required		4	8		m2	492
								Year 1 Repair Cost (£

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First					
ROOM : Toilet 26	No : 002/4/	1/007	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind B	Priority	L'Expec 33	Quantity 2	m2	Cost (£) 68
								Year 1 Repair Cost (£
Element : Walls	CODE:5							Devlessment
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В		38	12	m2	410
								Year 1 Repair Cost (£)
Element : Doors	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Cost (£)
Softwood timber flush	Fair	No Action Required	В		23	1	No	492
								Year 1 Repair Cost (£)
Element : Floors	CODE : 5							Devlessment
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	,	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	-	8	•	m2	82
								Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	16	m2	114 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First			
ROOM : Bedroom 27	No : 002/4/	/1/008	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Pr B	riority L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Donlocomont
Description	Condition	Action	Cond/Ind Pr	riority L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£
Element : Doors	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Pr	riority L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£
Element : Floors	CODE:5					Denlessment
Description	Condition	Action	Cond/Ind Pr	riority L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	B 4	8	12 m2	492
						Year 1 Repair Cost (£

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First				
ROOM : Toilet 27	No : 002/4/	/1/009	USE :				
Element : Ceilings	CODE : 5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	с	ond/Ind Priority B	L'Expec 33	Quantity 2 m2	Cost (£)
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Denlessment
Description	Condition	Action	С	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	12 m2	410
							Year 1 Repair Cost (£
Element : Doors	CODE:5						Replacement
Description	Condition	Action	С	ond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required		В	23	1 No	492
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Denlessment
Description	Condition	Action	с	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required		В	8	2 m2	
							Year 1 Repair Cost (£

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	16	m2	114 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Circulation Area	UPRN : No : 002/4		FLOOR : First USE :					
Element : Ceilings Description	CODE :5 Condition	Action	Cond/Ind F	•	L'Expec	Quantity	•	Replacement Cost (£)
Plasterboard ceiling	Fair	No Action Required	В		33	8	m2	273 Year 1 Repair Cost (£)
Element : Walls	CODE :5							Replacement
Description	Condition	Action	Cond/Ind F	-	L'Expec	Quantity	y	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	:	38	32	m2	1,093
								Year 1 Repair Cost (£)
Element : Floors	CODE :5							Replacement
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind F B	-	L'Expec 8	Quantity 8	/ m2	Cost (£) 328
								Year 1 Repair Cost (£)
Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quantity	y	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	:	3	50	m2	410
gloss/varnish to timber finishes								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First				
ROOM : Bedroom 28	No : 002/4/1	1/011	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	C	ond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Doulocomont
Description	Condition	Action	C	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	30 m2	1,025
							Year 1 Repair Cost (£
Element : Doors	CODE :5						Replacement
Description	Condition	Action	C	ond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required		В	23	1 No	1,025
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Denlessment
Description	Condition	Action	C	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required		B 4	8	12 m2	492
							Year 1 Repair Cost (£)

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First			
ROOM : Toilet 28	No : 002/4/	/1/012	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priorit B	y L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	12 m2	410
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	2 m2	82
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	16	m2	114 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First				
ROOM : Bedroom 29	No : 002/4/	1/013	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Co	ond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£)
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Denlessment
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	30 m2	
							Year 1 Repair Cost (£
Element : Doors	CODE:5						Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required		В	23	1 No	1,025
							Year 1 Repair Cost (£
Element : Floors	CODE:5						Denlessment
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required		B 4	8	12 m2	
							Year 1 Repair Cost (£

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First			
ROOM : Toilet 29	No : 002/4/	1/014	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priorit	y L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Deplessment
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	12 m2	410
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	2 m2	82
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	16	m2	131 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First					
ROOM : Bedroom 30	No : 002/4/	/1/015	USE :					
Element : Ceilings	CODE :5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind B	I Priority	L'Expec 33	Quantity 12	/ m2	Cost (£) 410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Deplessment
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quantity	/	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	-	38	30	m2	1,025
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	I Priority	L'Expec	Quantity	,	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В		23	1	No	1,025
								Year 1 Repair Cost (£)
Element : Floors	CODE :5							Devlessment
Description Carpet floor finish	Condition Fair	Action No Action Required	Cond/Ind B	I Priority 4	L'Expec 8	Quantity 12	/ m2	Replacement Cost (£) 492
								Year 1 Repair Cost (£)

Element : Decoration	CODE : 5							Replacement
Description	Condition	Action	Cond/Ind F	Priority	L'Expec	Quant	ity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В 4	4	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First			
ROOM : Toilet 30	No : 002/4/	/1/016	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Pric B	ority L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Donlocomont
Description	Condition	Action	Cond/Ind Pric	ority L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	6 m2	492
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Pric	ority L'Expec	Quantity	Cost (£)
Pre-finished board	Fair	No Action Required	В	38	5 m2	205
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Donlocomont
Description	Condition	Action	Cond/Ind Pric	ority L'Expec	Quantity	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£

Element : Floors Description Vinyl sheet finish (non-slip)	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 2	. y m2	Replacement Cost (£) 82
							Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantit	····	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	с схрес 3	2	. y m2	16
Emulsion to ceiling only	-			-			Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First			
ROOM : Toilet	No : 002/4/	(1/017	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind F B	Priority L'Expec 35	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Denlessment
Description	Condition	Action	Cond/Ind F	Priority L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	35	15 m2	512
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind F	Priority L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Donlocoment
Description Vinyl sheet floor finish	Condition Fair	Action No Action Required	Cond/Ind F B	Priority L'Expec 4	Quantity 3 m2	Replacement Cost (£) 123
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	20	m2	164 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : First			
ROOM : Circulation Area	No : 002/4/	/1/018	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec33	Quantity 13 m2	Cost (£) 444
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	38 m2	1,298
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
1 hour fire door sets	Fair	No Action Required	В	23	4 No	5,468
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	13 m2	533
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	73	m2	598 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bedroom 31	UPRN : No : 002/4/1/0		R : First			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair, although minor repairs required	Make good plaster finish	B 4	38	30 m2	1,025
	required					Year 1 Repair Cost (£) 30
Element : Doors	CODE : 5					Replacement
Description 1/2 hour fire door set	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description Carpet floor finish	Condition Poor	Action Replace	Cond/Ind Priority C 4	L'Expec Replace/In	Quantity 12 m2	Cost (£) 492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First						
ROOM : Toilet 31	No : 002/4/	1/021	USE :						
Element : Ceilings	CODE : 5								Replacement
Description	Condition	Action	C	ond/Ind Pric	ority	L'Expec	Quantity	y	Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	-	33	2	m2	68
									Year 1 Repair Cost (£
Element : Walls	CODE :5								Replacement
Description	Condition	Action	C	ond/Ind Pric	ority	L'Expec	Quantity	y	Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	•	38	12	m2	410
									Year 1 Repair Cost (£)
Element : Doors	CODE :5								Donlocoment
Description	Condition	Action	C	ond/Ind Pric	ority	L'Expec	Quantity	v	Replacement Cost (£)
Softwood timber flush	Fair	No Action Required		В	•	23	1	No	492
									Year 1 Repair Cost (£)
Element : Floors	CODE:5								Replacement
Description	Condition	Action	C	ond/Ind Pric	ority	L'Expec	Quantity	y	Cost (£)
Vinyl sheet finish (non-slip)	Poor	No Action Required		C 4	-	Replace/In	-	m2	82
									Year 1 Repair Cost (£)

Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Poor	Redecorate	C 4	Replace/In	16 m2	131 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First					
ROOM : Bedroom 32	No : 002/4/	1/022	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	/	Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	33	12	m2	410
								Year 1 Repair Cost (£
Element : Walls	CODE :5							Donlocomont
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	30	m2	1,025
								Year 1 Repair Cost (£
Element : Doors	CODE : 5							Replacement
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	/	Cost (£)
1/2 hour fire door set	Fair	No Action Required		В	23	1	No	1,025
								Year 1 Repair Cost (£)
Element : Floors	CODE : 5							Donlocomont
Description	Condition	Action	Co	ond/Ind Priority	L'Expec	Quantity	,	Replacement Cost (£)
Carpet floor finish	Poor	Replace		C 4	Replace/In	-	m2	492
								Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First			
ROOM : Toilet 32	No : 002/4/	/1/023	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	/ L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	12 m2	410
						Year 1 Repair Cost (£
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	2 m2	82
						Year 1 Repair Cost (£

Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Poor	Redecorate	C 4	Replace/In	16 m2	131 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Circulation Area	UPRN : No : 002/4/		FLOOR : First USE :			
Element : Ceilings Description Plasterboard ceiling	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Prio B	rity L'Expec 33	Quantity 8 m2	Replacement Cost (£) 273 Year 1
						Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prio	•	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	32 m2	1,093
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prio		Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	8 m2	328
						Year 1 Repair Cost (£)
Element : Decoration	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Prio	rity L'Expec	Quantity	Cost (£)
Re-decoration	Fair	No Action Required	В	3	50 m2	410
Emulsion to ceiling and walls; gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First					
ROOM : Bedroom 33	No : 002/4/	/1/025	USE :					
Element : Ceilings	CODE : 5							Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Inc B	d Priority	L'Expec 33	Quantity 12	y m2	Cost (£) 410
Thasterboard centing	i an	No Action Required	D		00	12	1112	
								Year 1 Repair Cost (£
Element : Walls	CODE : 5							Replacement
Description	Condition	Action	Cond/Inc	d Priority	L'Expec	Quantity	у	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В		38	30	m2	1,025
								Year 1 Repair Cost (£)
Element : Doors	CODE:5							Replacement
Description	Condition	Action	Cond/Inc	d Priority	L'Expec	Quantity	у	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В		23	1	No	1,025
								Year 1 Repair Cost (£)
Element : Floors	CODE : 5							Replacement
Description	Condition	Action	Cond/Inc	d Priority	L'Expec	Quantity	y	Cost (£)
Unpainted Concrete	Fair	No Action Required	В	Ĩ	38	12	m2	492
								Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First			
ROOM : Toilet 33	No : 002/4/	/1/026	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	12 m2	410
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Vinyl sheet floor finish	Fair	No Action Required	В	2	2 m2	82
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	14	m2	114 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First			
ROOM : Bedroom 34	No : 002/4/	1/027	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Pri B	ority L'Expec 33	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Deplessment
Description	Condition	Action	Cond/Ind Pri	ority L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	30 m2	1,025
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Pri	ority L'Expec	Quantity	Cost (£)
1/2 hour fire door set	Fair	No Action Required	В	23	1 No	1,025
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Pri	• •	Quantity	Replacement Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	12 m2	492
						Year 1 Repair Cost (£)

Element : Decoration	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	46	m2	377 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	I	FLOOR : First			
ROOM : Toilet 34	No : 002/4/	1/028	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Pr B	iority L'Expec 33	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Pr	iority L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	12 m2	410
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Pr	iority L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Pr	iority L'Expec	Quantity	Replacement Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	2 m2	82
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	3	14	m2	114 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : First					
ROOM : Bedroom 35	No : 002/4/	1/029	USE :					
Element : Ceilings	CODE : 5							Replacement
Description	Condition	Action		d/Ind Priority	L'Expec	Quantity		Cost (£)
Plasterboard ceiling	Fair	No Action Required		В	33	12	m2	410
								Year 1 Repair Cost (£)
Element : Walls	CODE : 5							Replacement
Description	Condition	Action	Con	d/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	38	6	m2	205
								Year 1 Repair Cost (£)
Element : Walls	CODE:5							Replacement
Description	Condition	Action	Con	d/Ind Priority	L'Expec	Quantity	,	Cost (£)
Plasterboard walls	Fair	No Action Required		В	33	25	m2	854
								Year 1 Repair Cost (£)
Element : Doors	CODE :5							Replacement
Description 1 hour fire door set	Condition Fair	Action No Action Required		d /Ind Priority B	L'Expec 23	Quantity	, No	Cost (£) 1,025
I hour fire door set								Year 1 Repair Cost (£)

Element : Floors Description Carpet floor finish	CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 8	Quantit 12	y m2	Replacement Cost (£) 492
							Year 1 Repair Cost (£)
Element : Decoration	CODE : 5	Action	Cond/Ind Driverity		Quentit		Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	•	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	43	m2	352
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : First			
ROOM : Toilet 35	No : 002/4/	/1/030	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 33	Quantity 4 m2	Cost (£) 136
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Devlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	38	2 m2	68
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	33	4 m2	136
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	28	4 m2	328
						Year 1 Repair Cost (£

Element : Doors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Softwood timber flush	Fair	No Action Required	В	23	1	No	492
							Year 1 Repair Cost (£)
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	8	3	m2	82
							Year 1 Repair Cost (£)
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity		Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	3	-	m2	98
gloss/varnish to timber finishes							Year 1 Repair Cost (£)

BUILDING : Block 05 Dining	UPRN :		FLOOR : Dining			
ROOM : Dining Room	No : 002/5/0)/001	USE :			
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	•	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	20	56 m2	1,913
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Poplacomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В		63 m2	2,153
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber/glazed	Fair	No Action Required	В	10	2 No	1,312
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Carpet floor finish	Fair	No Action Required	В	8	56 m2	2,296
						Year 1 Repair Cost (£)

Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Re-decoration	Fair	No Action Required	В	4	119	m2	976
							Year 1 Repair Cost (£)

BUILDING : Block 06 Greenhous	e UPRN :		FLOOR : Ground			
ROOM : Conservatory 1	No : 002/6/0/	001	USE :			
Element : Walls	CODE : 5					Replacement
Description Block pointed finish (painted)	Condition Fair	Action No Action Required	Cond/Ind Priority B	 L'Expec 35 	Quantity 15 m2	Cost (£) 410
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	25	43 m2	1,469
						Year 1 Repair Cost (£
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Softwood timber panelled top &	Fair	No Action Required	В	15	1 No	656
bottom glazed						Year 1 Repair Cost (£
Element : Floors	CODE :5					
Description Timber laminate floor	Condition Fair	Action No Action Required	Cond/Ind Priority B	 L'Expec 15 	Quantity 50 m2	Replacement Cost (£) 4,101
						Year 1 Repair Cost (£

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Emulsion to walls; gloss/varnish to timber finishes	Fair	No Action Required	В	2	60	m2	492 Year 1
							Repair Cost (£)

BUILDING : Block 06 Greenhous	e UPRN	:	FLOOR : Gro	bund				
ROOM : Conservatory 2	No	: 002/6/0/002	USE :					
Element : Walls Description	CODE :5	Action		Cond/Ind Priority	L'Expec	Quant	itv	Replacement Cost (£)
Block pointed finish (unpainted)	Fair	No Action Require		В	35	15	m2	410
								Year 1 Repair Cost (£)
Element : Floors	CODE : 5							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Concrete slab finish	Fair	No Action Require	ed	В	31	55	m2	3,760
								Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A	UPRN :		FLOOR : Ground			
ROOM : Living Room	No : 002/7/0/	/001	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec	Quantity 23 m2	Cost (£) 786
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Denlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	20	12 m2	341
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Poplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	32	14 m2	478
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Doplocoment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 22	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

CODE : 5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 7	Quant 23	t ity m2	Replacement Cost (£) 943
						Year 1 Repair Cost (£)
CODE : 5	Action	Cond/Ind Driovity	LIEvnoo	Quant		Replacement
		•	•		•	Cost (£)
Fair	No Action Required	В	Ζ	53	m2	434
						Year 1 Repair Cost (£)
	Condition Fair	Condition Action Fair No Action Required CODE : 5 Action Condition Action	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5ActionCond/Ind Priority	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 7CODE :5ActionCond/Ind PriorityL'ExpecConditionActionCond/Ind PriorityL'Expec	Condition Action Cond/Ind Priority L'Expec Quant Fair No Action Required B 7 23 CODE : 5 Action Cond/Ind Priority L'Expec Quant Condition Action Cond/Ind Priority L'Expec Quant	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 23Quantity 23CODE : 5ConditionActionCond/Ind PriorityL'ExpecQuantity

BUILDING : Block 07 Flat 1A	UPRN :		FLOOR : Ground			
ROOM : Kitchen	No : 002/7/	/0/002	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 32	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	27	12 m2	984
						Year 1 Repair Cost (£)
Element : Walls	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	32	1 m2	34
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Donlocoment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 22	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Quarry tiled floor	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 27	Quantity 9 m2	Replacement Cost (£) 738
						Year 1 Repair Cost (£)
Element : Decoration Description	CODE :5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	2	12 m2	98
Emulsion to ceiling only						Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A	UPRN :		FLOOR : Grou	und			
ROOM : Circulation Area	No : 002/7/0/00	3	USE :				
Element : Ceilings	CODE :5						Replacement
Description Plasterboard ceiling	Condition Fair, although slightly marked in	Action No Action Required		Cond/Ind Priority B	L'Expec 32	Quantity 5 m2	Cost (£) 170
	areas						Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action	C	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required		В	32	6 m2	205
							Year 1 Repair Cost (£
Element : Walls	CODE :5						Replacement
Description	Condition	Action	C	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required		В	20	5 m2	170
							Year 1 Repair Cost (£
Element : Floors	CODE :5						Replacement
Description Carpet floor finish	Condition Fair	Action No Action Required		Cond/Ind Priority B	L'Expec 7	Quantity 5 m2	Cost (£) 205
							Year 1 Repair Cost (£

Element : Decoration	CODE :5							Replacement
Description	Condition	Action	Cond/Ind	Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration	Fair, although ceiling marked	Redecorate ceiling	В	4	2	16	m2	131
								Year 1 Repair Cost (£) 40

BUILDING : Block 07 Flat 1A	UPRN :		FLOOR : Ground			
ROOM : Bathroom	No : 002/7/	/0/004	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 32	Quantity 3 m2	Cost (£) 102
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	27	17 m2	1,394
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	22	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Vinyl sheet finish (non-slip)	Fair	No Action Required	В	7	2 m2	82
						Year 1 Repair Cost (£)

Element : Decoration	CODE:5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Re-decoration Emulsion to ceiling only	Fair	No Action Required	В	2	3	m2	24
							Year 1 Repair Cost (£)
							Repair Co

BUILDING : Block 07 Flat 1A	UPRN :		FLOOR : Ground			
ROOM : Bedroom	No : 002/7/	/0/005	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	 L'Expec 32 	Quantity 15 m2	Cost (£) 512
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	20	12 m2	410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	/ L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	32	12 m2	410
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Deplessment
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 22	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

Element : Floors Description Carpet floor finish	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 7	Quantity 15 m2	Replacement Cost (£) 615
						Year 1 Repair Cost (£)
Element : Decoration Description	CODE : 5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	B	2	47 m2	Cost (£) 385
gloss/varnish to timber finishes						Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Ground			
ROOM : Vestibule	No : 002/8/0	0/001	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	27	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Devlessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	27	3 m2	102
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	20	7 m2	239
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Timber strip flooring	Fair	No Action Required	В	17	2 m2	205
						Year 1 Repair Cost (£)

Element : Decoration Description	CODE :5 Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Re-decoration	Fair	No Action Required	В	2	16	m2	131
							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Ground			
ROOM : Bedroom 1	No : 002/8/	0/002	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 27	Quantity 14 m2	Cost (£) 478
						Year 1 Repair Cost (£)
Element : Walls	CODE : 5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	27	40 m2	1,367
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	15	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Poplacomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Timber strip flooring	Fair	No Action Required	В	17	14 m2	1,148
						Year 1 Repair Cost (£)

Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Re-decoration Emulsion to ceiling, decorative paper to walls; gloss to timber finishes	Fair, although slightly marked in areas	No Action Required	В	2	56	m2	459 Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :	-	FLOOR : Ground			
ROOM : Bedroom 2	No : 002/8/	/0/003	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 27	Quantity 9 m2	Cost (£) 307
						Year 1 Repair Cost (£
Element : Walls	CODE:5					Donlocomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	27	32 m2	1,093
						Year 1 Repair Cost (£)
Element : Doors	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	15	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Timber strip flooring	Fair	No Action Required	В	17	9 m2	738
						Year 1 Repair Cost (£)

Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	tity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	2	43	m2	352 Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :	I	FLOOR : Ground			
ROOM : Living Room	No : 002/8/	0/004	USE :			
Element : Ceilings	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Lath & plaster ceiling	Fair	No Action Required	В	10	13 m2	711
						Year 1 Repair Cost (£
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	27	17 m2	581
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	20	8 m2	273
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	27	58 m2	1,982
						Year 1 Repair Cost (£)

Element : Doors	CODE : 5						Replacement
Description Softwood timber flush	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 22	Quantit	y No	Cost (£) 492
			B	22	I	NO	492 Year 1 Repair Cost (£
Element : Floors	CODE:5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Timber strip flooring	Fair	No Action Required	В	17	23	m2	943
							Year 1 Repair Cost (£
Element : Decoration	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantit	v	Cost (£)
Re-decoration Emulsion to ceiling and walls;	Fair	No Action Required	В	2	96	m2	787
gloss/varnish to timber finishes							Year 1 Repair Cost (£

BUILDING : Block 08 Lodge	UPRN :	I	FLOOR : Ground			
ROOM : Bathroom	No : 002/8/	/0/005	USE :			
Element : Ceilings	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Pre finished board	Fair	No Action Required	В	27	1 m2	54
						Year 1 Repair Cost (£
Element : Ceilings	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard ceiling	Fair	No Action Required	В	27	4 m2	136
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	22	10 m2	820
						Year 1 Repair Cost (£)
Element : Doors	CODE : 5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	15	1 No	492
						Year 1 Repair Cost (£)

Element : Floors Description Quarry tiled floor	CODE :5 Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 22	Quantity 3 m2	Replacement Cost (£) 123
						Year 1 Repair Cost (£)
Element : Decoration Description	CODE :5	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Re-decoration	Fair	No Action Required	B	2	3 m2	24
Emulsion to ceiling only						Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :	I	FLOOR : Ground			
ROOM : Toilet	No : 002/8/	/0/006	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 27	Quantity 2 m2	Cost (£) 68
						Year 1 Repair Cost (£)
Element : Walls	CODE:5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	22	10 m2	820
						Year 1 Repair Cost (£)
Element : Doors	CODE:5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	15	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE:5					Deplessment
Description	Condition	Action	Cond/Ind Priority	•	Quantity	Replacement Cost (£)
Quarry tiled floor	Fair	No Action Required	В	22	2 m2	164
						Year 1 Repair Cost (£)

Element : Decoration Description	CODE : 5 Condition	Action	Cond/Ind Priority	L'Expec	Quan	titv	Replacement Cost (£)
Re-decoration	Fair	No Action Required	В	2	2	m2	16
Emulsion to ceiling only							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Ground			
ROOM : Kitchen	No : 002/8/0	0/007	USE :			
Element : Ceilings	CODE : 5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 27	Quantity 11 m2	Cost (£) 375
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic tiles to walls	Fair	No Action Required	В	22	8 m2	656
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	27	8 m2	273
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Donlocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	20	10 m2	341
						Year 1 Repair Cost (£)

Element : Doors	CODE : 5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	y	Cost (£)
Softwood timber panelled top glazed	Fair	No Action Required	В	15	1	No	656
9.0200							Year 1 Repair Cost (
Element : Floors	CODE :5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	У	Cost (£)
Quarry tiled floor	Fair	No Action Required	В	27	9	m2	738
							Year 1 Repair Cost
Element : Decoration	CODE :5						Replacemen
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	y	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	2	35	m2	287 Year 1
							Repair Cost

BUILDING : Block 08 Lodge	UPRN :	F	LOOR : Ground			
ROOM : Circulation Area	No : 002/8/	/0/008	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 32	Quantity 9 m2	Cost (£) 307
						Year 1 Repair Cost (£)
Element : Ceilings	CODE :5					Doplocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Timber panel at rooflight	Fair	No Action Required	В	20	1 m2	54
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Plasterboard walls	Fair	No Action Required	В	32	19 m2	649
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Donlocoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plaster on hard to walls	Fair	No Action Required	В	20	2 m2	68
						Year 1 Repair Cost (£)

CODE : 5						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
Fair	No Action Required	В	15	1	No	656
						Year 1 Repair Cost (£)
CODE :5						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantit	у	Cost (£)
Fair	No Action Required	В	5	10	m2	410
						Year 1 Repair Cost (£)
CODE :5						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantit	y	Cost (£)
Fair	No Action Required	В	2	51	m2	418
						Year 1 Repair Cost (£)
	Condition Fair CODE : 5 Condition Fair CODE : 5 Condition	Condition FairAction No Action RequiredCODE :5Action No Action RequiredFairAction No Action RequiredCODE :5Action No Action RequiredCODE :5ActionConditionAction	Condition FairAction No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority BCODE :5Action No Action RequiredCond/Ind Priority B	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 5Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 5CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 5CODE :5ActionL'Expec BL'Expec 5	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quantit 1CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 5Quantit 10CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 5Quantit 10CODE :5Action No Action RequiredCond/Ind Priority BL'Expec 5Quantit 10CODE :5Action ActionCond/Ind Priority BL'Expec 5Quantit 10	Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 15Quantity 1CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 5Quantity 10CODE :5 Condition FairAction No Action RequiredCond/Ind Priority BL'Expec 5Quantity 10CODE :5 ConditionAction ActionCond/Ind Priority BL'Expec 5Quantity 10CODE :5 ConditionActionCond/Ind Priority L'ExpecL'Expec Quantity

BUILDING : Block 08 Lodge	UPRN :	F	LOOR : Ground			
ROOM : Bedroom 3	No : 002/8/	0/009	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec 27	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£)
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	27	38 m2	1,298
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	15	1 No	492
						Year 1 Repair Cost (£)
Element : Floors	CODE :5					Poplocoment
Description	Condition Fair	Action	Cond/Ind Priority	L'Expec 17	Quantity 12 m2	Replacement Cost (£) 984
Timber strip flooring	rall	No Action Required	В	17	12 m2	
						Year 1 Repair Cost (£)

Element : Decoration	CODE:5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	lity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	2	52	m2	426 Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Ground			
ROOM : Bedroom 4	No : 002/8/	/0/010	USE :			
Element : Ceilings	CODE :5					Replacement
Description Plasterboard ceiling	Condition Fair	Action No Action Required	Cond/Ind Priority B	27	Quantity 12 m2	Cost (£) 410
						Year 1 Repair Cost (£
Element : Walls	CODE :5					Deplessment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Plasterboard walls	Fair	No Action Required	В	27	38 m2	1,298
						Year 1 Repair Cost (£)
Element : Doors	CODE :5					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Softwood timber flush	Fair	No Action Required	В	15	1 No	492
						Year 1 Repair Cost (£
Element : Floors	CODE:5					Replacement
Description Timber strip flooring	Condition Fair	Action No Action Required	Cond/Ind Priority B	L'Expec	Quantity 12 m2	Cost (£) 984
						Year 1 Repair Cost (£)

Element : Decoration	CODE:5						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quant	lity	Cost (£)
Re-decoration Emulsion to ceiling and walls; gloss/varnish to timber finishes	Fair	No Action Required	В	2	52	m2	426 Year 1 Repair Cost (£)

FIXTURES & FITTINGS

BUILDING : Block 01 Kyd	UPRN :		FLOOR : G	round				
ROOM : Office	No : 00	2/1/0/003	USE :					
Element : Built in cupboards	CODE :6							Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quant	ity	Cost (£)
Timber buit in cupboards	Fair	No action required		В	15	1	No	820
								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Store	UPRN : No : 002	2/1/0/010	FLOOR : Ground USE :			
Element : Worktops Description Laminate / chipboard worktop	CODE : 6 Condition Fair	Action No action required	Cond/Ind Pri B	ority L'Expec 13	Quantity 5 m2	Replacement Cost (£) 341 Year 1 Repair Cost (£)
Element : Built in cupboards Description Timber base and wall units	CODE : 6 Condition Fair	Action No action required	Cond/Ind Pri B	ority L'Expec 15	Quantity 6 No	Replacement Cost (£) 3,600 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Laundry	UPRN : No : 002	2/1/0/013	FLOOR : Grou USE :	Ind				
Element : Shelving Description Timber/metal shelving	CODE : 6 Condition Fair	Action No action required	с	cond/Ind Priority B	L'Expec 10	Quant 6	ity m	Replacement Cost (£) 328
								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground				
ROOM : Kitchen Staff	No : 002	2/1/0/020	USE :				
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ind Priorit B	/ L'Expec 15	Quant 1	i ity No	Replacement Cost (£) 820
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Store	UPRN : No : 002	/1/0/023A	FLOOR : Gr USE :	round				
Element : Shelving Description	CODE :6	Action		Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Timber shelving	Fair	No action required		В	15	3	m	82 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Store	UPRN : No : 002	2/1/0/024	FLOOR : Ground USE :				
Element : Shelving Description Timber/metal shelving	CODE : 6 Condition Fair	Action No action required	Cond/Ind Prior B	ty L'Expec	Quar 12	itity m	Replacement Cost (£) 656
							Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Firs	st				
ROOM : Circulation Area	No : 0	02/1/1/014	USE :					
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quant 2	ity No	Replacement Cost (£) 1,640
								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Firs	t				
ROOM : Circulation Area	No : 00	02/1/1/017	USE :					
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quanti 2	ty No	Replacement Cost (£) 1,640
								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : First	st				
ROOM : Circulation Area	No : 0	02/1/1/020	USE :					
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quant 2	i ty No	Replacement Cost (£) 1,640
								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Fir	st				
ROOM : Circulation Area	No : 0	02/1/1/023	USE :					
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quant 2	ty No	Replacement Cost (£) 1,640
								Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN	:	FLOOR : G	Ground				
ROOM : Grampian Lounge	No	: 002/2/0/016	USE :					
Element : Worktops Description Timber bar counter	CODE : 6 Condition Fair	Action No action requ	lired	Cond/Ind Priority B	L'Expec 13	Quan	tity m2	Replacement Cost (£) 2,000
				L		·		Year 1 Repair Cost (£)

NO : 00	2/2/1/008	USE :				
CODE :6						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quar	ntity	Cost (£)
Fair	No action required	В	23	1	m	27
						Year 1 Repair Cost (£)
	No : 00 CODE : 6 Condition	No : 002/2/1/008 CODE : 6 Condition Action	No: 002/2/1/008 USE: CODE:6 Condition Action Cond/Ind Priority	No: 002/2/1/008 USE: CODE:6 Condition Action Cond/Ind Priority L'Expect	No: 002/2/1/008 USE: CODE:6 Condition Action Cond/Ind Priority L'Expec Quar	No: 002/2/1/008 USE: CODE:6 Condition Action Cond/Ind Priority L'Expec Quantity

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : G	round				
ROOM : Store	No : 002	2/3/0/004	USE :					
Element : Shelving Description	CODE : 6	Action		Cond/Ind Priority	L'Expec	Quan	titv	Replacement Cost (£)
Timber shelving	Fair	No action required		B	18	2	m	54
								Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Grou	und				
ROOM : Store	No : 00	02/3/0/005	USE :					
Element : Shelving Description	CODE : 6 Condition	Action	(Cond/Ind Priority	L'Expec	Quant	ity	Replacement Cost (£)
Timber shelving	Fair	No action required		В	18	1	m	54
								Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie ROOM : Store	UPRN :	2/3/1/007	FLOOR : First USE :				
ROOM . Stole	NO . 00.	2/3/1/007	032.				
Element : Shelving Description	CODE :6	Action	Cond/Ind Priori	y L'Expec	Quar	ntitv	Replacement Cost (£)
Timber shelving	Fair	No action required	B	18	2	m	54
							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : First					
ROOM : Store	No : 00	2/3/1/008	USE :					
Element : Shelving Description	CODE : 6	Action	Co	nd/Ind Priority	L'Expec	Quant	i+\/	Replacement
Timber shelving	Fair	No action required	CO	B	18	1	m	Cost (£) 54
								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground				
ROOM : Store	No : 002	/4/0/004	USE :				
Element : Shelving Description	CODE : 6 Condition	Action	Cond/Ind Priority	•	Quant	•	Replacement Cost (£)
Timber shelving	Fair	No action required	В	23	30	m	820 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet	UPRN : No : 002	/4/0/018	FLOOR : Ground USE :				
Element : Shelving Description Timber shelving	CODE : 6 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quant 9	i ity m	Replacement Cost (£) 246
							Year 1 Repair Cost (£)

UPRN :							
No : 002	2/4/1/002	USE :					
CODE : 6	Action	Cond/Ind	Drievity		0	4:4.7	Replacement
			Priority	•	Quar	•	Cost (£)
Fair	No action required	В		23	1	m	191
							Year 1 Repair Cost (£)
	No : 002	No: 002/4/1/002 CODE:6 Condition Action	No: 002/4/1/002 USE: CODE:6 Condition Cond/Ind	No: 002/4/1/002 USE: CODE:6 Condition Action Cond/Ind Priority	No: 002/4/1/002 USE: CODE:6 Condition Action Cond/Ind Priority L'Expect	No: 002/4/1/002 USE: CODE:6 Condition Action Cond/Ind Priority L'Expec Quar	No: 002/4/1/002 USE: CODE:6 Condition Action Cond/Ind Priority L'Expec Quantity

BUILDING : Block 04 Keays ROOM : Bedroom 26	UPRN : No : 002	2/4/1/006	FLOOR : First USE :				
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ind Priority B	7 L'Expec 5	Quan 2	tity No	Replacement Cost (£) 1,640
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 26	UPRN : No : 002	2/4/1/007	FLOOR : First USE :					
Element : Built in cupboards Description Timber base units	CODE : 6 Condition Fair	Action No action required	Cond/Ind Pr B	iority	L'Expec 5	Quant 1	ity No	Replacement Cost (£) 820
								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bedroom 27	UPRN : No : 002	2/4/1/008	FLOOR : First USE :				
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ind Prio B	ity L'Expec	Quar 2	ntity No	Replacement Cost (£) 1,640
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 27	UPRN : No : 002	2/4/1/009	FLOOR : Firs	st				
Element : Built in cupboards Description Timber base units	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec	Quanti t	i y No	Replacement Cost (£) 820
								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bedroom 28	UPRN : No : 002	2/4/1/011	FLOOR : First USE :				
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec	Quan 2	tity No	Replacement Cost (£) 1,640
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 28	UPRN : No : 002	2/4/1/012	FLOOR : Fir USE :	rst				
Element : Built in cupboards Description Timber base units	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 5	Quanti 1	ty No	Replacement Cost (£) 820
								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bedroom 29	UPRN :	2/4/1/013	FLOOR : First USE :				
	NO . 00.	2/4/1/010	002.				
Element : Built in cupboards Description	CODE : 6 Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Replacement Cost (£)
Timber buit in cupboards	Fair	No action required	В	5	2	No	1,640
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 29	UPRN : No : 002	2/4/1/014	FLOOR : Fir USE :	st				
Element : Built in cupboards Description Timber base units	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 5	Quanti 1	ty No	Replacement Cost (£) 820
								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet	UPRN : No : 002	/4/1/017	FLOOR : First USE :					
Element : Shelving Description Timber shelving	CODE : 6 Condition Fair	Action No action required	Cond B	I/Ind Priority	L'Expec 23	Quant 9	ity m	Replacement Cost (£) 246
								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bedroom 31	UPRN : No : 002	2/4/1/020	FLOOR : First USE :					
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ind B	Priority	L'Expec 5	Quan 2	tity No	Replacement Cost (£) 1,640
								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 31	UPRN : No : 002	2/4/1/021	FLOOR : First USE :					
Element : Built in cupboards Description Timber base unit	CODE : 6 Condition Fair	Action No action required		nd Priority	L'Expec	Quant	i ty No	Replacement Cost (£) 820
							-	Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bedroom 32	UPRN : No : 002	2/4/1/022	FLOOR : First USE :				
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ind Priori B	y L'Expec	Quar 2	ntity No	Replacement Cost (£) 1,640
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 32	UPRN :	2/4/1/023	FLOOR : First USE :				
ROOM . Tollet 32	NO .002	2/4/1/023	03E .				
Element : Built in cupboards	CODE :6						Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quant	tity	Cost (£)
Timber base unit	Fair	No action required	В	2	1	No	820
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bedroom 33	UPRN :	2/4/1/025	FLOOR : First USE :				
	-		002.				
Element : Built in cupboards Description	CODE : 6 Condition	Action	Cond/Ind Priorit	y L'Expec	Quar	ntity	Replacement Cost (£)
Timber buit in cupboards	Fair	No action required	В	5	2	No	1,640
							Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 33	UPRN : No : 002	2/4/1/026	FLOOR : Fir USE :	rst					
Element : Built in cupboards Description Timber base unit	CODE : 6 Condition Poor	Action Replace		Cond/Ind	I Priority 4	L'Expec Replace/In	Quantity	y No	Replacement Cost (£) 820
									Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Fir	st				
ROOM : Bedroom 34	No : 002	2/4/1/027	USE :					
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 5	Quant 2	i ty No	Replacement Cost (£) 1,640
								Year 1 Repair Cost (£)

UPRN :						
NO : 00.	2/4/1/028	USE :				
CODE : 6						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Fair	No action required	В	2	1	No	820
						Year 1 Repair Cost (£)
	No : 002 CODE : 6 Condition	No: 002/4/1/028 CODE:6 Condition Action	No: 002/4/1/028 USE: CODE:6 Condition Action Cond/Ind Priority	No: 002/4/1/028 USE: CODE:6 Condition Action Cond/Ind Priority L'Expect	No: 002/4/1/028 USE: CODE:6 Condition Action Cond/Ind Priority L'Expec Quant	No: 002/4/1/028 USE: CODE:6 Condition Action Cond/Ind Priority L'Expec Quantity

BUILDING : Block 04 Keays ROOM : Bedroom 35	UPRN :	2/4/1/029	FLOOR : First USE :					
ROOM : Bedroom 35	NO : 00.	2/4/1/029	03E :					
Element : Built in cupboards Description	CODE : 6 Condition	Action	Cond/Ind I	Priority	L'Expec	Quan	tity	Replacement Cost (£)
Timber buit in cupboards	Fair	No action required	В		23	2	No	1,640
								Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A ROOM : Kitchen	UPRN : FL No : 002/7/0/002		FLOOR : Gro USE :	FLOOR : Ground USE :				
Element : Worktops Description Laminate / chipboard worktop	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 12	Quanti 5	ty m2	Replacement Cost (£) 341 Year 1 Repair Cost (£)
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 22	Quanti 7	ty No	Replacement Cost (£) 5,741 Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A ROOM : Circulation Area	UPRN : No : 002	2/7/0/003	FLOOR : Ground USE :					
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond B	l/Ind Priority	L'Expec	Quanti 3	t y No	Replacement Cost (£) 2,460
1 double and 1 single								Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A ROOM : Bathroom	UPRN : No : 002	2/7/0/004	FLOOR : Ground USE :					
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ir B	nd Priority	L'Expec 10	Quan 1	tity No	Replacement Cost (£) 820
								Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A ROOM : Bedroom	UPRN : No : 002	2/7/0/005	FLOOR : Gro USE :	bund				
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 22	Quanti 1	ty No	Replacement Cost (£) 820
								Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge ROOM : Vestibule	UPRN : No : 002	2/8/0/001	FLOOR : Ground USE :				
Element : Built in cupboards Description Timber built in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ind Priority B	 L'Expec 15 	Quant 1	t ity No	Replacement Cost (£) 820
							Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Ground				
ROOM : Bathroom	No : 002	/8/0/005	USE :				
Element : Built in cupboards Description Timber built in cupboards	CODE : 6 Condition Fair	Action	Cond/Ind Pric	2	Qu	iantity	Replacement Cost (£)
Timber buit in cupboards	Faii	No action required	В	17	2	No	1,640 Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :	F	LOOR : Ground			
ROOM : Kitchen	No : 002/8/	/0/007	USE :			
Element : Worktops	CODE :6					Replacement
Description Laminate / chipboard worktop	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 7	Quantity 9 m2	Cost (£) 615
						Year 1 Repair Cost (£)
Element : Built in cupboards	CODE :6					Replacement
Description Timber buit in cupboards	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 22	Quantity 1 No	Cost (£) 820
						Year 1 Repair Cost (£)
Element : Built in cupboards	CODE : 6					Replacement
Description Timber buit in cupboards	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 17	Quantity 12 No	Cost (£) 9,843
						Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Ground				
ROOM : Circulation Area	No : 002	2/8/0/008	USE :				
Element : Built in cupboards Description Timber buit in cupboards	CODE : 6 Condition Fair	Action No action required	Cond/Ind Priority B	7 L'Expec 17	Quan 3	tity No	Replacement Cost (£) 2,460
							Year 1 Repair Cost (£)

SANITARY

BUILDING : Block 01 Kyd	UPRN :		FLOOR : Ground				
ROOM : Store	No : 0	02/1/0/010	USE :				
Element : Sinks	CODE :7						Replacement
Description	Condition	Action	Cond/Ind Prior	ity L'Expec	Qua	ntity	Cost (£)
Stainless steel sink - single drainer	Fair	No action required	В	13	1	No	328
							Year 1 Repair Cost (£

BUILDING : Block 01 Kyd ROOM : Kitchen	UPRN :	2/1/0/016	FLOOR : Ground USE :				
ROOM : Kitchen	NO : 002	2/1/0/016	U3E :				
Element : Sinks	CODE : 7				0		Replacement
Description	Condition	Action	Cond/Ind Prior	•	Quar	•	Cost (£)
Stainless steel sink	Fair	No action required	В	13	2	No	656
							Year 1 Repair Cost (£)

UPRN	:	FLOOR : Ground				
) No	: 002/1/0/017	USE :				
CODE : 7	Antinu			0		Replacement
		•	•	Quan	•	Cost (£)
Fair	No action required	В	13	1	NO	410
						Year 1 Repair Cost (£)
) No	CODE : 7 Condition Action	No: 002/1/0/017 USE: CODE:7 Condition Action Cond/Ind Priority	No: 002/1/0/017 USE: CODE:7 Condition Action Cond/Ind Priority L'Expect	No: 002/1/0/017 USE: CODE:7 Condition Action Cond/Ind Priority L'Expec Quant	No: 002/1/0/017 USE: CODE:7 Condition Action Cond/Ind Priority L'Expec Quantity

BUILDING : Block 01 Kyd ROOM : Store	UPRN : No : 002	2/1/0/017A	FLOOR : Gr USE :	round				
Element : Sinks Description Stainless steel cleaner's sink	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 13	Quanti 1	ty No	Replacement Cost (£) 328
								Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Toilet	UPRN : No : 002/	/1/0/026	FLOOR : Ground USE :					
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		d/Ind Priority B	L'Expec 15	Quantit <u>y</u> 1	/ No	Replacement Cost (£) 328 Year 1 Repair Cost (£)
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		d/Ind Priority B	L'Expec 10	Quantity 1	/ No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd ROOM : Bathroom	UPRN : No : 002/	/1/1/002	FLOOR : Fi USE :	irst				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1	No	Replacement Cost (£) 328 Year 1 Repair Cost (£)
Element : Baths Description Pressed steel bath	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1	, No	Replacement Cost (£) 656 Year 1 Repair Cost (£

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : First			
ROOM : Toilet 7	No : 002/1	1/1/005	USE :			
Element : WC	CODE : 7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE :7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Shower cabinet with prefinished board walls and glazed doors	Fair	No action required	В	18	1 No	1,148
board wails and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : First			
ROOM : Toilet 6	No : 002/1	1/1/007	USE :			
Element : WC	CODE : 7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE :7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : First			
ROOM : Toilet	No : 002/1	/1/009	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action	Cond/Ind Priority B	 L'Expec 23 	Quantity 1 No	Replacement Cost (£) 328
Ceramic WC distern and bown	Fair	No action required	Б	23	ΙΝΟ	³²⁸ Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	 L'Expec 18 	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

UPRN :		FLOOR : First				
No : 00	2/1/1/010	USE :				
CODE : 7						Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Fair	No action required	В	13	1	No	328
						Year 1 Repair Cost (£)
	No : 00 CODE : 7 Condition	No: 002/1/1/010 CODE:7 Condition Action	No: 002/1/1/010 USE: CODE:7 Condition Action Cond/Ind Priority	No: 002/1/1/010 USE: CODE:7 Condition Action Cond/Ind Priority L'Expect	No: 002/1/1/010 USE: CODE:7 Condition Action Cond/Ind Priority L'Expec Quant	No: 002/1/1/010 USE: CODE:7 Condition Action Cond/Ind Priority L'Expec Quantity

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : First			
ROOM : Toilet 4	No : 002/1	///013	USE :			
Element : WC	CODE :7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Pric	ority L'Expec	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE :7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Pric	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description	Condition	Action	Cond/Ind Price	ority L'Expec	Quantity	Cost (£)
Shower cabinet with prefinished board walls and glazed doors	Fair	No action required	В	18	1 No	1,148
board wails and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : First			
ROOM : Toilet 3	No : 002/1	1/1/016	USE :			
Element : WC	CODE : 7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE :7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Shower cabinet with prefinished	Fair	No action required	В	18	1 No	1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	F	FLOOR : First			
ROOM : Toilet 2	No : 002/ ²	1/1/019	USE :			
Element : WC	CODE : 7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Shower cabinet with prefinished board walls and glazed doors	Fair	No action required	В	18	1 No	1,148
board wails and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 01 Kyd	UPRN :	I	FLOOR : First	st			
ROOM : Toilet 1	No : 002/1	/1/022	USE :				
Element : WC	CODE:7						Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
							Year 1 Repair Cost (£)
Element : Basins	CODE : 7						Replacement
Description Ceramic WHB	Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
							Year 1 Repair Cost (£)
Element : Showers	CODE : 7						Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door	, un			5	10		Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Toilet	UPRN : No : 002/2	2/0/004	FLOOR : Ground USE :					
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328 Year 1 Repair Cost (£	
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		nd Priority	L'Expec 23	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :		FLOOR : Ground			
ROOM : Toilet	No : 002/2/0)/005	USE :			
Element : WC	CODE:7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Basins	CODE : 7					Donlagoment
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic WHB	Fair	No action required	В	23	1 No	328
						Year 1 Repair Cost (£)
Element : Cubicles	CODE : 7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Laminated toilet cubicle	Fair	No action required	В	23	1 No	820
						Year 1 Repair Cost (£)
Element : Urinals	CODE : 7					Deplessment
Description Ceramic urinal	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 492
						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : Circulation Area	UPRN : No : 002	2/2/0/008	FLOOR : Gro USE :	ound				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1	y No	Replacement Cost (£) 328
								Year 1 Repair Cost (£)
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantit	y No	Replacement Cost (£) 328
								Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	FI	LOOR : Ground			
ROOM : Toilet 8	No : 002/2/0/0	011	USE :			
Element : WC Description	CODE : 7 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic WC cistern and bowl	Fair	No action required	B	23	1 No	328
						Year 1 Repair Cost (£
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	F	LOOR : Ground			
ROOM : Toilet 9	No : 002/2/0/	/013	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
Ceramic WC cistern and bowi				20		Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	F	LOOR : First			
ROOM : Toilet 22	No : 002	2/2/1/003	USE :			
Element : WC	CODE : 7					Poplacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	F	FLOOR : First			
ROOM : Toilet 21	No : 002	2/2/1/006	USE :			
Element : WC	CODE :7					Poplacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	I	FLOOR : First			
ROOM : Toilet 20	No : 002	2/2/1/011	USE :			
Element : WC	CODE :7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	F	LOOR : First			
ROOM : Toilet 19	No : 002	2/2/1/016	USE :			
Element : WC	CODE : 7					Poplacomont
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	F	FLOOR : First			
ROOM : Toilet 18	No : 002	2/2/1/020	USE :			
Element : WC	CODE : 7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	F	FLOOR : First			
ROOM : Toilet 24	No : 002	2/2/1/025	USE :			
Element : WC	CODE:7					Poplacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney	UPRN :	F	LOOR : First			
ROOM : Toilet 23	No : 002	2/2/1/028	USE :			
Element : WC	CODE : 7					Poplacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie UI ROOM : Store		IPRN : F No : 002/3/0/005		FLOOR : Ground USE :					
Element : Cleaners & Belfast Si Description Ceramic cleaners/Belfast sink	nks CODE : 7 Condition Fair	Action No action rea	quired	Cond/Ind Priority B	L'Expec 23	Quantity 1 No		Replacement Cost (£) 656	
								Year 1 Repair Cost (£)	

BUILDING : Block 03 Dalhousie	UPRN :	F	LOOR : Ground			
ROOM : Toilet 12A	No : 002	2/3/0/008	USE :			
Element : WC	CODE :7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 13	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :	F	LOOR : Ground			
ROOM : Toilet 12	No : 002/3/0	/010	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 13	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£

BUILDING : Block 03 Dalhousie	UPRN :	F	LOOR : Ground			
ROOM : Toilet 11	No : 002/3	3/0/012	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE :7 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Replacement Cost (£) 328
				10		Year 1 Repair Cost (£)
Element : Basins	CODE :7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 13	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£

BUILDING : Block 03 Dalhousie	UPRN :	F	LOOR : Ground			
ROOM : Toilet 10	No : 002	2/3/0/014	USE :			
Element : WC Description	CODE : 7	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic WC cistern and bowl	Fair	No action required	В	18	1 No	328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Shower cabinet with prefinished board walls and glazed door	Fair	No action required	В	13	1 No	1,148
board wails and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :		FLOOR : Fir	st			
ROOM : Bathroom	No : 002/3/1/0	002	USE :				
Element : WC	CODE:7						Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
							Year 1 Repair Cost (£)
Element : Basins	CODE : 7						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic WHB	Fair	No action required		В	18	1 No	328
							Year 1 Repair Cost (£)
Element : Baths	CODE : 7						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic bath	Fair	No action required		В	18	1 No	656
							Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :	F	LOOR : First			
ROOM : Toilet 17	No : 002/3	3/1/004	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Replacement Cost (£) 328
Ceramic WC cistern and bowl	Fall	No action required	В	18	I NO	320 Year 1 Repair Cost (£)
Element : Basins	CODE :7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 13	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :	F	FLOOR : First			
ROOM : Toilet 16	No : 002	/3/1/006	USE :			
Element : WC	CODE:7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 13	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie ROOM : Store	RN : No : 002/3/1/008	FLOOR : F USE :	irst					
Element : Cleaners & Belfast Si Description Ceramic cleaners/Belfast sink	CODE : 7 Condition Action		Cond/Ind Priority B	L'Expec 23	Quantity 1 No		Replacement Cost (£) 656	
							Year 1 Repair Cost (£)	

BUILDING : Block 03 Dalhousie	UPRN :	F	LOOR : First			
ROOM : Toilet 15	No : 002/3	3/1/011	USE :			
Element : WC Description	CODE : 7 Condition	Action	Cond/Ind Priority	•	Quantity	Replacement Cost (£)
Ceramic WC cistern and bowl	Fair	No action required	В	18	1 No	328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Shower cabinet with prefinished	Fair	No action required	В	13	1 No	1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 03 Dalhousie	UPRN :	F	LOOR : First			
ROOM : Toilet 14	No : 002	/3/1/013	USE :			
Element : WC	CODE:7					Poplacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 13	Quantity 1 No	Cost (£) 1,148
board walls and glazed door						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :		FLOOR : Ground			
ROOM : Male WC	No : 002/4/	/0/003	USE :			
Element : WC	CODE:7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Basins	CODE : 7					Doulocomout
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic WHB	Fair	No action required	В	23	1 No	328
						Year 1 Repair Cost (£)
Element : Cubicles	CODE : 7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Shower cubicle	Fair	No action required	В	23	1 No	820
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Doulocomout
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Shower heads/mixer valve	Fair	No action required	В	18	1 No	1,148
						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Groun	d			
ROOM : Toilet 39	No : 002/4/	0/006	USE :				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Co	n d/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
							Year 1 Repair Cost (£
Element : Basins	CODE:7						Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Co	n d/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
							Year 1 Repair Cost (£
Element : Showers	CODE : 7						Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Co	n d/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors							Year 1 Repair Cost (£

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Ground			
ROOM : Toilet 38	No : 002/4/0)/008	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Ground			
ROOM : Toilet 37	No : 002/4	/0/011	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
Ceramic WC cistem and bow			L	20		Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Poplacoment
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Replacement Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : Ground			
ROOM : Toilet 36	No : 002/4/	/0/013	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE:7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Ground			
ROOM : Toilet 45	No : 002/4/0)/020	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Ground			
ROOM : Toilet 44	No : 002/4/0	0/022	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	 L'Expec 23 	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	 L'Expec 18 	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Ground			
ROOM : Toilet 43	No : 002/4/0	0/024	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	 L'Expec 23 	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE:7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	 L'Expec 18 	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Ground			
ROOM : Toilet 42	No : 002/4/0	0/027	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Ground			
ROOM : Toilet 41	No : 002/4/	/0/029	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	LOOR : Ground			
ROOM : Toilet 40	No : 002/4/0/	/031	USE :			
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE : 7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£
Element : Showers	CODE : 7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet	UPRN : No : 002/4/0/032		FLOOR : Ground USE :					
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Replacement Cost (£) 328 Year 1 Repair Cost (£	
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1	/ No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : First			
ROOM : Toilet 25	No : 002/2	4/1/004	USE :			
Element : WC	CODE : 7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE :7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priorit B	y L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description	Condition	Action	Cond/Ind Priorit	y L'Expec	Quantity	Cost (£)
Shower cabinet with prefinished	Fair	No action required	В	18	1 No	1,148
ooard walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Bathroom	UPRN : FL No : 002/4/1/005		FLOOR : First USE :					
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1 No	•	Replacement Cost (£) 328 Year 1
Flamant - Dotho	CODE + 7							Repair Cost (£)
Element : Baths Description Ceramic bath	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantit 1	y No	Replacement Cost (£) 656
								Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 26	UPRN : No : 002/4/1/007		FLOOR : Fin USE :					
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 27	UPRN : I No : 002/4/1/009		FLOOR : Fi USE :	LOOR : First USE :					
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)	
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantity 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)	

BUILDING : Block 04 Keays ROOM : Toilet 28	UPRN : No : 002/4/1/012		FLOOR : F	FLOOR : First USE :				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantit 1	: y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 29	UPRN : No : 002/4/1/014		FLOOR : Fi USE :	irst				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantit 1	Quantity 1 No	Replacement Cost (£) 328 Year 1 Repair Cost (£)
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 23	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays	UPRN :	F	FLOOR : First			
ROOM : Toilet 30	No : 002/4	4/1/016	USE :			
Element : WC	CODE : 7					Replacement
Description Ceramic WC cistern and bowl	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Basins	CODE :7					Replacement
Description Ceramic WHB	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 23	Quantity 1 No	Cost (£) 328
						Year 1 Repair Cost (£)
Element : Showers	CODE :7					Replacement
Description Shower cabinet with prefinished	Condition Fair	Action No action required	Cond/Ind Priority B	L'Expec 18	Quantity 1 No	Cost (£) 1,148
board walls and glazed doors						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 31	UPRN : No : 002/4/1/021		FLOOR : F USE :	irst				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	I	Cond/Ind Priority B	L'Expec 15	Quantii 1	ty No	Replacement Cost (£) 328 Year 1 Repair Cost (£
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required	l	Cond/Ind Priority B	L'Expec 2	Quantin 1	ty No	Replacement Cost (£) 328 Year 1 Repair Cost (£

BUILDING : Block 04 Keays ROOM : Toilet 32	UPRN : No : 002/4/1/023		FLOOR : Fi USE :	rst				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 15	Quantity 1 No	Replacement Cost (£) 328 Year 1 Repair Cost (£)	
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 2	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 33	UPRN : No : 002/4/1/026		FLOOR : First USE :							
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	Cond B	'Ind Priority	L'Expec 15	Quantity 1	/ No	Replacement Cost (£) 328 Year 1 Repair Cost (£)		
Element : Basins Description Ceramic WHB	CODE : 7 Condition Poor	Action Replace	Cond C	Ind Priority 4	L'Expec Replace/In	Quantity 1	/ No	Replacement Cost (£) 328 Year 1 Repair Cost (£		

BUILDING : Block 04 Keays ROOM : Toilet 34	UPRN : No : 002/4/1/028		FLOOR : Fi USE :	FLOOR : First USE :				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 15	Quantit 1	Quantity 1 No	Replacement Cost (£) 328 Year 1 Repair Cost (£)
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 2	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : Toilet 35	UPRN : No : 002/4/1/030		FLOOR : Fi USE :	irst				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 15	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 2	Quantit 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A	UPRN :		FLOOR : Ground				
ROOM : Kitchen	No : 00	2/7/0/002	USE :				
Element : Sinks	CODE :7						Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quan	tity	Cost (£)
Plastic sink and drainer	Fair	No action required	В	12	1	No	328
							Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A	UPRN :	I	FLOOR : Grou	und			
ROOM : Bathroom	No : 002/7/0	/004	USE :				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required	C	Cond/Ind Priority B	L'Expec 22	Quantity 1 No	Replacement Cost (£) 328 Year 1 Repair Cost (£
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required	(Cond/Ind Priority B	L'Expec 22	Quantity 1 No	Replacement Cost (£) 328 Year 1 Repair Cost (£
Element : Showers Description Shower cabinet with glazed door	CODE : 7 Condition Fair	Action No action required	(Cond/Ind Priority B	L'Expec 17	Quantity 1 No	Replacement Cost (£) 1,148 Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :	FI	LOOR : Ground			
ROOM : Bathroom	No : 002/8/0/00	5	USE :			
Element : WC	CODE:7					Bonlocomont
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Ceramic WC bowl and plastic cistern	Fair	No action required	В	17	1 No	328
						Year 1 Repair Cost (£
Element : Basins	CODE : 7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Ceramic WHB	Fair	No action required	В	17	1 No	328
						Year 1 Repair Cost (£)
Element : Showers	CODE : 7					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Shower cabinet with prefinished board walls and glazed door	Fair	No action required	В	12	1 No	1,148
Soard wails and glazed door						Year 1 Repair Cost (£

BUILDING : Block 08 Lodge ROOM : Toilet	UPRN : No : 002	2/8/0/006	FLOOR : Gro USE :	und				
Element : WC Description Ceramic WC cistern and bowl	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 17	Quantity 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)
Element : Basins Description Ceramic WHB	CODE : 7 Condition Fair	Action No action required		Cond/Ind Priority B	L'Expec 17	Quantity 1	y No	Replacement Cost (£) 328 Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :		FLOOR : Grou	Ind				
ROOM : Kitchen	No : 002	2/8/0/007	USE :					
Element : Sinks Description	CODE : 7	Action	<u> </u>	Cond/Ind Priority	L'Expec	Quanti	ta z	Replacement Cost (£)
Plastic sink and drainer	Fair	No action required		B	с Ехрес 7	Quanti 1	No	328
								Year 1 Repair Cost (£)

MECHANICAL SERVICES

BUILDING : Block 01 Kyd ROOM : M & E	UPRN : No : 002/1/M&E	FLOOR : Ma	ξE			
Element : Gas Heating System	CODE : 13					Poplacement
Description Heating was provided by 2 Remeha Quinta 65 Gas fired boilers. Hot water from the system was pumped round the bld to a number of convection radiators, by a Grundfos pumping setup.	Condition The heating and its associated equipment were in fair condition however it was noted that the control of the radiators via the TRV's was poor, within rooms 3, 5 & 7 the radiators were cold when on settings 3 & 4, when TRV turned slightly the radiator appeared to heat to maximum temperature.	Action Continue maintenance It is recommended that the set up of the TRV's is investigated.	Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 40,000 Year 1 Repair Cost (£)

Element : Extraction System	CODE :13					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
There was a mix of Manrose, Vectaire and Vent Axia single	The condition of these were fair	Continue Maintenance	В	15		30,000
point extractors in use within the toilets in the resident's rooms. Single point Delta Extract extractors are installed within communal toilets. Within the kitchen an industrial Canopy Extractor was installed and a Vent Axia extractor fitted. A mix of Vent Axia and Xpelair extraction units were installed within the Laundry room.						Year 1 Repair Cost (£)

with no defects noted.

Element : Domestic Hot Water	CODE : 13					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Hot water was provided by two A.O.Smith Gas Fired DHW	The condition of this was fair with no defects noted.	Continue Maintenance	В	15		20,000
Boilers. The water was pumped throughout the bld by Grundfos pumps. All pipework was lagged and identified.						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : M & E	UPRN : No : 002/2/M&E	FLOOR : M /M&E USE :	&E			
Element : Gas Heating System Description Heating was provided by 2 Remeha Quinta 65 Gas fired boilers. Hot water from system was pumped round the bld to a number of convection radiators, by a Grundfos pumping setup.	CODE : 13 Condition The heating and its associated equipment were in fair condition with no defects evident. However within the boiler room there was evidence of water pooling on the floor. There was also a hose within the boiler room which appeared to be redundant,	Action Continue maintenance the source of the pool of water is unknown and should be investigated further. it is recommended that the hose purpose be ascertained.	Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 40,000 Year 1 Repair Cost (£)

Photo 1



Photo 2

Position

Element : Domestic Hot Water

Descripti

Hot water main boile water was bld by Gru pipework v identified. ayyı

nt: Domestic Hot Water	CODE :13					Replacement
otion	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
ter was provided by the biler to a Calorfier, the	The condition of this was fair	Continue Maintenance	В	15		25,000
vas pumped throughout the Grundfos pumps. All rk was lagged and						Year 1 Repair Cost (£)

with no defects noted.

BUILDING : Block 03 Dalhousie	UPRN :	F	LOOR : M&	&Е			
ROOM : M & E	No : 002/3/M&B	E/M&E	USE :				
Element : Gas Heating System Description Heating was provided by 2 Remeha Quinta 65 Gas fired boilers located in the mcKinney block. Hot water from system was pumped round the bld to a	CODE : 13 Condition The heating and its associated equipment were in fair condition with no defects evident.	Action Continue maintenance	1	Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 10,000 Year 1 Repair Cost (£
number of convection radiators, by a Grundfos pumping setup.							
Element : Extraction System	CODE : 13						Replacement
Description There was a mix of Manrose, Vectaire and Vent Axia single point extractors in use within the toilets in the resident's rooms.	Condition The condition of these were fair with no defects noted.	Action Continue Maintenance		Cond/Ind Priority B	L'Expec 15	Quantity	Cost (£) 800 Year 1 Repair Cost (£
Element : Domestic Hot Water	CODE : 13						Replacement
Description Hot water was provided by an electric Calorfier, the water was	Condition The condition of this was fair with no defects noted.	Action Continue Maintenance		Cond/Ind Priority B	L'Expec 15	Quantity	Cost (£) 15,000
pumped throughout the bld by Grundfos pumps.							Year 1 Repair Cost (£

BUILDING : Block 04 Keays	UPRN :	FI	LOOR : M&	E			
ROOM : M & E	No : 002/4/M&I	E/M&E	USE :				
Element : Gas Heating System	CODE :13						Poplacement
Description Heating was provided by a	Condition The heating and its associated	Action Continue maintenance		Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 50,000
Powrmatic Gas fired boiler. Hot water from system was pumped round the bld to a number of convection radiators by a Grundfos pumping setup.	equipment were in fair condition with no defects evident.						Year 1 Repair Cost (/
Element : Extraction System	CODE : 13						Replacement
Description	Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Cost (£)
There was a mix of Manrose, Vectaire and Vent Axia single	The condition of these were fair with no defects noted.	Continue Maintenance		В	15		8,000
point extractors in use within the toilets in the resident's rooms.							Year 1 Repair Cost (
Element : Domestic Hot Water	CODE : 13						
Description	Condition	Action		Cond/Ind Priority	l 'Expec	Quantity	Replacemen

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Hot water was provided by the	The condition of this was fair	Continue Maintenance	В	15		20,000
main boiler to a Calorfier, the	with no defects noted.					
water was pumped throughout the	9					Year 1
bld by Grundfos pumps. All						Repair Cost (£)
pipework was lagged and						
identified.						

BUILDING : Block 05 Dining ROOM : M & E	UPRN : No : 002/5//	FLOOR : USE :	M & E			
Element : Extraction System Description The dining area has a Roof Units		Action Continue Maintenance	Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 30,000
Group extraction system in place.	no defects noted.					Year 1 Repair Cost (£)

BUILDING : Block 06 Greenhouse ROOM : M & E	e UPRN : No : 002/6/M&B		LOOR : M&E USE :			
Element : Electrical Heating Syster	Condition	Action	Cond/Ind Priority	•	Quantity	Replacement Cost (£)
This consisted of electric tubular heaters.	The heating and its associated equipment were in fair condition with no defects evident.	Continue maintenance	В	15		750 Year 1 Repair Cost (£)

BUILDING : Block 07 Flat 1A	UPRN :	F	LOOR : M&E			
ROOM : M & E	No : 002/6/M&I	E/M&E	USE :			
Element : Gas Heating System Description Heating was provided by boilers within the Keays block of the main bld. Hot water from the system was pumped round the bld to a number of convection radiators.	CODE : 13 Condition The heating and its associated equipment were in fair condition with no defects evident.	Action Continue maintenance	Cond/Ind Prior	ity L'Expec 15	Quantity	Replacement Cost (£) 1,000 Year 1 Repair Cost (£
Element : Extraction System Description Within the toilet an Aidelle Loovent extractor is fitted and a domestic extractor hood is fitted within the kitchen.	CODE : 13 Condition The condition of these were fair with no defects noted.	Action Continue Maintenance	Cond/Ind Prior B	ity L'Expec 15	Quantity	Replacement Cost (£) 150 Year 1 Repair Cost (£
Element : Domestic Hot Water Description Hot water was supplied by a 3Kw single electric immersion Calorfiel		Action Continue Maintenance	Cond/Ind Prior B	ity L'Expec 15	Quantity	Replacement Cost (£) 1,000 Year 1 Repair Cost (£

BUILDING : Block 08 Lodge	UPRN :	FLO	DR:M&E			
ROOM : M & E	No : 002/8/M&E	E/M&E U	SE :			
Element : Gas Heating System Description Heating was provided by a Saunier Duval Combi-boiler. Hot water from system was pumped round the bld to a number of convection radiators.	CODE : 13 Condition The heating and its associated equipment were in fair condition with no defects evident.	Action Continue maintenance	Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 7,000 Year 1 Repair Cost (£
Element : Extraction System Description Within the shower a domestic extractor fitted and a domestic extractor hood is fitted within the kitchen.	CODE : 13 Condition The condition of these were fair with no defects noted.	Action Continue Maintenance	Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 200 Year 1 Repair Cost (£
Element : Domestic Hot Water Description Hot water was supplied by the Combi-boiler to the kitchen, toilet and bathroom.	CODE : 13 Condition The condition of this was fair with no defects noted.	Action Continue Maintenance	Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 1,000 Year 1 Repair Cost (£

ELECTRICAL SERVICES

BUILDING : Block 01 Kyd ROOM : M & E	UPRN : No : 002/1/M&E	FLOOR : M	&E			
Element : Incoming Mains & Meter Description	ering CODE : 14 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Power is supplied from the main REC supplies. This feeds a switching system supplying a number of Distribution Boards (DB).	All were in fair condition. However it was noted that no statutory signage was evident. Evidence of cables disconnected from the DB and left in place.	Continue Maintenance Provide Statutory Signage BS7671 states that all redundant cabling should be removed.	В	20		15,000 Year 1 Repair Cost (£)

Photo 1

Photo 2

Position

Element : Mains Distribution

CODE : 14

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Power distribution was via a mix of Wylex, GEC and Merlin Gerin	All were in a fair condition with no	Continue Maintenance	В	20		55,000
DBs located around the bld. Wiring was contained within trunking. This also houses the IT						Year 1 Repair Cost (£)

& Telephone system.

defects noted. However there was It is recommended that the use of evidence of extension leads and 3- extensions is reviewed and the way adapters in use throughout the bld. removal of 3-way adapters is considered.





Photo 2

Position

Element : Light Fittings Internal	CODE:14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
In the main this was T8, (fitted with anti glare diffusers) tungsten	The condition of the system was fair with no defects noted.	Continue maintenance This survey did not look at	В	20		25,000
and 2D fluorescent fittings. The		system compliance, a further				Year 1
corridors were controlled by PIR's		lighting compliance survey would				Repair Cost (£)
all other lighting were manually		be required.				
controlled.						

Element : Light Fittings Internal	CODE : 14					Replacement
Description This consisted of a mix of maintained and non-maintained self contained fittings.	Condition The condition of the system was fair with no defects noted.	Action Continue maintenance This survey did not look at system compliance, a further lighting compliance survey would be required.	Cond/Ind Priority B	L'Expec 20	Quantity	Cost (£) 8,000 Year 1 Repair Cost (£)
Element : Light Fittings External	CODE : 14					Replacement
Description This consisted of a number of	Condition The condition of the lighting and	Action Continue Maintenance	Cond/Ind Priority B	L'Expec 20	Quantity	Cost (£) 2,500
Halogen Floodlight and Spotlights which are controlled by dawn/dusk sensors.	its associated equipment was fair with no defects noted.	This survey did not look at system compliance, a further in depth compliance survey would be required.	D	20		2,500 Year 1 Repair Cost (£)
Element : I.T.	CODE : 14					Replacement
Description The bld is connected to the main	Condition The condition of the IT network	Action Continue Maintenance	Cond/Ind Priority B	L'Expec 20	Quantity	Cost (£) 150
Council IT network via a Netgear Router located within the Managers office. This provides a secure wireless network throughout the building.	was fair with no defects noted.					Year 1 Repair Cost (£)

Element : C.C.T.V.	CODE : 14					Replacement
Description A 7-camera CCTV system is in	Condition The condition of these was fair	Action Continue Maintenance	Cond/Ind Priority B	L'Expec 20	Quantity	Cost (£) 10,000
use. This covers the entrances and the ground boundaries .	with no defects noted.					Year 1 Repair Cost (£)
Element : Fire Alarms Description	CODE : 14 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
An automatic system consisting of a number of break glass manual call points, detectors and	The condition of the system was fair with no defects noted.	Continue Maintenance. This survey did not look at system compliance, a further in	В	20	Ĩ	15,000 Year 1
audible alarms connected to a Gent Vigilon Compact control		depth compliance survey would be required.				Repair Cost (£)

Element : Security Systems	CODE :14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
There is a secure door entry installed and the bld is protected	The condition of this was fair with no defects noted.	Continue maintenance	В	20		13,000
by a Nova alarm system.						Year 1 Repair Cost (£)

BUILDING : Block 02 McKinney ROOM : M & E	UPRN : No : 002/2/M&E	FLOOR : M /M&E USE :	&E			
Element : Mains Distribution Description	CODE : 14 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Power distribution was via a mix of Wylex, GEC and Merlin Gerin DBs located around the bld. Wiring was contained within trunking. This also houses the IT & Telephone system.	All were in a fair condition with no defects noted. However there was evidence of extensions in use.	Continue Maintenance It is recomended that the use of extensions is reviewed	В	20		40,000 Year 1 Repair Cost (£)

Element : Light Fittings Internal	CODE : 14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
In the main this was T8, (fitted with anti glare diffusers) tungsten	The condition of the system was fair with no defects noted.	Continue maintenance This survey did not look at	В	20		25,000
and 2D fluorescent fittings. The		system compliance, a further				Year 1
corridors were controlled by PIR's		lighting compliance survey would				Repair Cost (£)
all other lighting were manually controlled.		be required.				

Element : Light Fittings Internal	CODE :14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
This consisted of a mix of maintained	The condition of the system was fair with no defects noted.	Continue maintenance This survey did not look at	В	20		8,000
self contained fittings.		system compliance, a further lighting compliance survey would be required.				Year 1 Repair Cost (£)

Element : Light Fittings External	CODE : 14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
This consisted of a number of Halogen Floodlight and Spotlights	The condition of the lighting and its associated equipment was fair	Continue Maintenance This survey did not look at	В	20		2,500
which are controlled by dawn/dusk sensors.	with no defects noted.	system compliance, a further in depth compliance survey would be required.				Year 1 Repair Cost (£)
Element : Fire Alarms	CODE : 14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
An automatic system consisting of a number of break glass	The condition of the system was fair with no defects noted.	Continue Maintenance. This survey did not look at	В	20		10,000
manual call points, detectors and		system compliance, a further in				Year 1
audible alarms connected to the main Gent Vigilon Compact		depth compliance survey would be required.				Repair Cost (£)

manual call points, detectors and audible alarms connected to the main Gent Vigilon Compact control panel.

BUILDING : Block 03 Dalhousie	UPRN :	FLOOR :	M&E			
ROOM : M & E	No : 002/3/M&E	/M&E USE :				
Element : Mains Distribution	CODE : 14					Replacement
Description Power distribution was via a mix	Condition All were in a fair condition with no	Action Continue Maintenance	Cond/Ind Priority B	L'Expec 20	Quantity	Cost (£) 15,000
of Wylex, GEC and Merlin Gerin DBs located around the bld. Wiring was contained within trunking. This also houses the IT & Telephone system.	defects noted.					Year 1 Repair Cost (£
Element : Light Fittings Internal	CODE :14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
In the main this was T8, (fitted with anti glare diffusers) tungsten	The condition of the system was fair with no defects noted.	Continue maintenance This survey did not look at	В	20		10,000
and 2D fluorescent fittings. The		system compliance, a further				Year 1
corridors were controlled by PIR's all other lighting were manually controlled.		lighting compliance survey wou be required.	ıld			Repair Cost (£

Repair Cost (£)	Repair	r Cost	(£)
-----------------	--------	--------	-----

Element : Light Fittings Internal	CODE : 14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
This consisted of a mix of maintained and non-maintained	The condition of the system was fair with no defects noted.	Continue maintenance This survey did not look at	В	20		5,000
self contained fittings.		system compliance, a further lighting compliance survey would be required.				Year 1 Repair Cost (£)

CODE :14					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
		В	20		1,000
with no defects noted.	system compliance, a further in depth compliance survey would be required.				Year 1 Repair Cost (£)
CODE : 14					
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
The condition of the system was	Continue Maintenance.	В	20	-	6,000
fair with no defects noted.	This survey did not look at				
	Condition The condition of the lighting and its associated equipment was fair with no defects noted. CODE : 14 Condition	ConditionActionThe condition of the lighting and its associated equipment was fair with no defects noted.Continue Maintenance This survey did not look at system compliance, a further in depth compliance survey would be required.CODE : 14Action	ConditionActionCond/IndPriorityThe condition of the lighting and its associated equipment was fair with no defects noted.Continue Maintenance This survey did not look at system compliance, a further in depth compliance survey would be required.BIICODE : 14ConditionActionCond/IndPriority	Condition The condition of the lighting and its associated equipment was fair with no defects noted.ActionCond/Ind PriorityL'ExpecB20This survey did not look at system compliance, a further in depth compliance survey would be required.B20CODE :14ActionCond/Ind PriorityL'Expec	Condition The condition of the lighting and its associated equipment was fair with no defects noted.ActionCond/Ind PriorityL'ExpecQuantityB202

main Gent Vigilon Compact control panel.

BUILDING : Block 04 Keays	UPRN :	FLOO	R : M&E			
ROOM : M & E	No : 002/4/M&E	I/M&E US	E :			
Element : Mains Distribution	CODE : 14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
Power distribution was via a mix	All were in a fair condition with no	Continue Maintenance	В	20		50,000
of Wylex, GEC and Merlin Gerin DBs located around the bld. Wiring was contained within trunking. This also houses the IT & Telephone system.	defects noted.					Year 1 Repair Cost (
Element : Light Fittings Internal	CODE : 14 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
n the main this was T8, (fitted	The condition of the system was	Continue maintenance	В	20	•	25,000
with anti glare diffusers) tungsten and 2D fluorescent fittings. The	fair with no defects noted.	This survey did not look at system compliance, a furth				Year 1

and 2D fluorescent fittings. The corridors were controlled by PIR's all other lighting were manually controlled.

Element : Light Fittings Internal

CODE:14

Replacement Condition Action Cond/Ind Priority Cost (£) Description L'Expec Quantity This consisted of a mix of The condition of the system was Continue maintenance В 20 8,000 fair with no defects noted. This survey did not look at maintained and non-maintained system compliance, a further self contained fittings. Year 1 lighting compliance survey would Repair Cost (£) be required.

lighting compliance survey would

be required.

Repair Cost (£)

Element : Light Fittings External	CODE : 14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
This consisted of a number of Halogen Floodlight and Spotlights	The condition of the lighting and its associated equipment was fair	Continue Maintenance This survey did not look at	В	20		2,500
which are controlled by dawn/dusk sensors.	with no defects noted.	system compliance, a further in depth compliance survey would be required.				Year 1 Repair Cost (£)
Element : Fire Alarms	CODE : 14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
An automatic system consisting of a number of break glass	The condition of the system was fair with no defects noted.	Continue Maintenance. This survey did not look at	В	20		10,000
manual call points, detectors and		system compliance, a further in				Year 1
audible alarms connected to the main Gent Vigilon Compact		depth compliance survey would be required.				Repair Cost (£)

manual call points, detectors and audible alarms connected to the main Gent Vigilon Compact control panel.

BUILDING : Block 05 Dining ROOM : M & E	UPRN : No : 002/5//	FLOOR : M USE :	& E			
Element : Light Fittings Internal Description	CODE : 14 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
This consisted of T8, (fitted with anti glare diffusers) fluorescent fittings.	The condition of the system was fair with no defects noted.	Continue maintenance This survey did not look at system compliance, a further lighting compliance survey would be required.	В	20	,	5,000 Year 1 Repair Cost (£)

Action Action e system was Contin noted.	USE : n nue maintenance	Cond/Ind Priority B	L'Expec 20	Quantity	Replacement Cost (£)
e system was Contir		•		Quantity	•
iotea.			-		500
					Year 1 Repair Cost (£)
					Replacement
Actio	n	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
	nue Maintenance	В	20		50
u.					Year 1 Repair Cost (£)
			s was fair Continue Maintenance B	s was fair Continue Maintenance B 20	s was fair Continue Maintenance B 20

BUILDING : Block 07 Flat 1A	UPRN :	F	LOOR : M&E			
ROOM : M & E	No : 002/6/M&E	/M&E	USE :			
	CODE : 14 Condition All were in a fair condition with no	Action Continue Maintenance	Cond/Ind Priority B	L'Expec 20	Quantity	Replacement Cost (£) 5,000
DB located within a cupboard in the hallway. Wiring was contained within the walls of the bld.	defects noted.					Year 1 Repair Cost (f
Element : Sub Mains Distribution	CODE : 14					Replacement

st (£)
)
ar 1
pair Cost (£)

Photo 1

Element : Light Fittings Internal **CODE**:14 Replacement Condition Action Cond/Ind Priority L'Expec Cost (£) Description Quantity The condition of the system was fair with no defects noted. Continue maintenance This survey did not loo In the main this was a mix of В 20 1,000 tungsten, CFL, and T8 fittings. This survey did not look at There were no signs of automatic system compliance, a further Year 1 lighting compliance survey would controls. Repair Cost (£) be required.

Element ·	Light Fittings	External
Liement.	Light i ittings i	

CODE : 14

Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
This consisted of tungsten fitting with PIR control front of the bld.	The condition of the lighting and its associated equipment was fair		В	20		250
At the rear of the bld there is a Halogen fitting with PIR control.	with no defects noted.	system compliance, a further in depth compliance survey would be required.				Year 1 Repair Cost (£)

Photo 2

Position

Element : Fire Alarms Description Smoke detectors connected to the main bld Fire Alarm System have been installed.	CODE : 14 Condition The condition of the system was fair with no defects noted.	Action Continue Maintenance. This survey did not look at system compliance, a further in depth compliance survey would be required.	Cond/Ind Priority B	L'Expec 20	Quantity	Replacement Cost (£) 750 Year 1 Repair Cost (£)
Element : Security Systems Description	CODE : 14 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
The bld is protected by a Nova alarm system.	The condition of this was fair with no defects noted.	Continue maintenance	В	20		1,500 Year 1 Repair Cost (£)

BUILDING : Block 08 Lodge	UPRN :	FLOOR : M	l&E			
ROOM : M & E	No : 002/8/M&E	/M&E USE :				
Element : Incoming Mains & Mete	ering CODE : 14					Replacement
Description Power is supplied from the main	Condition All were in fair condition with no	Action Continue Maintenance	Cond/Ind Priority B	L'Expec 20	Quantity	Cost (£) 1,500
REC supplies. This feeds a MEM Distribution Board (DB). The main incomer and associated equipment were located within a dedicated cupboard in the hallway.	defects evident.					Year 1 Repair Cost (f
Element : Mains Distribution	CODE : 14	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
Power distribution was via a MEM	All were in a fair condition with no		B	20	Quantity	5,000
DB located within a cupboard in the hallway. Wiring was contained within the walls of the bld.	defects noted.					Year 1 Repair Cost (£
Element : Light Fittings Internal	CODE : 14					Replacement
Description In the main this was a mix of	Condition The condition of the system was fair with no defects noted.	Action Continue maintenance	Cond/Ind Priority B	L'Expec 20	Quantity	Cost (£) 1,000
tungsten and CFL fittings. There were no signs of automatic controls.		This survey did not look at system compliance, a further lighting compliance survey would be required.	3			Year 1 Repair Cost (£

CODE :14					Replacement
Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
		В	20		250
with no defects noted.	system compliance, a further in				Year 1
	be required.				Repair Cost (£)
	Condition The condition of the lighting and its associated equipment was fair	ConditionActionThe condition of the lighting and its associated equipment was fair with no defects noted.Continue Maintenance This survey did not look at system compliance, a further in depth compliance survey would	ConditionActionCond/Ind PriorityThe condition of the lighting and its associated equipment was fair with no defects noted.Continue Maintenance This survey did not look at system compliance, a further in depth compliance survey wouldB	ConditionActionCond/Ind PriorityL'ExpecThe condition of the lighting and its associated equipment was fair with no defects noted.Continue Maintenance This survey did not look at system compliance, a further in depth compliance survey wouldB20	ConditionActionCond/Ind PriorityL'ExpecQuantityThe condition of the lighting and its associated equipment was fair with no defects noted.Continue Maintenance This survey did not look at system compliance, a further in depth compliance survey wouldB20

Element : Fire Alarms	CODE :14					Replacement
Description	Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Cost (£)
There are two battery operated smoke detectors situated within	The condition of the system was fair with no defects noted.	Continue Maintenance. This survey did not look at	В	20		50
the hallway.		system compliance, a further in depth compliance survey would be required.				Year 1 Repair Cost (£)
Element : Security Systems Description	CODE : 14 Condition	Action	Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
The bld is protected by a Nova alarm system.	The condition of this was fair with no defects noted.	Continue maintenance	В	20		1,500

Year 1 Repair Cost (£)

OTHER M&E

BUILDING : Block 01 Kyd ROOM : M & E	UPRN : No : 002/1/M&		FLOOR : M USE :	&E			
Element : Elevator/Lifts Description There was a passenger lift	CODE : 15 Condition The condition of this and its	Action Continue maintenand	ce.	Cond/Ind Priority B	L'Expec 15	Quantity	Replacement Cost (£) 80,000
installed.	associated equipment was fair with no defects noted						Year 1 Repair Cost (£)

BUILDING : Block 04 Keays ROOM : M & E	UPRN : No : 002/4/M&		FLOOR : M USE :	&E			
Element : Elevator/Lifts Description	CODE : 15 Condition	Action		Cond/Ind Priority	L'Expec	Quantity	Replacement Cost (£)
There was a passenger lift installed.	The condition of this and its associated equipment was fair with no defects noted	Continue maintenand	ce.	В	15		80,000 Year 1 Repair Cost (£)





SECTION 6

Life Cycle Costing Report 30 years

		Repair			Replacement					
Description	Priority 1	Priority 2 Priority 3	Priority 4	Repair Total	Priority 1	Priority 2	Priority 3	Priority 4	Replacement Total	Immediate Action Total
Block 01 Kyd										
ROOFS->Covering		£1,050		£1,050					£O	£1,050
ROOFS->Structure				£O					£O	£O
ROOFS->Flashings		£2,015		£2,015					£O	£2,015
ROOFS->Parapets				£0					£O	£O
ROOFS->Rainwater goods		£70		£70					£O	£70
ROOFS->Chimney stacks/flues			£230	£230					£O	£230
ROOFS->TV aerials/dishes etc				£0					£O	£O
ROOFS->Decoration				£0					£O	£O
ROOFS->Roof Lights				£0					£O	£O
WALLS->External walls				£0					£O	£0
WALLS->Windows				£O					£O	
WALLS->Doors				£O		1		1	£O	
WALLS->External joinery				£O					£O	
WALLS->Decoration				£O		1		£246	£246	£246
EXTERNAL GROUNDS->Roads & Parking Areas				£O					£O	£O
EXTERNAL GROUNDS->Underground Drainage										
EXTERNAL GROUNDS->Paths & Paving			£300	£300					£O	£300
EXTERNAL GROUNDS->Steps/ramps										
EXTERNAL GROUNDS->Handrails				£0					£O	£0
EXTERNAL GROUNDS->Boundary fencing/walls				£O					£O	
EXTERNAL GROUNDS->Outdoor Sports Facilities / Fixed Furniture				£O					£O	£O
STRUCTURE->Floors										
STRUCTURE->Stairs										
STRUCTURE->Walls										
ROOMS->Ceilings			£400	£400					£O	£400
ROOMS->Walls			£750						£O	
ROOMS->Partitions				£O					£O	£O
ROOMS->Windows				£O					£O	
ROOMS->Doors			£300	£300					£O	£300
ROOMS->Floors			£50						£O	
ROOMS->Decoration			£50	£50				£943	£943	£993
FIXTURES & FITTINGS->Shelving				£O					£O	£O
FIXTURES & FITTINGS->Worktops				£0					£O	
FIXTURES & FITTINGS->Built in cupboards				£0					£O	
SANITARY->WC				£O					£0	
SANITARY->Basins				£O		1			£0	
SANITARY->Showers				£0					£0	
SANITARY->Sinks				£0		1	1		£0	
SANITARY->Baths				£O					£0	
MECHANICAL SERVICES->Gas Heating System				£0		1	1		£0	
MECHANICAL SERVICES->Extraction System				£0		1	1		£0	
MECHANICAL SERVICES->Domestic Hot Water				£0		1	1		£0	
ELECTRICAL SERVICES->Incoming Mains & Metering				£0		1	-	1	£0	
ELECTRICAL SERVICES->Mains Distribution				£0		1	-		£0	
ELECTRICAL SERVICES->Light Fittings Internal				0£		1			£0	
ELECTRICAL SERVICES->Light Fittings External				£0					£0	

		Rep	oair				Replacement		
Description	Priority 1	Priority 2	Priority 3	Priority 4	Repair Total	Priority 1	Priority 2 Priority 3 Priority 4	Replacement Total	Immediate Action Total
		,	,	,		,			
ELECTRICAL SERVICES->I.T.					£O			£C	£0
ELECTRICAL SERVICES->C.C.T.V.					£O			£C	£0
ELECTRICAL SERVICES->Fire Alarms					£O			£C	
ELECTRICAL SERVICES->Security Systems					£0			£C	
OTHER M&E->Elevator/Lifts					£0			£C	
Block 02 McKinney									
ROOFS->Covering					£O			£C	£0
ROOFS->Structure									
ROOFS->Rainwater goods					£O			£C	£0
ROOFS->Fascias					£0			£C	
ROOFS->Chimney stacks/flues					£O			£C	
ROOFS->TV aerials/dishes etc					£0			£C	
ROOFS->Decoration					£0			£C	
WALLS->External walls					£O			£C	
WALLS->Windows					£0			£C	
WALLS->Doors					£0			£C	
WALLS->External joinery					£0			£C	
WALLS->Decoration					£0			£C	
WALLS->Cills									
STRUCTURE->Floors									
STRUCTURE->Stairs					£O			£C	£0
STRUCTURE->Walls					20				
ROOMS->Ceilings				£250	£250			£C	£250
ROOMS->Walls				£250				£C	
ROOMS->Partitions				2200	£0			£C	
ROOMS->Windows									
ROOMS->Doors					£O			£C	£0
ROOMS->Floors					£0			£C	
ROOMS->Decoration				£160			£919		
FIXTURES & FITTINGS->Shelving				2000	£0		a./ 1	£C	
FIXTURES & FITTINGS->Worktops					£O			Dit C	
SANITARY->WC					0£ D			LC LC	
SANITARY->Basins					£0			£C	
SANTAR -> Dubicles					£O			Dit C	
SANITAR					£0 £0			D£ D£	
SANITAR 1-2510 Weis					£0			LC LC	
MECHANICAL SERVICES->Gas Heating System					£0 £0			D£ D£	
MECHANICAL SERVICES->Gas Healing System MECHANICAL SERVICES->Domestic Hot Water					£0 £0			t. £C	
ELECTRICAL SERVICES->Domestic Hor Water					£0 £0			l fl	
ELECTRICAL SERVICES->Mains Distribution ELECTRICAL SERVICES->Light Fittings Internal					£0 £0			Lt D£	
ELECTRICAL SERVICES->Light Fittings Internal					£0 £0			Lt D£	
								L£ D£	
ELECTRICAL SERVICES->Fire Alarms					£O			±C	£0
Plack 02 Dalhausia									
Block 03 Dalhousie									l
ROOFS->Covering					£O			£C	£0
ROOFS->Structure									

		Rep	oair				Replacement		
Description	Priority 1	Priority 2	Priority 3	Priority 4	Repair Total Pr	iority 1	Priority 2 Priority 3 Priority 4	Replacement Total	Immediate Action Total
ROOFS->Flashings					£O			£O	O£
ROOFS->Rainwater goods			£80		£80			£O	£80
WALLS->External walls					£O			£O	O£
WALLS->Windows					£O			£O	O£
WALLS->Doors					£O			£O	O£
WALLS->External joinery					£O			£O	O£
WALLS->Decoration					£O			£O	O£
WALLS->Cills					£O			£O	O£
STRUCTURE->Floors									
STRUCTURE->Stairs									
STRUCTURE->Walls									
ROOMS->Ceilings					£O			£O	O£
ROOMS->Walls					£0			£O	0£
ROOMS->Doors					£0			£O	
ROOMS->Floors					£0			£O	
ROOMS->Decoration					£0			£O	
FIXTURES & FITTINGS->Shelving					£0			£O	
SANITARY->WC					£0			£O	£O
SANITARY->Basins					£0			£O	
SANITARY->Showers					£0			£0	
SANITARY->Cleaners & Belfast Sinks					£0			£O	
SANITARY->Baths					£0			£O	
MECHANICAL SERVICES->Gas Heating System					£0			£0	
MECHANICAL SERVICES->Extraction System					£0			£O	
MECHANICAL SERVICES->Domestic Hot Water					£0			£O	
ELECTRICAL SERVICES->Mains Distribution					£0			£O	£O
ELECTRICAL SERVICES->Light Fittings Internal					£0			£0	
ELECTRICAL SERVICES->Light Fittings External					£0			£O	
ELECTRICAL SERVICES->Fire Alarms					£0			£O	
Block 04 Keays									
ROOFS->Covering					£0			£0	£0
ROOFS->Structure									
ROOFS->Flashings									
ROOFS->Rainwater goods			£40		£40			£O	£40
ROOFS->TV aerials/dishes etc					£0			£0	
ROOFS->Decoration					£0			£0	
WALLS->External walls					£0			£0	
WALLS->Windows					£0			£0	
WALLS->Doors					£0			£0	
WALLS->External joinery					£0			£0	
WALLS->Decoration					£0			£0	
WALLS->Cills					0£			£0	
STRUCTURE->Floors					Us			20	0.6
STRUCTURE->Stairs									
STRUCTURE->Walls									
ROOMS->Ceilings									
ROOMS->Cellings ROOMS->Walls				£130	£130			£O	£130

[Repair				Replac	cement			
Description	Priority 1	Priority 2 Priority 3	Priority 4	Repair Total	Priority 1	Priority 2	Priority 3	Priority 4	Replacement Total	Immediate Action Total
					· · · ·					
ROOMS->Doors				£O					£C	£O
ROOMS->Floors				£O				£1,558	£1,558	£1,558
ROOMS->Decoration			£150	£150				£1,230		£1,380
FIXTURES & FITTINGS->Shelving				£O					£C	£O
FIXTURES & FITTINGS->Built in cupboards				£0				£820	£820	£820
SANITARY->WC				£O					£C	£O
SANITARY->Basins				£0				£328	£328	£328
SANITARY->Cubicles		+		£0					£C	
SANITARY->Showers				£0					£C	
SANITARY->Baths		+		£0					£C	
MECHANICAL SERVICES->Gas Heating System				£0					£C	
MECHANICAL SERVICES->Extraction System		+		£0					£C	
MECHANICAL SERVICES->Domestic Hot Water				£0					£C	
ELECTRICAL SERVICES->Mains Distribution				£0					£C	
ELECTRICAL SERVICES->Light Fittings Internal				£0					£C	
ELECTRICAL SERVICES->Light Fittings External				£0					£C	
ELECTRICAL SERVICES->Fire Alarms		+		0£					£C	
OTHER M&E->Elevator/Lifts		+		£0					£C	
				J.					0.6	J
Block 05 Dining		+								
		+								
ROOFS->Covering				£0					£C	£0
ROOFS->Structure				£0					£C	
ROOFS->Flashings				£0					£C	
WALLS->External walls				0£					£C	
WALLS->Windows				£0					£C	
WALLS->Doors				0£ 0					Di Contra da Contra E Contra da Con	
WALLS->Wall fixture & fittings				0£					£C	
WALLS-> Decoration				£O					Dit C	
WALLS->Cills				£O					D£	
STRUCTURE->Floors				20					0.6 0	20
STRUCTURE->Walls										
ROOMS->Ceilings				£O					£C	£0
ROOMS-> Walls				£0					Di Contra da Contra E Contra da Con	
ROOMS->Doors				£O					D£	
ROOMS->Floors				£O					D£	
ROOMS->Decoration				£0 £0					Dit C	
MECHANICAL SERVICES->Extraction System				£0					L L L L L L L L L L L L L L L L L L L	
ELECTRICAL SERVICES->Light Fittings Internal				£0					D£ D£	
				a U					a.C	20
Block 06 Greenhouse		<u>├───</u>				-				
		<u> </u>								
ROOFS->Covering		<u> </u>		£O					£C	£0
ROOFS->Covering ROOFS->Structure		<u>├───</u>		TO T		-			JI	Ut
ROOFS->Structure ROOFS->Flashings		<u>├───</u>				-				
ROOFS->Flashings ROOFS->Rainwater goods		<u> </u>							£C	00
		<u>├</u>		0£						
WALLS->External walls		ļ!		£0					£C	
WALLS->Windows				£O					£C	
WALLS->Doors				£O			l		£C	£0

		Rep	oair			Replac	cement			
Description	Priority 1	Priority 2	Priority 3	Priority 4	Repair Total			Priority 4	Replacement Total	Immediate Action Total
	,		,	,		, ,				
WALLS->Decoration					£O				£O	£0
STRUCTURE->Frame/Columns										
STRUCTURE->Floors										
STRUCTURE->Walls										
ROOMS->Walls					£O				£0	£0
ROOMS->Doors					£O				£0	£0
ROOMS->Floors					£O				£O	£0
ROOMS->Decoration					£0				£O	
MECHANICAL SERVICES->Electrical Heating System					£0				£O	
ELECTRICAL SERVICES->Light Fittings Internal					£0				£O	
ELECTRICAL SERVICES->Light Fittings External					£0				£O	
Block 07 Flat 1A										
ROOFS->Covering					0£				£O	£0
ROOFS->Structure										
ROOFS->Flashings					£0				£0	£O
ROOFS->Rainwater goods					£0				£0	
ROOFS->Fascias					£0				£0	
ROOFS->Decoration					£0				£0	
WALLS->External walls										
WALLS->Windows					0£				£O	£0
WALLS->Doors					£0				£0	
WALLS->External joinery					£0				£0	
WALLS->Decoration					£0				£0	
STRUCTURE->Floors										
STRUCTURE->Stairs										
STRUCTURE->Walls										
ROOMS->Ceilings					£0				£O	£0
ROOMS->Walls					0£				£0	
ROOMS->Doors					£0				£0	
ROOMS->Floors					£0				£0	
ROOMS->Decoration				£40	£40				£0	
FIXTURES & FITTINGS->Worktops				&+U	0£				£0	
FIXTURES & FITTINGS->Built in cupboards					£0				£0	
SANITARY->WC					0£				£0	
SANITARY->Basins					0£				£0	
SANITARY->Showers					0£				£0	
SANITARY->Sinks					£0				£0	
MECHANICAL SERVICES->Gas Heating System					0£				£0	
MECHANICAL SERVICES->Gds Hedning System					£0		+		£0	
MECHANICAL SERVICES->LANGENON System					£0 £0		+		£0	
ELECTRICAL SERVICES-> Mains Distribution					£O				£0	
ELECTRICAL SERVICES->Mains Distribution					£0 £0				£U £0	
ELECTRICAL SERVICES->Sob Mains Distribution ELECTRICAL SERVICES->Light Fittings Internal					£0 £0		+		LU D£	
ELECTRICAL SERVICES->Light Fittings External					£0 £0				O£ D£	
ELECTRICAL SERVICES->EIgni Finings External ELECTRICAL SERVICES->Fire Alarms					t0 £0				£U £0	
ELECTRICAL SERVICES->FIRE AIDEMS ELECTRICAL SERVICES->Security Systems									U£ D£	
ELECTRICAL SERVICES->SOCUTITY SYSTOMS					£O				t.U	t0
										1

		Repair				Replac	cement			
Description	Priority 1	Priority 2 Priority 3	Priority 4	Repair Total	Priority 1	Priority 2	Priority 3	Priority 4	Replacement Total	Immediate Action Total
		, ,	,					,		
Block 08 Lodge										
×										
ROOFS->Covering		£598	£40	£638					£O	£638
ROOFS->Structure										
ROOFS->Flashings										
ROOFS->Rainwater goods		£120		£120					£O	£120
ROOFS->Fascias				£0					£O	£0
ROOFS->Chimney stacks/flues				£0					£O	£0
ROOFS->TV aerials/dishes etc				£O					£O	£0
ROOFS->Decoration				£0					£O	£0
ROOFS->Roof Lights				£0					£O	£0
WALLS->External walls				£O					£O	£0
WALLS->Windows				£0					£O	£0
WALLS->Doors				£O					£O	
WALLS->Decoration			£80						£O	
EXTERNAL GROUNDS->Paths & Paving				£0					£O	£0
EXTERNAL GROUNDS->Steps/ramps				£0					£O	£0
EXTERNAL GROUNDS->Walls/dwarf walls				£O					£O	£0
EXTERNAL GROUNDS->Decoration				£O					£O	£0
EXTERNAL GROUNDS->Landscaping				£0					£O	£0
EXTERNAL GROUNDS->Boundary fencing/walls				£0					£O	£0
EXTERNAL GROUNDS->Outdoor Sports Facilities / Fixed Furniture				£0					£O	£0
STRUCTURE->Floors										
STRUCTURE->Stairs										
STRUCTURE->Walls										
ROOMS->Ceilings				£O					£O	£0
ROOMS->Walls				£0					£O	£0
ROOMS->Doors				£0					£O	£0
ROOMS->Floors				£0					£O	£0
ROOMS->Decoration				£0					£O	£0
FIXTURES & FITTINGS->Worktops				£O					£O	
FIXTURES & FITTINGS->Built in cupboards				£0					£O	£0
Sanitary->wc				£0					£O	£0
SANITARY->Basins				£O					£O	£0
SANITARY->Showers				£0					£O	£0
SANITARY->Sinks				£0					£O	£0
MECHANICAL SERVICES->Gas Heating System				£0					£O	£0
MECHANICAL SERVICES->Extraction System				£0					£O	£0
MECHANICAL SERVICES->Domestic Hot Water				£O					£O	£0
ELECTRICAL SERVICES->Incoming Mains & Metering				£O					£O	£0
ELECTRICAL SERVICES->Mains Distribution				£O					£O	£O
ELECTRICAL SERVICES->Light Fittings Internal				£O					£O	£0
ELECTRICAL SERVICES->Light Fittings External				£O					£O	£0
ELECTRICAL SERVICES->Fire Alarms				£O					£O	£0
ELECTRICAL SERVICES->Security Systems				£O					£O	£0

	Т													
Description	1	2	3	4	5	6	5 7	8	9	10	11 12	13	14	15
													-	-
Block 01 Kyd														
ROOFS->Covering										£2,379				£3,035
ROOFS->Structure														
ROOFS->Flashings										£1,558				
ROOFS->Parapets														
ROOFS->Rainwater goods										£164				£8,230
ROOFS->Chimney stacks/flues														
ROOFS->TV aerials/dishes etc										£1,805				£800
ROOFS->Decoration			£804					£804				£804		
ROOFS->Roof Lights														£300
WALLS->External walls										£109				
WALLS->Windows					£1,641		£492							£43,132
WALLS->Doors										£984				£2,769
WALLS->External joinery														
WALLS->Decoration			£3,158		£246			£3,158		£246		£3,158		£246
EXTERNAL GROUNDS->Roads & Parking Areas														
EXTERNAL GROUNDS->Underground Drainage													-	
EXTERNAL GROUNDS->Paths & Paving										£4,265				£15,640
EXTERNAL GROUNDS->Steps/ramps													-	-
EXTERNAL GROUNDS->Handrails	-													-
EXTERNAL GROUNDS->Boundary fencing/walls											£10,335		-	£2,091
EXTERNAL GROUNDS->Outdoor Sports Facilities / Fixed Furniture										£10,000			-	-
STRUCTURE->Floors													-	-
STRUCTURE->Stairs													-	-
STRUCTURE->Walls													-	-
ROOMS->Ceilings										£34,115			-	£6,788
ROOMS->Walls	-													£69,244
ROOMS->Partitions	-													£1,969
ROOMS->Windows	-									£820				£8,561
ROOMS->Doors	-									£17,622				£9,651
ROOMS->Floors	-	£205			£779			£27,370		£2,246	£205		-	£2,517
ROOMS->Decoration	-		£18,538		£943			£18,521		£943		£18.521		£943
FIXTURES & FITTINGS->Shelving	-									£328				£738
FIXTURES & FITTINGS->Worktops	-											£342		
FIXTURES & FITTINGS->Built in cupboards	-													£5,241
Sanitary->wc	-													£328
SANITARY->Basins	-									£328				
SANITARY->Showers	-												-	
SANITARY->Sinks	-											£2,051		-
SANITARY->Baths	-												-	
MECHANICAL SERVICES->Gas Heating System	-	1												£40,000
MECHANICAL SERVICES->Extraction System	+													£30,000
MECHANICAL SERVICES->Domestic Hot Water	+													£20,000
ELECTRICAL SERVICES->Incoming Mains & Metering	+	1												
ELECTRICAL SERVICES->Mains Distribution	+	1												
ELECTRICAL SERVICES->Light Fittings Internal	+	1												
ELECTRICAL SERVICES->Light Fittings External	+	1					+ +							
		1	I	1	I	l	1	I			I	I		

Description	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
			-												
ELECTRICAL SERVICES->I.T.															
ELECTRICAL SERVICES->C.C.T.V.															
ELECTRICAL SERVICES->Fire Alarms															
ELECTRICAL SERVICES->Security Systems															
OTHER M&E->Elevator/Lifts															£80,000
Block 02 McKinney															
,															
ROOFS->Covering													£9,186		
ROOFS->Structure															
ROOFS->Rainwater goods															£2,461
ROOFS->Fascias															£1,347
ROOFS->Chimney stacks/flues															
ROOFS->TV aerials/dishes etc										£656					
ROOFS->Decoration			£787				1	£787					£787		
WALLS->External walls															
WALLS->Windows															
WALLS->Doors															
WALLS->External joinery															
WALLS->Decoration			£314					£314					£314		
WALLS->Cills															
STRUCTURE->Floors															
STRUCTURE->Stairs															£410
STRUCTURE->Walls															
ROOMS->Ceilings															
ROOMS->Walls															
ROOMS->Partitions															
ROOMS->Windows															
ROOMS->Doors										£492					
ROOMS->Floors				£164			t	19,395		N172				£164	
ROOMS->Decoration	£123		£14,459	20104	£919	£123		12,542		£919	£123		£12,542	2104	£919
FIXTURES & FITTINGS->Shelving			801-1,-107		80717	2120	~	12,012		80717	0120		W12,012		80717
FIXTURES & FITTINGS->Worktops													£2,000		
SANITARY->WC													22,000		
SANITARY->Basins															
SANITARY->Cubicles															
SANITARY->Showers															
SANITARY->Urinals															
MECHANICAL SERVICES->Gas Heating System															£40,000
MECHANICAL SERVICES -> Domestic Hot Water															£25,000
ELECTRICAL SERVICES->Domestic Hor Water							 								مدي.000
ELECTRICAL SERVICES->Light Fittings Internal							 								
ELECTRICAL SERVICES->Light Fittings External							 								
ELECTRICAL SERVICES->Light Finings External ELECTRICAL SERVICES->Fire Alarms															
Block 03 Dalhousie															
ROOFS->Covering															
ROOFS->Covering ROOFS->Structure															

	-												· · · · · · · · · · · · · · · · · · ·	-	
Description	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
								-		-					
ROOFS->Flashings													-	-	-
ROOFS->Rainwater goods									£1,764					-	
WALLS->External walls											£9,132		-	-	-
WALLS->Windows													-	-	-
WALLS->Doors													£1,627		-
WALLS->External joinery					£1,258				£2,187					-	-
WALLS->Decoration			£547					£547					£547	-	-
WALLS->Cills													-	-	
STRUCTURE->Floors													-		
STRUCTURE->Stairs													-	-	-
STRUCTURE->Walls													-	-	
ROOMS->Ceilings													-		
ROOMS->Walls													-	-	-
ROOMS->Doors													-	-	-
ROOMS->Floors		ł	6,767		£850								£6,767	-	£738
ROOMS->Decoration	£6,8	815					£6,833					£6,833	-		
FIXTURES & FITTINGS->Shelving	-												-	-	-
SANITARY->WC													-	-	-
SANITARY->Basins															
SANITARY->Showers													£9,187		
SANITARY->Cleaners & Belfast Sinks															
SANITARY->Baths														-	-
MECHANICAL SERVICES->Gas Heating System															£10.000
MECHANICAL SERVICES->Extraction System															£800
MECHANICAL SERVICES->Domestic Hot Water															£15,000
ELECTRICAL SERVICES->Mains Distribution													-	-	
ELECTRICAL SERVICES->Light Fittings Internal															
ELECTRICAL SERVICES->Light Fittings External															
ELECTRICAL SERVICES->Fire Alarms													-	-	
													-	-	
Block 04 Keays															
ROOFS->Covering								£984					-	-	
ROOFS->Structure															-
ROOFS->Flashings														-	-
ROOFS->Rainwater goods						£287									£4,265
ROOFS->TV aerials/dishes etc										£164					,
ROOFS->Decoration			£213					£213					£213		
WALLS->External walls															
WALLS->Windows											£27,820				
WALLS->Doors										£6,193					
WALLS->External joinery						£5,468				,					
WALLS->Decoration		£	61,422					£1,422					£1,422		
WALLS->Cills															
STRUCTURE->Floors	-			<u> </u>											
STRUCTURE->Stairs															
STRUCTURE->Walls															
ROOMS->Ceilings															
ROOMS->Walls															
				1											

1 2	3	4	5	6	7	8	9	10	11	12	13	14	15
								£1,148					
£1,066		£369				£14,275		£1,558		£1,066		£369	
	£13,458		£1,230			£13,510		£1,230			£13,510		£1,230
£2,461			£16,405										
													£1,641
£1,312													
													£50,000
													£8,000
													£20,000
													£80,000
													£5,474
													00,171
											£1.312		
								£1914					
						£4.511							
						w 1/0 1 1		w2/001			£3.254		
								£68					
	£478					£478					£478		
								£1.312					
						£2.297							
		£976				w2/2//	£976					£976	
													£30,000
													2007000
													£1,230
													a, 200
								£3,254					
	£1,066	£1,066 £13,458 £2,461	£1,066 £369 £13,458 £2,461 £1,312 £1,312	£1,066 £369 £1,3,458 £1,230 £2,461 £16,405 £1,312 1 1 1	£1,066 £369 £1,3458 £1,230 £2,461 £16,405 £1,312	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	£1,066 £369 £14,275 £13,458 £1,230 £13,510 £2,461 £16,405 1 £1,312 1 1 1	£1,066 £369 £14,275 £13,458 £1,230 £13,510 £2,461 £16,405 1 £1,312 1 1 £1,312 1 1 £1,312 1 1 £1,312 1 1 £1,312 1 1 £1,312 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1	$\begin{array}{c c c c c c c c c c c c c c c c c c c $	$\begin{array}{c c c c c c c c c c c c c c c c c c c $	$\begin{array}{c c c c c c c c c c c c c c c c c c c $	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $

Description	1 2	3	4	5	6	7	8	9	10	11	12	13	14	15
WALLS->Decoration	£164					£164					£164			
STRUCTURE->Frame/Columns														
STRUCTURE->Floors														-
STRUCTURE->Walls														
ROOMS->Walls														-
ROOMS->Doors														£656
ROOMS->Floors														£4,101
ROOMS->Decoration	£492					£492					£492			
MECHANICAL SERVICES->Electrical Heating System														£750
ELECTRICAL SERVICES->Light Fittings Internal														
ELECTRICAL SERVICES->Light Fittings External														
Block 07 Flat 1A														
ROOFS->Covering												£656		
ROOFS->Structure														
ROOFS->Flashings												£328		
ROOFS->Rainwater goods														
ROOFS->Fascias														-
ROOFS->Decoration		£49					£49					£49		
WALLS->External walls														-
WALLS->Windows														
WALLS->Doors														-
WALLS->External joinery														-
WALLS->Decoration		£191					£191					£191		-
STRUCTURE->Floors														
STRUCTURE->Stairs														-
STRUCTURE->Walls														-
ROOMS->Ceilings														-
ROOMS->Walls														
ROOMS->Doors														-
ROOMS->Floors						£1,846								
ROOMS->Decoration	£1,075					£1,075					£1,075			
FIXTURES & FITTINGS->Worktops	\$1,070					21,070					£342			
FIXTURES & FITTINGS->Built in cupboards									£820		0012			
SANITARY->WC									0020					
SANITARY->Basins														
SANITARY->Showers														
SANITARY->Sinks											£328			
MECHANICAL SERVICES->Gas Heating System											2020			£1,000
MECHANICAL SERVICES-Sextraction System														£150
MECHANICAL SERVICES->Domestic Hot Water														£1,000
ELECTRICAL SERVICES->Mains Distribution														
ELECTRICAL SERVICES->Sub Mains Distribution														
ELECTRICAL SERVICES->300 Mains Dismounding														
ELECTRICAL SERVICES->Light Fittings External														
ELECTRICAL SERVICES->Fire Alarms														
									1					

Deservation															
Description	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
		-	•					0	,						
Block 08 Lodge															
ROOFS->Covering								£246							
ROOFS->Structure															-
ROOFS->Flashings															
ROOFS->Rainwater goods										£1,695					
ROOFS->Fascias										£581					
ROOFS->Chimney stacks/flues															£2,447
ROOFS->TV aerials/dishes etc										£328					
ROOFS->Decoration			£254					£254					£254		
ROOFS->Roof Lights										£500					
WALLS->External walls															
WALLS->Windows															£820
WALLS->Doors															
WALLS->Decoration			£1,928					£1,928					£1,928		
EXTERNAL GROUNDS->Paths & Paving															
EXTERNAL GROUNDS->Steps/ramps															
EXTERNAL GROUNDS->Walls/dwarf walls															
EXTERNAL GROUNDS->Decoration			£1,928					£1,928					£1,928		
EXTERNAL GROUNDS->Landscaping	£400														
EXTERNAL GROUNDS->Boundary fencing/walls										£5,414					
EXTERNAL GROUNDS->Outdoor Sports Facilities / Fixed Furniture										,					£600
STRUCTURE->Floors															
STRUCTURE->Stairs															
STRUCTURE->Walls															
ROOMS->Ceilings										£711					
ROOMS->Walls															
ROOMS->Doors															£4,265
ROOMS->Floors					£410										£410
ROOMS->Decoration		£3,330					£3,330					£3,330			
FIXTURES & FITTINGS->Worktops							£615								
FIXTURES & FITTINGS->Built in cupboards															£820
SANITARY->WC															
SANITARY->Basins															
SANITARY->Showers												£1,148			
SANITARY->Sinks							£328								
MECHANICAL SERVICES->Gas Heating System															£7,000
MECHANICAL SERVICES->Extraction System															£200
MECHANICAL SERVICES->Domestic Hot Water															£1,000
ELECTRICAL SERVICES->Incoming Mains & Metering															
ELECTRICAL SERVICES->Mains Distribution															-
ELECTRICAL SERVICES->Light Fittings Internal															
ELECTRICAL SERVICES->Light Fittings External															
ELECTRICAL SERVICES->Fire Alarms															
ELECTRICAL SERVICES->Security Systems															

Description	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	Totals
Block 01 Kyd																
ROOFS->Covering									1	£89,786					£3,035	£99,284
ROOFS->Structure					£848											£848
ROOFS->Flashings									ł	£20,131					£2,406	£26,110
ROOFS->Parapets										£2,707						£2,707
ROOFS->Rainwater goods					£205											£8,669
ROOFS->Chimney stacks/flues										£2,447					£7,341	£10,018
ROOFS->TV aerials/dishes etc					£1,805					£164					£1,805	£6,378
ROOFS->Decoration			£804					£804					£804			£4,823
ROOFS->Roof Lights										£6,800						£7,100
WALLS->External walls	£1,394				£36,953										£10,144	£48,600
WALLS->Windows													£22,147			£67,412
WALLS->Doors	+ +	£3	3,753												£984	£8,490
WALLS->External joinery								£219								£219
WALLS->Decoration		£3	3,158		£246			£3,158		£246			£3,158		£246	£20,671
EXTERNAL GROUNDS->Roads & Parking Areas			,		£76,940			,					,			£76,940
EXTERNAL GROUNDS->Underground Drainage																
EXTERNAL GROUNDS->Paths & Paving					£45.661											£65,866
EXTERNAL GROUNDS->Steps/ramps																
EXTERNAL GROUNDS->Handrails					£1,230											£1,230
EXTERNAL GROUNDS->Boundary fencing/walls					£12,851							£10,335	£383		£861	£36,856
EXTERNAL GROUNDS->Outdoor Sports Facilities / Fixed Furniture					£7,000											£17,000
STRUCTURE->Floors																,
STRUCTURE->Stairs																
STRUCTURE->Walls																
ROOMS->Ceilings		fC	2,085							£1,094					£1,777	£46,258
ROOMS->Walls			,000		£752					£6,486			£3,609			£80,841
ROOMS->Partitions					87.02					20,100			20,007			£1,969
ROOMS->Windows																£9,382
ROOMS->Doors								£23,391								£50,964
ROOMS->Floors		£27	,028		£1,066		£205	20,071		£779			£27,028		£328	
ROOMS->Decoration			3,521		£943		200	£18,521		£943			£18,521			
FIXTURES & FITTINGS->Shelving			,021		27 10			210,021		87 10			£10,021		8710	£1,066
FIXTURES & FITTINGS->Worktops													£342			£684
FIXTURES & FITTINGS->Built in cupboards								£6,562					807Z			£11,803
SANITARY->WC								£2,625								£2,953
SANITARY->Basins								£2,297								£2,625
SANITARY->Showers		£5	3,039					02,277								£8,039
SANITARY->Sinks		auc	,007										£2,051			£4,101
SANITARY->Baths								£656					a2,001			£656
MECHANICAL SERVICES->Gas Heating System	+							2000								£40,000
MECHANICAL SERVICES->Extraction System	+				<u>├</u>											£30,000
MECHANICAL SERVICES->EXITCLION System MECHANICAL SERVICES->Domestic Hot Water	+				<u>├</u>											£30,000 £20,000
ELECTRICAL SERVICES->Incoming Mains & Metering	+				£15,000											£15,000
ELECTRICAL SERVICES->Incoming Mains & Metering ELECTRICAL SERVICES->Mains Distribution	+				£15,000 £55,000											£15,000 £55,000
ELECTRICAL SERVICES->/Mains Distribution ELECTRICAL SERVICES->Light Fittings Internal	+				£33,000											£33,000
ELECTRICAL SERVICES->Light Fittings External	+				£33,000 £2,500											£33,000 £2,500

														L
Description	16	17 18	19 20	21	22	23	24	25	26	27	28	29	30	Totals
ELECTRICAL SERVICES->I.T.			£150]	£150
ELECTRICAL SERVICES->C.C.T.V.			£10,000											£10,000
ELECTRICAL SERVICES->Fire Alarms			£15,000											£15,000
ELECTRICAL SERVICES->Security Systems			£13,000											£13,000
OTHER M&E->Elevator/Lifts			a 13,000											£80,000
														200,000
Block 02 McKinney														
ROOFS->Covering			£26,392								£12,796			£48,374
ROOFS->Structure														
ROOFS->Rainwater goods						£3,623								£6,084
ROOFS->Fascias											£2,625			£3,971
ROOFS->Chimney stacks/flues			£2,447											£2,447
ROOFS->TV aerials/dishes etc			£656										£656	
ROOFS->Decoration		£787				£787					£787			£4,725
WALLS->External walls	£437										£1,613			£2,051
WALLS->Windows											£51,130			£51,130
WALLS->Doors		£5,865												£5,865
WALLS->External joinery						£1,914								£1,914
WALLS->Decoration		£314				£314					£314			£1,887
WALLS->Cills														
STRUCTURE->Floors														
STRUCTURE->Stairs														£410
STRUCTURE->Walls														
ROOMS->Ceilings		£991						£7,587						£8,829
ROOMS->Walls		£1,914				£123		£14,799			£9,105			£26,191
ROOMS->Partitions						£1,641								£1,641
ROOMS->Windows														
ROOMS->Doors						£41,163								£41,656
ROOMS->Floors		£17,020					£164				£19,071			£55,978
ROOMS->Decoration	£123	£12,542	£919	£123		£12,542		£919	£123		£12,542		£919	£84,497
FIXTURES & FITTINGS->Shelving						£27								£27
FIXTURES & FITTINGS->Worktops											£68			£2,068
Sanitary->wc						£3,937								£3,937
SANITARY->Basins						£3,937								£3,937
SANITARY->Cubicles						£820								£820
SANITARY->Showers		£10,335												£10,335
SANITARY->Urinals						£492								£492
MECHANICAL SERVICES->Gas Heating System														£40,000
MECHANICAL SERVICES->Domestic Hot Water														£25,000
ELECTRICAL SERVICES->Mains Distribution			£40,000											£40,000
ELECTRICAL SERVICES->Light Fittings Internal			£33,000											£33,000
ELECTRICAL SERVICES->Light Fittings External			£2,500											£2,500
ELECTRICAL SERVICES->Fire Alarms			£10,000											£10,000
Block 03 Dalhousie														
ROOFS->Covering						£10	0,166							£10,166
ROOFS->Structure						متار	0,100							a 10,100

WALLS-Decordion £547 E547 E547 E547 STRUCTURE-FROMS £4000		
BOOKS-Additive goods Image: Book addition of the second of t	30 To	Totals
ROOFS-Rolmwing goods Image: Solution of the solution o		
WALLS-Media Mather Methods Mather Met		£8
WALLS-Monow WALLS-Schemol joiney. Image: schemol joiney.		£1,8
WALLS-Shoors Image: Start		£10,0
WALLS-Schemoliphiney E		£25,5
WALLS-Decordion 540 5547 5547 5547 5547 STRUCTURE-Shons 54,000		£1,6
WALLS-Calls E4.000 Image: Coll and C	258,1,258	£4,7
SIRUCTURE-Priors Image: Constraint of the second of the seco		£3,2
SIRUCTURE-Stains Image: Siructure in the state of the st		£4,0
STRUCTURE-Works Image: Construction of the state of the		
ROOMS>Cellings Image: Source of the source of		
ROOMS-Doors E B E <th< td=""><td></td><td></td></th<>		
ROOMS>Doos E18.982 Image: Source of the sou		£6,6
ROOMS>Floor £6,77 £738 M M E		£9,0
ROOMS-Decordion £6.833 E £6.833 E £6.833 E <th< td=""><td></td><td>£18,9</td></th<>		£18,9
PRTURES & FITTINGS-Shelving E217 Image: Constraint of the second		£22,6
SANIARY-SWC E2.953 Image: Constraint of the second		£40,9
SANIARY-Basins E2.953 Image: Solution of the solution		£2
SANUARY-Showers Image: Constant of the state of the stat		£2,9
SANTARY-Sciences & Belicat Sinks Image: Santary Barbon Sinks		£2,9
SANTARY-Baths E E I <thi< th=""> I <thi< th=""> <th< td=""><td></td><td>£9,1</td></th<></thi<></thi<>		£9,1
MECHANICAL SERVICES->Gas Heating System		£1,3
MECHANICAL SERVICES->Extraction System		£ć
MECHANICAL SERVICES->Domestic Hot Water 215,000 <		£10,0
ELECTRICAL SERVICES->Mains Distribution £15,000 <th< th=""> <th< th=""> <th< td=""><td></td><td>£8</td></th<></th<></th<>		£8
ELECTRICAL SERVICES->Light Fittings External £15,000 £1000 £1000<		£15,0
ELECTRICAL SERVICES->Light Fittings External Image: starting in the starting in		£15,0
ELECTRICAL SERVICES->Fire Alarms £6,000		£15,0
Image: constraint of the sector of the se		£1,0
ROOFS->Covering L <thl< th=""> L <thl< th=""> <</thl<></thl<>		£6,0
ROOFS->Covering Image: Construction		
ROOFS->Structure Image: Construction Image: Construline Image: Construline		
ROOFS->Structure Image: Construction Image: Construline Image: Construline		£5,4
ROOFS->Flashings Image: Constraint of the sector of th		
ROOFS->Rainwater goods Image: State of the		
ROOFS->TV aerials/dishes etc Image: State of the s		£4,5
ROOFS->Decoration £213 <td>£164</td> <td>£4</td>	£164	£4
WALLS->External walls £17,608 Image: Constraint of the second secon	2101	£1,2
WALLS->Windows Image: Constraint of the second		£17,6
WALLS->Doors Image: Constraint of the second se		£27,8
WALLS->External joinery Image: Constraint of the system of t		£12,3
WALLS->Decoration £1,422 £1,422 £1,422 £1,422 £1,422 £1,422 £1,422 £1,422 £1,422 E1,422	,0,170	£5,4
WALLS->Cills £19,000 Image: Color Structure ->Floors Image: Color Structure ->FloorStructure ->FloorStruc		£8,5
STRUCTURE->Floors INTEGRATING INTEGRATION INTEGRATING INTEG		£19.0
STRUCTURE->Stairs		au 17,0
ROOMS-SCeilings		
ROOMS->Cellings £82 £205 £8,039		£8,4

Deve is the	1/	17	10	10 00	01			0.1	0.5	0.4	07	00	00	00	T . I . I.
Description	16	17	18	19 20	21	22	23	24	25	26	27	28	29	30	Totals
ROOMS->Doors							£49,557								£50,70
ROOMS->Floors			£14,149	£1,558		£1,066		£369				£14,149		£1,558	
ROOMS->Decoration			£13,510	£1,230			£13,510		£1,230			£13,510		£1,230	
FIXTURES & FITTINGS->Shelving			w10/010	w1,200			£1,504		w17200			w10/010		w:,200	£1,50
FIXTURES & FITTINGS->Built in cupboards							£1,641		£820		£2,461			£16,405	
SANITARY->WC							£5,906		2020		82,101			\$10,100	£7,54
SANITARY->Basins							£6,234		£328		£1,312				£9,51
SANITARY->Cubicles							£820		2020		Z I U, I Jo				£82
SANITARY->Showers			£14,929				2020								£14,92
SANITARY->Boths			du 1 *+, / Z /				£656								£65
MECHANICAL SERVICES->Gas Heating System							2010								£50,00
MECHANICAL SERVICES->Extraction System															£8,00
MECHANICAL SERVICES->Domestic Hot Water															£20,00
ELECTRICAL SERVICES->Domestic Horware				£50.000											£20,00
				£33,000											
ELECTRICAL SERVICES->Light Fittings Internal ELECTRICAL SERVICES->Light Fittings External				£33,000 £2,500											£33,00 £2,50
ELECTRICAL SERVICES->Fire Alarms				£10,000											£10,00
OTHER M&E->Elevator/Lifts															£80,00
Block 05 Dining															
ROOFS->Covering															£5,47
ROOFS->Structure														£5,971	
ROOFS->Flashings												£1,312			£2,62
WALLS->External walls															£1,91
WALLS->Windows															£6,56
WALLS->Doors															£3,25
WALLS->Wall fixture & fittings															£6
WALLS->Decoration			£478				£478					£478			£2,87
WALLS->Cills			21/0	£5,000			\$170					21/0			£5,00
STRUCTURE->Floors				20,000											20,00
STRUCTURE->Walls															
ROOMS->Ceilings				£1,914											£1,91
ROOMS->Walls				۰۱٫/۱۰۲											£
ROOMS->Doors															£1,31
ROOMS->Floors			£2.297									£2,297			£6,89
ROOMS->Decoration			du Z , Z / /	£976				£976				duZ,Z//	£976		£5,85
MECHANICAL SERVICES->Extraction System				2.770				27/0					27/0		£30,00
ELECTRICAL SERVICES->Light Fittings Internal				£5,000											£5,00
Block 06 Greenhouse															
ROOFS->Covering				£20,000											£20,00
ROOFS->Structure															
ROOFS->Flashings															
ROOFS->Rainwater goods															£1,23
WALLS->External walls				£109					£656						£76
WALLS->Windows				£45,866											£45,86
WALLS->Doors		Т										Т		£3,254	£6,50

Description	16 17	18	19	20	21	22	23	24	25	26	27	28	29	30 1	otals
WALLS->Decoration	£164					£164					£164				£984
STRUCTURE->Frame/Columns	2104					2104					2104				1,704
STRUCTURE->Floors															
STRUCTURE->FIGUIS															
									01 470						01 470
ROOMS->Walls									£1,470						£1,470
ROOMS->Doors															£656
ROOMS->Floors						0.100									£4,101
ROOMS->Decoration	£492					£492					£492				£2,953
MECHANICAL SERVICES->Electrical Heating System															£750
ELECTRICAL SERVICES->Light Fittings Internal				£500											£500
ELECTRICAL SERVICES->Light Fittings External				£50											£50
Block 07 Flat 1A															
ROOFS->Covering												£656		£4,799	£6,111
ROOFS->Structure												2000		/ / ۲٫۵	a.U, i I I
ROOFS->Flashings									£1,353			£328			£2,010
ROOFS->Rainwater goods				£1,504			£287		a 1,000			2020			£1,791
ROOFS->Fascias				at 1,304			£205								£205
ROOFS->Pascias ROOFS->Decoration		£49					£203					£49			£205
WALLS->External walls		JU47					247					3547			JZ7J
												011 (00			011 /00
WALLS->Windows WALLS->Doors		01 (07										£11,689			£11,689
		£1,627					0010								£1,627
WALLS->External joinery		0101					£219					0101			£219
WALLS->Decoration		£191					£191					£191			£1,148
STRUCTURE->Floors															
STRUCTURE->Stairs															
STRUCTURE->Walls															
ROOMS->Ceilings															£O
ROOMS->Walls				£922							£2,379				£3,301
ROOMS->Doors						£1,969									£1,969
ROOMS->Floors	£1,846										£2,584				£6,275
ROOMS->Decoration	£1,075					£1,075					£1,075				£6,487
FIXTURES & FITTINGS->Worktops											£342				£684
FIXTURES & FITTINGS->Built in cupboards						£9,023									£9,843
SANITARY->WC						£328									£328
SANITARY->Basins						£328									£328
SANITARY->Showers	£1,148														£1,148
SANITARY->Sinks											£328				£656
MECHANICAL SERVICES->Gas Heating System															£1,000
MECHANICAL SERVICES->Extraction System															£150
MECHANICAL SERVICES->Domestic Hot Water															£1,000
ELECTRICAL SERVICES->Mains Distribution				£5,000											£5,000
ELECTRICAL SERVICES->Sub Mains Distribution				£250											£250
ELECTRICAL SERVICES->Light Fittings Internal				£1,000											£1,000
ELECTRICAL SERVICES->Light Fittings External				£250											£250
ELECTRICAL SERVICES->Fire Alarms				£750											£750
ELECTRICAL SERVICES->Security Systems				£1,500											£1,500
															,


Description	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	Totals
Block 08 Lodge																
ROOFS->Covering								£246								£1,13
ROOFS->Structure																
ROOFS->Flashings																
ROOFS->Rainwater goods																£1,81
ROOFS->Fascias																£58
ROOFS->Chimney stacks/flues																£2,44
ROOFS->TV aerials/dishes etc					£328										£328	£98
ROOFS->Decoration			£254					£254					£254			£1,52
ROOFS->Roof Lights																£50
WALLS->External walls					£355								£2,543			£2,89
WALLS->Windows													£15,038			£15,85
WALLS->Doors			£2,400													£2,40
WALLS->Decoration			£1,928					£1,928					£1,928			£11,64
EXTERNAL GROUNDS->Paths & Paving								£1,367		£2,734					£1,148	£5,25
EXTERNAL GROUNDS->Steps/ramps													£2,256			£2,25
EXTERNAL GROUNDS->Walls/dwarf walls															£3,589	£3,58
EXTERNAL GROUNDS->Decoration			£1,928					£1,928					£1,928			£11,56
EXTERNAL GROUNDS->Landscaping																£40
EXTERNAL GROUNDS->Boundary fencing/walls										£5,414						£10,82
EXTERNAL GROUNDS->Outdoor Sports Facilities / Fixed Furniture																£60
STRUCTURE->Floors																
STRUCTURE->Stairs																
STRUCTURE->Walls																
ROOMS->Ceilings					£55							£2,891				£3,65
ROOMS->Walls					£923		£2,297					£7,417				£10,63
ROOMS->Doors							£492									£4,75
ROOMS->Floors		£5,003					£287			£410		£738				£7,25
ROOMS->Decoration		£3,330					£3,330					£3,330				£19,98
FIXTURES & FITTINGS->Worktops							£615									£1,23
FIXTURES & FITTINGS->Built in cupboards		£13,944					£820									£15,58
Sanitary->wc		£656														£65
SANITARY->Basins		£656														£65
SANITARY->Showers																£1,14
SANITARY->Sinks							£328									£65
MECHANICAL SERVICES->Gas Heating System																£7,00
MECHANICAL SERVICES->Extraction System																£20
MECHANICAL SERVICES->Domestic Hot Water																£1,00
ELECTRICAL SERVICES->Incoming Mains & Metering					£1,500											£1,50
ELECTRICAL SERVICES->Mains Distribution					£5,000											£5,00
ELECTRICAL SERVICES->Light Fittings Internal					£1,000											£1,00
ELECTRICAL SERVICES->Light Fittings External					£250											£23
ELECTRICAL SERVICES->Fire Alarms					£50											£
ELECTRICAL SERVICES->Security Systems					£1,500											£1,50







SECTION 7

Floor Plans



			VICTOR	IA	ROAD		
Chartered Architects 1 Burns Street, Edinburgh EH6 8DS TEL 0131 554 7666 FAX 0131 554 8777 Drowing Number ref. R116/500/01	MO PA	Scale 1:500 Drawn MH Date 25/01/07 Checked	Rosendael for Scottish Veterans Housing Association	Internal Alterations		Amendments ref Date Description	





Upper Floor